



Commercial Vehicle
Inspection Report

Decal Number: GK54456
Decal Expiry Date: 2026-Feb-28
Inspection Number: 21471564

L03-37
Inspection Result:
PASS

CILITY:	TWISTED METAL MECHANICS LTD. / S20269	INSP. TYPE:	Complete	INSP. START:	2025-Aug-24 02:26 PM PDT
SPECTOR:	BOLIVAR, MICHAEL BRANDON / 202902	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2025-Aug-24 03:26 PM PDT
ORK ORDER #:	14	INSP. REASON:	Semi-annual		
EHICLE JUR:	British Columbia	REGI:	14762838	VIN:	1NKZL40X6SJ996189
ATE #:	WC5391	UNIT/FLEET#:	153	OWNER/LESSEE NAME:	SWAMP DONKEY, SWAMP
ENCED GVW(kg):	63500	BODY STYLE:	Truck Tractor	ADDRESS:	PO BOX 2394 STN MAIN, PO BOX 2394 STN MAIN
EHICLE YEAR:	2025	ODOMETER:	63000 KM		Dawson Creek, British Columbia
AKE:	KENWORTH	HUB ODOMETER:			V1G4T9, Canada
ODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

ehicle Identification (VIN)	Passed
ection 1 - Power Train	Passed
ection 2 - Suspension	Passed
ection 3 - Brake System	Passed
ection 3A - Air Brakes	Passed
ection 3H - Hydraulic Brakes	Not Applicable
ection 4 - Steering	Passed
ection 5 - Instruments and Auxiliary quipment	Passed
ection 6 - Lamps	Passed
ection 7 - Electrical System	Passed
ection 8 - Frame and Body	Passed
ection 9A - Tires	Passed
ection 9B - Wheels	Passed
ection 10 - Coupling Devices	Passed
ection 11 - Other Vehicle Components	Passed

Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	25	25	12			12	✓
2	Clamp	30	Automatic	30	28	10	10	10	10	
3	Clamp	30	Automatic	29	29	10	10	10	10	
4	Clamp	30	Automatic	31	31	10	10	10	10	
omment:						Comment:				



Commercial Vehicle Inspection Report

Decal Number: GK54456
Decal Expiry Date: 2026-Feb-28
Inspection Number: 21471564

Inspection Result:
PASS

Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axes	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	35	35	Lining (Shoe)	19	19	Drum		
2	40	35	Lining (Shoe)	19	19	Drum		
3	35	35	Lining (Shoe)	19	19	Drum		
4	42	45	Lining (Shoe)	19	19	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:

Is this Vehicle been road tested? No
Inspector: BOLIVAR, MICHAEL BRANDON

Road Test Date: Road Tester:
Signature: M. Bolivar

This Inspection Report was submitted to CVSE on 2025-Aug-24 04:26 PM PDT
Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

Personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement.

SED014

4/2025 4:26:58 PM PDT