

## Commercial Vehicle Inspection Report

**Decal Number: Decal Expiry Date:** Inspection Number: GK54451 2026-Aug-31 21471545

Inspection Result:

CILITY: SPECTOR: TWISTED METAL MECHANICS LTD. INSP. TYPE:

/ S20269

BOLIVAR, MICHAEL BRANDON /

INSP CLASS INSP. REASON: Complete

Class 3 - Trailer and Semi-Trailer

Annual

INSP START

OWNER/LESSEE NAME:

INSP. COMPLETE:

2025-Aug-24 08:44 AM PDT 2025-Aug-24 01:44 PM PDT

**ORK ORDER #:** 

HICLE JUR:

British Columbia

50720K

202902

REGI:

11787356

Air

238 Tank Trailer VIN:

ADDRESS:

1T0DL483XCS000516

SWAMP DONKEY SWAMP PO BOX 2394 STN MAIN, PO BOX 2394

STN MAIN

Dawson Creek, British Columbia

HICLE YEAR:

ATE #:

AKE:

DDEL:

2012

**TREMCAR** 

ODOMETER: HUB ODOMETER:

UNIT/FLEET#:

BODY STYLE:

**BRAKE TYPE:** 

**FUEL TYPE:** 

V1G4T9, Canada

Thickness or Drum Diameter not measured.

shicle Identification (VIN)

**CENCED GVW(kg):** 999999

ection 1 - Power Train ection 2 - Suspension

ection 3 - Brake System ection 3A - Air Brakes ection 3H - Hydraulic Brakes ection 4 - Steering

ection 5 - Instruments and Auxiliary quipment

ection 6 - Lamps ection 7 - Electrical System

ection 8 - Frame and Body ection 9A - Tires ection 9B - Wheels

ection 10 - Coupling Devices ection 11 - Other Vehicle Components Passed

Not Applicable Passed

Passed Passed Not Applicable

Passed

Passed Passed

Passed Passed Passed Passed Passed Passed

Brake Chamber Type, Size and Push Rod Stroke (mm)

Tire Tread Depth (mm)

| Axles   | Type  | Size | Slack Adj. | Left | Right | Outer L  | Inner L | Inner R | Outer R | Steering |
|---------|-------|------|------------|------|-------|----------|---------|---------|---------|----------|
| 1       | Clamp | 30   | Automatic  | 35   | 35    | 12       | 12      | 12      | 12      |          |
| 2       | Clamp | 30   | Automatic  | 32   | 32    | 10       | 10      | 10      | 10      |          |
| 3       | Clamp | 30   | Automatic  | 32   | 35    | 10       | 12      | 12      | 10      |          |
| omment: |       |      |            |      |       | Comment: |         |         |         |          |

| · Brake Camshaft | t Rotation (degre | ees)  | Brake Lining/Pad (mm) |      |       | Rotor Thickness or Drum Inside Diameter (mm)          |      |       |  |
|------------------|-------------------|-------|-----------------------|------|-------|---|------|-------|--|
| Axles            | Left              | Right | Lining/Pad            | Left | Right | Rotor/Drum  | Left | Right |  |
| 1                | 95                | 55    | Lining (Shoe)         | 12   | 16    | Drum  |      |       |  |
| 2                | 90                | 65    | Lining (Shoe)         | 11   | 15    | Drum  |      |       |  |
| 3                | 85                | 75    | Lining (Shoe)         | 12   | 12    | Drum  |      |       |  |
| omment:          |                   |       | Comment:              |      |       | Comment: Air Brake Camshaft Rotation performed. Rotor |      |       |  |

spection Comments:

s this Vehicle been road tested? spector: BOLIVAR, MICHAEL BRANDON Road Test Date:

Signature:

Road Tester:

s Inspection Report was submitted to CVSE on 2025-Aug-24 03:45 PM PDT

No

e Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection I for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this rmation, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement SE0014