



# Commercial Vehicle Inspection Report

Decal Number: GK54466  
Decal Expiry Date: 2026-Aug-31  
Inspection Number: 21471600

Inspection Result:  
**PASS**

CITY: TWISTED METAL MECHANICS LTD. / S20269  
SPECTOR: BOLIVAR, MICHAEL BRANDON / 202902  
DRK ORDER #: 24  
INS. TYPE: Complete  
INS. CLASS: Class 3 - Trailer and Semi-Trailer  
INS. REASON: Annual  
INS. START: 2025-Aug-24 02:55 PM PDT  
INS. COMPLETE: 2025-Aug-24 03:55 PM PDT

255

VEHICLE JUR: Alberta  
ATE #: 202902  
PERMITTED GVW(kg): 9999  
VEHICLE YEAR: 2015  
MAKE: LAZER  
MODEL: TANK  
REGI: 255  
UNIT/FLEET#: 255  
BODY STYLE: Trailer  
VIN: 2L9TS5334FD079544  
OWNER/LESSEE NAME: SWAMP DONKEY, SWAMP  
ADDRESS: PO BOX 2394 STN MAIN, PO BOX 2394 STN MAIN  
Dawson Creek, British Columbia  
V1G4T9, Canada  
ODOMETER:  
HUB ODOMETER:  
BRAKE TYPE: Air  
FUEL TYPE: Not Applicable

L03-4

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Not Applicable
Section 11 - Other Vehicle Components	Not Applicable

Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	34	32	8	10	7	7	
2	Clamp	30	Automatic	35	31	8	8	8	8	
3	Clamp	30	Automatic	32	32	10	10	10	10	
Comment:						Comment:				

Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	70	65	Lining (Shoe)	15	15	Drum		
2	65	65	Lining (Shoe)	17	16	Drum		
3	70	75	Lining (Shoe)	15	15	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

## Inspection Comments:

Is this Vehicle been road tested? No  
Inspector: BOLIVAR, MICHAEL BRANDON  
Road Test Date:   
Signature: Road Tester:

This Inspection Report was submitted to CVSE on 2025-Aug-24 05:55 PM PDT  
Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

## PLEASE KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

Personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VP at the Commercial Vehicle Safety Enforcement.

SED014

4/2025 5:56:06 PM PDT