

Commercial Vehicle Inspection Report

Decal Number: Decal Expiry Date: Inspection Number:

VIN:

GC74326 2026-Jan-31 21194234

Inspection Result:

FACILITY: NICK'S AUTO REPAIR / S2670 **NSPECTOR:** LAROSE, STEVEN MICHAEL / 101636

INSP. TYPE: INSP. CLASS: Complete Class 1 - Light Vehicle with LGVW 5500 kg or less

INSP. START: INSP. COMPLETE: 2025-Jan-03 08:53 AM PST 2025-Jan-03 03:40 PM PST

NORK ORDER #:

INSP. REASON: REGI:

Annual

04295350

Crewcab

169263 KM

1GBJC73K69F118425

/EHICLE JUR: 21 ATF #: JCENCED GVW(kg): 5171 /EHICLE YEAR:

VIAKE:

NODEL:

I H0707

British Columbia

UNIT/FLEET#: BODY STYLE:

FUEL TYPE:

OWNER/LESSEE NAME: ADDRESS:

scorpio masonry bc inc, scorpio 12240 vickers way, 12240 vickers way

Richmond, British Columbia

v6v1h9, Canada

SILVR

2009

ODOMETER: HUB ODOMETER: BRAKE TYPE:

Hydraulic Gasoline

Vehicle Identification (VIN) Passed Section 1 - Power Train Passed

CHEVROLET

Section 2 - Suspension Section 3 - Brake System

Repaired (same day)

replace rear brake pads, rotors, calipers, park brake shoes

Section 3H - Hydraulic Brakes

Passed Passed

Passed

Section 4 - Steering

Section 5 - Instruments and Auxiliary Equipment

Repaired (same day)

replace fuel pump module, gas guage not working

Section 6 - Lamps Section 7 - Electrical System Passed Passed Passed

Section 8 - Frame and Body Section 9A - Tires

Passed Passed

Section 9B - Wheels Section 10 - Coupling Devices Section 11 - Other Vehicle Components

Passed Passed

Fire Tread Depth (mm) Axles Outer L

Inner L Inner R Outer R Steering 12 7 6 6

Brake Lining/Pad (mm) Lining/Pad Left Right Pad 5 5 Pad 11 11 Comment:

Rotor Thickness or Drum Inside Dlameter (mm) Rotor/Drum Left Right Rotor 37.64 37.71 Roto 30.00 30.00

nspection Comments:

2

Comment:

las this Vehicle been road tested? LAROSE, STEVEN MICHAEL nspector:

Yes

Road Test Date: Afte Signature:

steve larose

Comment:

This Inspection Report was submitted to CVSE on 2025-Jan-03 03:55 PM PST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.