



Commercial Vehicle Inspection Report

Decal Number: FS54507
Decal Expiry Date: 2022-Nov-30
Inspection Number: 20126367

Inspection Result: **PASS**
206-2
141

Facility: MT & M SERVICE LTD. / S0566
Inspector: Christy William Christopher / 102483
Work Order Number: x51/05/22
Inspection Type: Complete
Inspection Class: Class 2 - Heavy Vehicle with LGW 5501 kg or more
Inspection Reason: Semi-annual
Inspection Start Date/Time: 2022-May-28 08:05 AM
Inspection Complete Date/Time: 2022-May-28 10:30 AM

Vehicle Jurisdiction: British Columbia
Registration Number: 08916511
VIN: 1M2AA14C3RW043748
Plate Number: ND2634
Licenced GVW (kg): 44000
Vehicle Year: 1994
Make: MACK
Brake Type: Air
Fuel Type: Diesel
Odometer: 167540 KM
Hub Odometer:
Body Style: Dump Truck
Model:
Unit/Fleet Number:
Owner/Lessee Name: Huston Ashleigh Alaina, Huston Ashleigh Alaina
Address: 3061 Panorama Dr, Po Box 1812
City: Merritt
Province/State: British Columbia
Postal Code/ZIP: V1K 1B8
Country: Canada

	Result	Comment
Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Passed	
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Not Applicable	

Air Brake Chamber Type, Size and Push Rod Stroke Measurements (mm)

Axles (front)	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Manual	25	25
2	Clamp	30	Manual	25	25
3	Clamp	30	Manual	25	25
Comment:					

Tire Tread Depth (mm)

Axles (front)	Outer Left	Inner Left	Inner Right	Outer Right	Steering Axle?
1	9.5			11.9	✓
2	11.9	11.9	7.9	7.9	
3	8.7	8.7	7.1	7.1	
Comment:					

Air Brake Camshaft Rotation Measurement (degrees)

Axles (front)	Left (degrees)	Right (degrees)
1	45	45
2	60	45
3	45	30
Comment:		

Brake Lining/Pad Measurement (mm)

Axles (front)	Lining/Pad	Left	Right
1	Lining (Shoe)	16	16
2	Lining (Shoe)	14	16
3	Lining (Shoe)	16	16
Comment:			

Rotor Thickness or Drum Inside Diameter Measurement (mm)

Axles (front)	Rotor/Drum	Left	Right
1	Drum	0.00	0.00
2	Drum	0.00	0.00
3	Drum	0.00	0.00
Comment:			

Inspection Comments:

Has this Vehicle been road tested? No When?

Name of the person who did the road test:

Inspector Name: Christy William Christopher

Signature:

This Inspection Report was submitted to CVSE on 2022-May-31 08:09 AM

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014

5/31/2022 8:09:28 AM