



Commercial Vehicle Inspection Report

Decal Number: GN32108
Decal Expiry Date: 2026-Sep-30
Inspection Number: 21715826

L06-2
Inspection Result:
PASS

2026232

FACILITY: HARKO HEAVY DUTY LTD. / S17130
INSPECTOR: KRAJNC, HAYDEN / 202196
WORK ORDER #: POWDER VENTURES PV-88
INSP. TYPE: Complete
INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
INSP. REASON: Semi-annual
INSP. START: 2026-Mar-31 07:00 AM PDT
INSP. COMPLETE: 2026-Mar-31 08:30 AM PDT

VEHICLE JUR: British Columbia
PLATE #:
LICENCED GVW(kg): 39500
VEHICLE YEAR: 2001
MAKE: MACK
MODEL:
REGI: 12570548
UNIT/FLEET#: PV-88
BODY STYLE: Dump Truck
ODOMETER: 393596 KM
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 1M1AA18Y71W144029
OWNER/LESSEE NAME: POWDER VENTURES, LTD
ADDRESS: 2576 MOUNTAIN VIEW DR
Sun Peaks, British Columbia
V0E5N0, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Repaired (same day) REPLACED 2L SHOCK.
Section 3 - Brake System	Repaired (same day) REPAIRED AIRLEAK AT REAR AXLES.
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) REPLACED LP LAMP, REPAIRED WIRING TO TAIL LIGHT. REPLACED ROOF MARKER.
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	35	36	10			11	✓
2	Clamp	30L	Automatic	39	40	9	8	8	8	
3	Clamp	30	Automatic	37	36	10	9	9	10	

Comment:

Comment:

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)		Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	55	65	Lining (Shoe)	17	16	Drum		
2	80	81	Lining (Shoe)	12	12	Drum		
3	85	85	Lining (Shoe)	11	11	Drum		

Comment:

Comment:

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Road Test Date:

Road Tester:

Inspector: KRAJNC, HAYDEN

Signature:

This Inspection Report was submitted to CVSE on 2026-Mar-31 10:30 AMPDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VP at the Commercial Vehicle Safety Enforcement.

CVSE0014

3/31/2026 10:30:43 AM PDT