



# Commercial Vehicle Inspection Report

Decal Number: GC09047  
Decal Expiry Date: 2025-Jun-30  
Inspection Number: 20959846

LD6-3  
Inspection Result:  
**PASS**

FACILITY: LIGHTHOUSE MECHANICAL / S6863  
INSPECTOR: Chahal, Jaswinder Singh / 203652  
WORK ORDER #: 533V228  
INSP. TYPE: Complete  
INSP. CLASS: Class 3 - Trailer and Semi-Trailer  
INSP. REASON: Annual  
INSP. START: 2024-Jun-06 12:00 PM PDT  
INSP. COMPLETE: 2024-Jun-06 01:30 PM PDT

VEHICLE JUR: British Columbia  
PLATE #: 62475B  
LICENCED GVW(kg): 999999  
VEHICLE YEAR: 2007  
MAKE: VANGUARD  
MODEL:  
REGI: 03644790  
UNIT/FLEET#: 533V228  
BODY STYLE: Van Trailer  
ODOMETER:  
HUB ODOMETER: 3921 KM  
BRAKE TYPE: Air  
FUEL TYPE:  
VIN: 5V8VA53B77M700322  
OWNER/LESSEE NAME: Comox Valley, Distribution Ltd.  
ADDRESS: 11398 Bridgeview Drive  
Surrey, British Columbia  
V3R0C2, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) replace #2 left brake pot, #2 left linings & drum, #1 right drum replaced
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) door hinge butt broken
Section 9A - Tires	Passed
Section 9B - Wheels	Repaired (same day) #1 left wheel seal leaking
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

## Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	44	45	6	6	8	8	
2	Clamp	30	Automatic	42	43	8	8	10	8	
3	Clamp	30	Automatic	48	44	8	8	9	9	

Comment:

Comment:

## Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	75	60
2	80	65
3	60	55

Comment:

## Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	16	18
Lining (Shoe)	12	18
Lining (Shoe)	16	17

Comment:

## Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum	421.39	0.00
Drum	421.13	0.00
Drum	0.00	0.00

Comment:

## Inspection Comments:

Has this Vehicle been road tested? No  
Inspector: Chahal, Jaswinder Singh  
Road Test Date: Ch Ch  
Signature: Ch Ch  
Road Tester:

This Inspection Report was submitted to CVSE on 2024-Jun-06 04:02 PM PDT  
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

## NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement

CVSE0014

6/6/2024 4:02:29 PM PDT