



Commercial Vehicle Inspection Report

Decal Number: GP27481
Decal Expiry Date: 2027-Jan-31
Inspection Number: 21857726

L06-3
Inspection Result:
PASS

2026232

FACILITY: HARKO HEAVY DUTY LTD. / S17130
INSPECTOR: KRAJNC, HAYDEN / 202196
WORK ORDER #: POWDER VENTURES PV-97
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Semi-annual
INSP. START: 2026-Jul-23 10:02 AM PDT
INSP. COMPLETE: 2026-Jul-23 11:32 AM PDT

VEHICLE JUR: British Columbia
PLATE #:
LICENCED GVW(kg): 999999
VEHICLE YEAR: 1990
MAKE: MIDLAND
MODEL:
REGI: 06698924
UNIT/FLEET#: PV-97
BODY STYLE: Dump Trailer
ODOMETER:
HUB ODOMETER:
BRAKE TYPE: Air
FUEL TYPE:
VIN: 2C9B2S4D7LR018138
OWNER/LESSEE NAME: POWDER VENTURES, EXCAVATING
ADDRESS: 2576 MOUNTAIN VIEW DR
Sun Peaks, British Columbia
V0E5N0, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) REPLACED 2R PIGGYBACK.
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Repaired (same day) REPLACED REAR RH MARKER AND TAIL LIGHT, FRONT LH AMBER MARKER.
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Repaired (same day) WELDED RH SUPPORT.
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Manual	36	37
2	Clamp	30	Manual	37	36
3	Clamp	30	Manual	35	35

Comment:

Tire Tread Depth (mm)

	Outer L	Inner L	Inner R	Outer R	Steering
	10	10	9	9	
	10	11	8	8	
	8	8	9	7	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	89	90
2	75	75
3	85	70

Comment:

Brake Lining/Pad (mm)

	Lining/Pad	Left	Right
	Lining (Shoe)	11	11
	Lining (Shoe)	13	13
	Lining (Shoe)	11	14

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

	Rotor/Drum	Left	Right
	Drum		
	Drum		
	Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No

Inspector: KRAJNC, HAYDEN

Road Test Date:

Signature: 

Road Tester:

This Inspection Report was submitted to CVSE on 2026-Jul-23 01:09 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSQVIP at the Commercial Vehicle Safety Enforcement

CVSE0014

7/23/2026 1:09:13 PM PDT