



# Commercial Vehicle Inspection Report

Decal Number: GH28898  
Decal Expiry Date: 2026-Jan-31  
Inspection Number: 21213797

Inspection Result:  
**PASS**

FACILITY: LIGHTHOUSE MECHANICAL / S6863  
INSPECTOR: DYCK, ALLAN TRENT / 113057  
WORK ORDER #:  
INSP. TYPE: Complete  
INSP. CLASS: Class 3 - Trailer and Semi-Trailer  
INSP. REASON: Annual  
INSP. START: 2025-Jan-20 03:30 PM PST  
INSP. COMPLETE: 2025-Jan-21 10:30 AM PST

VEHICLE JUR: British Columbia  
PLATE #: 52144B  
LICENCED GVW(kg): 999999  
VEHICLE YEAR: 2006  
MAKE: VANGUARD  
MODEL:  
REGI: 03450915  
UNIT/FLEET#: 533V203  
BODY STYLE: Van Trailer  
VIN: 5V8VA53B96M603248  
OWNER/LESSEE NAME: Comox Valley, Distribution Ltd.  
ADDRESS: 11398 Bridgeview Drive, 11398 Bridgeview Drive  
Surrey, British Columbia  
V3R0C2, Canada  
ODOMETER:  
HUB ODOMETER: 8659 KM  
BRAKE TYPE: Air  
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day)
Section 3A - Air Brakes	Repaired (same day)
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Repaired (same day)
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

## Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	45	45	7.1	6.4	5.3	6.7	
2	Clamp	30	Automatic	46	45	7.5	8.5	5.1	3.1	
3	Clamp	30	Automatic	49	40	7.7	7.5	7	6.1	

Comment:

Comment:

## Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	54	52
2	38	45
3	56	48

Comment:

## Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	17	17
Lining (Shoe)	20	17
Lining (Shoe)	17	16

Comment:

## Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum	0.00	421.20
Drum	0.00	0.00
Drum	0.00	0.00

Comment: Only #1 RH drum removed

## Inspection Comments:

Has this Vehicle been road tested?

No

Road Test Date:

Signature:

*Allan Dyck*

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Jan-22 11:32 AM PST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

## NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVP at the Commercial Vehicle Safety Enforcement.

CVSED014

1/22/2025 11:32:55 AM PST

