



# Commercial Vehicle Inspection Report

Decal Number: FW56299  
Decal Expiry Date: 2024-Jan-31  
Inspection Number: 20387411

Inspection Result: PASS

L06-9

Facility: WAYNE VYE TRUCK & EQUIPMENT REPAIR / S7083  
Inspector: VYE, WAYNE GORDON / 100167  
Work Order Number: 21816  
Inspection Type: Complete  
Inspection Class: Class 3 - Trailer and Semi-Trailer  
Inspection Reason: Annual  
Inspection Start Date/Time: 2023-Jan-25 09:30 AM  
Inspection Complete Date/Time: 2023-Jan-25 11:09 AM

Vehicle Jurisdiction: British Columbia  
Registration Number: 04304603  
VIN: 2H8V04823TX000824  
Plate Number: 16942U  
Licensed GVW (kg): 999999  
Vehicle Year: 1996  
Make: FRUEHAUF  
Brake Type: Air  
Fuel Type:  
Odometer:  
Hub Odometer:  
Body Style: Van Trailer  
Model:  
Unit/Reet Number: 38GT01  
Owner/Lessee Name: COMOX VALLEY DISTRIBUTION LTD, COMOX  
Address: 11398 BRIDGEVIEW DR, 11398 BRIDGEVIEW DR  
City: Surrey  
Province/State: British Columbia  
Postal Code/ZIP: V3R0C2  
Country: Canada

	Result	Comment
Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Not Applicable	
Section 2 - Suspension	Passed	
Section 3 - Brake System	Repaired (same day)	REPLACE #1 AXLE RIGHT PIGGYBACK
Section 3A - Air Brakes	Passed	
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Not Applicable	
Section 5 - Instruments and Auxiliary Equipment	Not Applicable	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed	
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Passed	

## Brake Chamber Type, Size and Push Rod Stroke Measurements (mm)

Axles (front)	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	34	33
2	Clamp	30	Automatic	33	35

Comment:

## Tire Tread Depth (mm)

Axles (front)	Outer Left	Inner Left	Inner Right	Outer Right	Steering Axle?
1	6	8	7	6	
2	13	13	13	13	

Comment:

## Brake Camshaft Rotation Measurement (degrees)

Axles (front)	Left (degrees)	Right (degrees)
1	50	80
2	40	40

Comment:

## Brake Lining/Pad Measurement (mm)

Axles (front)	Lining/Pad	Left	Right
1	Lining (Shoe)	17	14
2	Lining (Shoe)	18	18

Comment:

## Rotor Thickness or Drum Inside Diameter Measurement (mm)

Axles (front)	Rotor/Drum	Left	Right
1	Drum	0.00	0.00
2	Drum	0.00	0.00

Comment: DNR

## Inspection Comments:

Has this Vehicle been road tested? No When? Name of the person who did the road test:

Inspector Name: VYE, WAYNE GORDON

Signature:

This Inspection Report was submitted to CVSE on 2023-Jan-25 11:10 AM

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

## NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/MP at the Commercial Vehicle Safety Enforcement

CVSE0014

1/25/2023 11:10:25 AM