Commercial Vehicle Inspection Report

BRITISH COLUMBIA

Decal Number:	GM71514
Decal Expiry Date:	2027-Feb-28
Inspection Number:	21667024

2026282

Inspection Result: **PASS**

FACILITY:	HEPPNER HD TRUCK REPAIR LTD / S14040	INSP. TYPE:	Complete	INSP. START:	2026-Feb-16 09:00 AM PST
		INSP. CLASS:	Class 3 - Trailer and Semi-Trailer	INSP. COMPLETE:	2026-Feb-16 12:00 PM PST
INSPECTOR:	VANDERSPEK, PETER MATHEW / 100333	INSP. REASON:	Annual		
WORK ORDER #:	3924				

VEHICLE JUR:	British Columbia	REGI:	00999471	VIN:	1UYVS35368G361919
PLATE #:		UNIT/FLEET#:	D363	OWNER/LESSEE NAME:	J.D., TRANSPORT LTD
LICENCED GVW(kg):	999999	BODY STYLE:	Van Trailer	ADDRESS:	PO BOX 2543 STN SARDIS MAIN
VEHICLE YEAR:	2008	ODOMETER:			Chilliwack, British Columbia
MAKE:	UTILITY	HUB ODOMETER:			V2R1A8, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Not Applicable	
Section 2 - Suspension	Repaired (same day)	AIR LEAK AT R/S # 3 AIR BAG
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Repaired (same day)	REPLACE BRAKE SHOES AND DRUM ON L/S #3 AXLE.
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Not Applicable	
Section 5 - Instruments and Auxiliary Equipment	Not Applicable	
Section 6 - Lamps	Repaired (same day)	R/S TAIL LIGHT AND R/R MARKER LIGHT NOT WORKING. REFLECTIVE TAPE FALLING OFF BACK.
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Passed with Caution	LOT'S OF RUST ON FRAME AND SIDES.
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Passed	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	47.6	47.6
2	Clamp	30	Automatic	47.6	50.8
3	Clamp	30	Automatic	54	47.6

Comment:

Tire Tread Depth (mm)

Outer L	Inner L	Inner R	Outer R	Steering
11.43	10.44	9.6	9.32	
6.52	6.43	8.98	5.25	
4.51	3.57	5.38	5.77	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	50	55
2	55	60
3	120	60

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	16	15
Lining (Shoe)	15	14
Lining (Shoe)	8	14

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No **Road Test Date:**

Inspector: VANDERSPEK, PETER MATHEW **Signature:** PMatthew **Road Tester:**

This Inspection Report was submitted to CVSE on 2026-Feb-17 04:52 PM PST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection report, administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Manager, ASD/VIP at the Commercial Vehicle Safety Enforcement.

CVSE0014
2/17/2026 4:52:42 PM PST