



Commercial Vehicle Inspection Report

Decal Number: GF01356
Decal Expiry Date: 2025-Nov-30
Inspection Number: 21157880

Inspection Result:
PASS

FACILITY: True North Forklifts Ltd / S20179
INSPECTOR: Barrett, Daniel David / 203233
WORK ORDER #:
INSP. TYPE: Complete
INSP. CLASS: Class 3 - Trailer and Semi-Trailer
INSP. REASON: Annual
INSP. START: 2024-Nov-27 10:16 AM PST
INSP. COMPLETE: 2024-Nov-27 12:16 PM PST

VEHICLE JUR: British Columbia
PLATE #: 39023J
LICENCED GVW(kg): 999999
VEHICLE YEAR: 2010
MAKE: GREAT DANE
MODEL:
REGI: 09514025
UNIT/FLEET#: 5332
BODY STYLE: Van Trailer
ODOMETER:
HUB ODOMETER: 546074 KM
BRAKE TYPE: Air
FUEL TYPE:
VIN: 1GRAA0625AB704443
OWNER/LESSEE NAME: ARGUS, CARRIERS LTD, ARGUS
ADDRESS: 3839 MYRTLE STREET, 3839 MYRTLE STREET
Burnaby, British Columbia
V5C4G1, Canada

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Not Applicable	
Section 2 - Suspension	Repaired (same day)	#1 AXLE L/S AIR BAG CRACKING REPLACED TO NEW #2 AXLE BOTH SIDE AIR BAG CRACKING REPLACED TO NEW
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Repaired (same day)	REPLACED #2 AXLE L/S BRAKE POT BROKEN SPRING REPLACED #2 AXLE BOTH SIDES BRAKE LINING CRACKED
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Not Applicable	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Repaired (same day)	REPLACE WORN DOCK BUMPERS BOTH SIDES
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Not Applicable	
Section 11 - Other Vehicle Components	Passed	

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	30	Automatic	38	38
2	Clamp	30	Automatic	38	38

Comment:

Tire Tread Depth (mm)

	Outer L	Inner L	Inner R	Outer R	Steering
	9	9	8	9	
	10	10	13	13	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	45	50
2	60	60

Comment:

Brake Lining/Pad (mm)

	Lining/Pad	Left	Right
	Lining (Shoe)	16	16
	Lining (Shoe)	13	13

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

	Rotor/Drum	Left	Right
	Drum		
	Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested?

No

Road Test Date:

Inspector: Barrett, Daniel David

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2024-Nov-27 12:17 PMPST

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VP at the Commercial Vehicle Safety Enforcement

CVSE0014

1/27/2024 12:17:23 PM PST