

Whelans Group ABN 83 143 750 449



Technician Name: Kima Clamanto	Date: 🗥	Nov 125
Unit No: TL32 (A)		
Make: Side Tisser (A) Model:	Km's/Hours:	7
- The topper		
Job Description:		7 W. T. H.
Service		
Service Papares		
rdrap		
*		
Additional work required or any safety concerns noted:		
- Ball Race O.b	-	
	4	
*		
	1	9
Detailed description of completed works Including any parts used:		WALL CO.
I		



- Chack rived.
- Lionoct Bocarnon Ok
- hopet Bourney Ok - Repair wining CHS/R decence inglot
- Pouris wising licence alote liest
- Repair wing licence plate light - Tightered Bolt Race Bolts

12/3/25
/



Trailer Inspection Form - Workshop

Trailer No / Rego / Kms:	THEST TL32	(A)		
Date:	11. Mw.25	Job:	Service	
Service By:	Jamos	Signed:	Ny	

Item Check	Yes	No	N/A or Comments
Operation Manual Available?			
Fire Extinguisher Fitted and Tagged?			
Check condition of Hydraulic Lines / Hoist for Leaks / Pivot Points	4		
Check Ringfeeder for condition and any movement / split pin in lock nut, record measurements found		D	
All controls/switches identified		1	
All levers, controls & switches have appropriate knobs	ⅎ		
Check and test tarp system for operation	ⅎ		
All exposed electrical wiring in serviceable condition	₩.		
Check operation park/service/emergency brakes			
Backup/travel alarm fitted and operational	₽′		
Check for any cracks in bin/chassis/axles repair if required	Ø		
External lighting fitted, condition and operational	7		
Check toe eye bush / replace if needed	·	□Z	Mm max toe eye 51.5mm
Check condition of brake hoses/valves, repair any air leaks	₽		
Check brake lining condition and report values	Ø		Dire
Check and grease all grease points / replace if needed	□ /		mm
Safety signs fitted / serviceable condition	Ø.		
Guards fitted as intended and safe operational	ত্র		
condition	<u> </u>		
Inspect trailer panels for damage 3 points of contact are available for accessing trailer		Ø	
internals	<u> </u>		-
Steps/footings in safe useable condition	<u> </u>		
Handrails/grabs in safe useable condition	<u> </u>		mm
Inspect/record ball race movement Remove hub caps, inspect grease / check/adjust wheel bearings	12/		
Check tyre pressures, rims, wheel nuts for tension	Ω [']		
Check tailgate safety lock is working correctly	e e		
Check load pressure gauges	<u> </u>		-
Check dolly ball race for wear, record measurement	Ø		0 · 6 mm
Check ejecta trailer blades and sweep assembly			0.0
Check safety switches for ejecta			
Clean and check underbody guards for ejecta	=	可	
Inspect ball race mount bolts, tension or replace if		1	T: \ \ \ \ a \
needed	Ū∕	, DEC	Tightened
Inspect tailgate lock mechanism	Ø		
Inspect tailgate seals, and repair if needed	D		
Check airbags and mounting	Ø		

Comments

