

Bild Equipment Pty Ltd

ACN 088 563 571
ABN 088 563 571

133 Metro Link Circuit
Campbellfield, Vic 3061

Postal Address: PO Box 437
Somerton, VIC 3062

Telephone: 03 9357 0770

SERVICE JOB REPORT

Work Order Number: **WO 20780**

HR/KM Service: **500hr**

Department: Bild Group	Date: 28/05/2028
Asset Make/Model: HAMM 3414	Asset Number: N98
Vin/Serial No: WGTH0H180LH1A04014	Hrs/Kms to Date: 2426hr

Job Description: **Carry out 500hr service**

Works Carried out: **Carried out service as per schedule
changed engine oil + filter, fuel filters x3
air filters x2. inspected for defects.
tapped up fluids**

Part Used:	Part Number:	Oil type & Quantity used:
Caterpillar oil		10L 15W40
500hr		

Job Start Time:	Job Finish time:	Total (hours)
7:30am	12pm	4.5hr

Next Service: 2950hr	Signed: JS
-----------------------------	-------------------