



RDO Equipment Pty Ltd  
415 Fitzgerald Road  
Derrimut VIC 3026  
Ph 03 8851 6200  
ABN: 58 060 286 759  
ACN: 060 286 759

Branch

MELBOURNE

Date

24/02/25

Account No.

0770011

Ship Via

ABN

28 097 282 981

Time

00:05:30 (B)

Phone No.

03 9357 0770

Purchase Order

469001091

ACN

Salesperson

LM8

Ship to: SAME AS BELOW

Invoice to: BITU-MILL CIVIL PTY LTD  
PO BOX 437  
SOMERTON VIC 3062

WORKSHOP SERVICE TAX INVOICE

| Rego / Fleet |                   | HRS  | PIN/EIN           | WARRANTY DATE | HRS    |
|--------------|-------------------|------|-------------------|---------------|--------|
| X137713      | 670G MOTOR GRADER | 4423 | 1DW670GPHMD712287 | 18/12/22      | 2000   |
| Y355         | 670G              |      | RG6090L145346     | 16/12/24      | 5000 H |

SEGMENT# 1 C AMJ03 PM20-0500 20/02/25 20/02/25 20/02/25  
500 HOUR SERVICE (D680878-)

REPAIR:

- 4500hr service carried out as per service manual
- Check axle oil level
- Check brake accumulator
- Check circle gear case oil level
- Check tandem oil level
- Drain and refill engine oil and replace filter
- Lubricate as per list
- Replace auxiliary fuel filter and water separator
- Replace final fuel filter
- Replace primary fuel filter and water separator
- Take axle oil sample
- Take engine oil sample
- Take hydraulic oil sample
- Take tandem oil sample x 2
- Take transmission oil sample
- hyd oil found low, topped up
- axle oil found low, topped up.
- mullboard side shift cylinder is leaking very badly, chrome is damaged and cylinder requires replacement.
- mullboard tilt hydraulic cylinder leaking from fitting, fitting removed and o-ring replaced. no longer leaking.
- Please note:
- operator is concerned with persistence intermitted articulation fault HVC 521900.10, code has been lodged 15 times in the last 500 hours.
- articulation sensor calibration carried out, EH

CONTINUED ON PAGE 02

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account  
Contact [ar@rdoequipment.com.au](mailto:ar@rdoequipment.com.au) for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at [www.rdoequipment.com.au](http://www.rdoequipment.com.au) and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd  
415 Fitzgerald Road  
Derrimut VIC 3026  
Ph 03 8851 6200  
ABN: 58 060 286 759  
ACN: 060 286 759

Branch

MELBOURNE

Date

24/02/25

Account No.

0770011

Ship Via

ABN

28 097 282 981

Time

00:05:30 (B)

Phone No.

03 9357 0770

Purchase Order

469001091

ACN

Salesperson

LM8

Ship to: SAME AS BELOW

Invoice to: BITU-MILL CIVIL PTY LTD  
PO BOX 437  
SOMERTON VIC 3062

WORKSHOP SERVICE TAX INVOICE

| Rego / Fleet                                                                                                                                        | HRS                         | PIN/EIN           | WARRANTY DATE | HRS     |
|-----------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------------|-------------------|---------------|---------|
| X137713 670G MOTOR GRADER                                                                                                                           | 4423                        | 1DW670GPHMD712287 | 18/12/22      | 2000    |
| Y355 670G                                                                                                                                           |                             | RG6090L145346     | 16/12/24      | 5000 H  |
| articulation calibration carried out, sensor voltage checked, and could not fault sensor at this time. if fault returns recommend replacing sensor. |                             |                   |               |         |
| - lower mullboard wear inserts are almost worn though. recommend replacing top and bottom inserts.                                                  |                             |                   |               |         |
| - operator is concerned with play in circle. there is still life left in inserts but adjustment is required or replacement of inserts.              |                             |                   |               |         |
| - axle belly plate is very bent and axle cooling return hose is damaged, recommend replacing this hose and repairing or replacing belly plate.      |                             |                   |               |         |
| AT365869                                                                                                                                            | FUEL FILTER                 | 1                 | 100.01        | 100.01  |
| CM23882                                                                                                                                             | Scan Test Kit               | 6                 | 42.42         | 254.52  |
| CP6657                                                                                                                                              | Plus-50 1l 5L               | 2                 | 44.20         | 88.40   |
|                                                                                                                                                     | Plus-50 II Oil 15W40 CK4/SN |                   |               |         |
| CP6658                                                                                                                                              | Plus-50 II 20L              | 1                 | 166.32        | 166.32  |
|                                                                                                                                                     | Plus-50 II Oil 15W40 CK4/SN |                   |               |         |
| DZ118283                                                                                                                                            | OIL FILTER                  | 1                 | 59.08         | 59.08   |
| RE525523                                                                                                                                            | FILTER ELEMENT              | 1                 | 159.75        | 159.75  |
|                                                                                                                                                     | PARTS                       |                   |               | 828.08  |
|                                                                                                                                                     | LABOUR                      |                   |               | 700.00  |
| 10401099                                                                                                                                            | SEGMENT TOTAL==>            |                   |               | 1528.08 |

SEGMENT# 2 C AMJ03 STT-40 20/02/25 20/02/25 20/02/25

TRAVEL, ROUND TRIP

REPAIR:

MITCH 0439 346 696

26 HUNTINGTON AVE BONNYBROOK

NOTES:

plumpton road closed, had to go around the long way

CONTINUED ON PAGE 03

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account  
Contact [ar@rdoequipment.com.au](mailto:ar@rdoequipment.com.au) for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at [www.rdoequipment.com.au](http://www.rdoequipment.com.au) and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard



RDO Equipment Pty Ltd  
415 Fitzgerald Road  
Derrimut VIC 3026  
Ph 03 8851 6200  
ABN: 58 060 286 759  
ACN: 060 286 759

Branch

MELBOURNE

Date

24/02/25

Time

00:05:30 (B)

Page

03

Account No.

0770011

Phone No.

03 9357 0770

Invoice No.

WN3333

Ship Via

Purchase Order

469001091

ABN

28 097 282 981

ACN

Salesperson

LM8

Ship to: SAME AS BELOW

Invoice to: BITU-MILL CIVIL PTY LTD  
PO BOX 437  
SOMERTON VIC 3062

WORKSHOP SERVICE TAX INVOICE

| Rego / Fleet |                   | HRS  | PIN/EIN           | WARRANTY DATE | HRS    |        |
|--------------|-------------------|------|-------------------|---------------|--------|--------|
| X137713      | 670G MOTOR GRADER | 4423 | 1DW670GPHMD712287 | 18/12/22      | 2000   |        |
| Y355         | 670G              |      | RG6090L145346     | 16/12/24      | 5000 H |        |
|              |                   |      | LABOUR            |               |        | 408.00 |
| 10401099     |                   |      | SEGMENT TOTAL==>  |               |        | 408.00 |

\*\*\*\*\* WORK ORDER TOTALS \*\*\*\*\*

|               |         |
|---------------|---------|
| PARTS         | 828.08  |
| LABOUR        | 1108.00 |
| Consumables   | 88.64   |
| Environmental | 33.24   |
| SUB TOTAL==>  | 2057.96 |
| GST           | 205.80  |
| ON ACCOUNT    | 2263.76 |

Please remit to:  
BSB: 014-657  
Account: 7754 77613  
Name: RDO Equipment Pty Ltd

Payment due on delivery / pick up unless invoiced to 30 Day End of Month Account  
Contact [ar@rdoequipment.com.au](mailto:ar@rdoequipment.com.au) for all account enquiries

Legal Information

RDO Equipment Pty Ltd and its related bodies corporate have Standard Terms and Conditions of Sale (Standard Terms). The Standard Terms may vary from time to time and are available at [www.rdoequipment.com.au](http://www.rdoequipment.com.au) and upon request. The Standard Terms form part of this transaction. By completing this transaction, the Buyer certifies that (1) it has read and understands and agrees to be bound by the Standard

Bild Equipment Pty Ltd

ACN 088 563 571  
ABN 88 088 563 571

133 Metro Link Circuit  
Campbellfield, Vic 3061

Postal Address: PO Box 437  
Somerton, VIC 3062

Telephone: 03 9357 0770

## SERVICE JOB REPORT

Work Order Number: 20234

HR/KM Service: 1000hr

|                                    |                         |
|------------------------------------|-------------------------|
| Department: Bild Urban             | Date: 05/03/2026        |
| Asset Make/Model: John deere 670gp | Asset Number: Y355      |
| Vin/Serial No: 1WD670GPHMD71287    | Hrs/Kms to Date: 4937hr |

Job Description: Carry out 1000hr service

Works Carried out: Carried out service as per schedule.  
Replaced engine oil + filter, fuel filter x2  
air filter x2 Topped up 30L 15W40. inspected  
for defects. changed 2x cabin filters.

| Part Used:                 | Part Number: | Oil type & Quantity used: |
|----------------------------|--------------|---------------------------|
| Caterpillar Service<br>oil |              | 30L 15W40                 |
|                            |              |                           |
|                            |              |                           |
|                            |              |                           |
|                            |              |                           |

| Job Start Time: | Job Finish time: | Total (hours) |
|-----------------|------------------|---------------|
| 3:00pm          | 5:00pm           | 3 hours.      |

|                      |                                                                                              |
|----------------------|----------------------------------------------------------------------------------------------|
| Next Service: 5450hr | Signed:  |
|----------------------|----------------------------------------------------------------------------------------------|