



Commercial Vehicle Inspection Report

Decal Number: GK23187
Decal Expiry Date: 2026-Jan-31
Inspection Number: 21443039

L12-2172
Inspection Result:
PASS

FACILITY:	HARKO HEAVY DUTY LTD. / S17130	INSP. TYPE:	Complete	INSP. START:	2025-Jul-29 06:31 AM PDT
INSPECTOR:	KRAJNC, HAYDEN / 202196	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2025-Jul-29 08:01 AM PDT
WORK ORDER #:	ROBO PETE 741	INSP. REASON:	Semi-annual		
VEHICLE JUR:	British Columbia	REGI:	11448102	VIN:	1XPXD40X5FD269408
PLATE #:	SG9726	UNIT/FLEET#:	741	OWNER/LESSEE NAME:	ROBO TRANSPORT, LTD
LICENCED GVW(kg):	47000	BODY STYLE:	Truck Tractor	ADDRESS:	462 DENE DR, 462 DENE DR
VEHICLE YEAR:	2015	ODOMETER:	844028 KM		Kamloops, British Columbia
MAKE:	PETERBILT	HUB ODOMETER:			V2H1P4, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:	Diesel		

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Repaired (same day) REPLACED WASHER SPRAYER PUMP.
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Passed
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Disc	N/A	Not Applicable	0	0	10			10	
2	Clamp	30L	Automatic	39	38	11	10	12	11	✓
3	Clamp	30L	Automatic	38	37	12	11	10	9	

Comment:

Comment:

Brake Camshaft Rotation (degrees)

Axles	Left	Right	Brake Lining/Pad (mm)	Left	Right	Rotor Thickness or Drum Inside Diameter (mm)	Left	Right
1	0	0	Lining/Pad	17	17	Rotor/Drum	42.30	42.40
2	50	55	Pad	17	17	Rotor	0.00	0.00
3	30	40	Lining (Shoe)	19	18	Drum	0.00	0.00

Comment:

Comment:

Comment:

Inspection Comments:

Is this Vehicle been road tested?

No

Road Test Date:

Inspector: KRAJNC, HAYDEN

Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2025-Jul-29 04:13 PM PDT

The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

Personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement.

ED014

2025 4:13:11 PM PDT