



JEFFERSON FORD PTY LTD.
ABN 27 005 620 897

MENTONE:
58 Nepean Highway,
Mentone 3194
Ph: 9581 2525 Fax: 9581 2577
Email: jfm_service@jeffersonford.com.au



"The Greatest Car Dealer in the World"

ALL MAIL:
P.O. BOX 206, Mentone 3194

Service TAX Invoice			Page 2 of 3		Doc #: FOHSM778174		
Customer No. 4966129	Customer Name & Address Turf One Pty Ltd U 12/89 Simcock Avenue Spotswood VIC 3015			Advisor Ravneel Prasad 1823	Colour ARCTIC WHITE	Team SERVICE	
Doc. Date 09/07/25				Year / Make / Model 19/FORD/RANGER XLT 4x4 DOUBLE 3.2L TDCI 6		Tag No. 21	
Reg. No. BAK665				Model No. ANLJ95D	Carline RANGER	Eng./Trans. /A	
Stock No.				VIN No. MPBUMFF50KX20648	Kilometres 190686	Prod. Date 09/01/19	Orig. Del. Date 20/05/19
Purchase Order No.	Driver	Contract No.		Contract Name	Contract Exp. Kms	Exp. Date	
☐ CASH ☐ CHEQUE ☐ CREDIT CARD ☐ ACCOUNT	Home Phone	Business Phone 0418882313	Terms Cash	Selling Dealer 35220	Delivery Kms.	Delivery Date 20/05/19	Warr. Exp. Date 20/05/24
	Vehicle ID. MPBUMFF50KX206480	Engine No.		Date & Time Promised 09/07/25 02:30pm	Time Received 07:45am	Quote Price	Air Y
							Pwr Y
							Turb Y

Parts	Qty	Number	Description	Unit Price	Amount
Job# 1	1	FOF5TZ6734BA	GASKET DRAIN	14.70	14.70
Job# 1	1	FOJU2Z6731B	FILTER OIL	19.07	19.07
Job# 1	1	FOR147A	WASHER SOLUTN	4.30	4.30
Petrol, Oils, Lubricants and Supplies					Amount
Job# 1		TITAN F ECO-DT 5W30			120.40
Job# 1		ENVIRONMENT LEV/SHOP SUPP			27.73
<<< Total For Job 1 >>>					372.73
Job# 2		SAFE-T-STOP	Tech(s): 308		31.82
Perform Brake-Steering-Suspension -----SAFE-T-STOP----- ***** PASSED					
<<< Total For Job 2 >>>					31.82
Job# 3		ROTATE & BALANCE	Tech(s): 308		50.00
ROTATE & BALANCE WHEELS ***** R & R ALL WHEELS, BALANCE & ROTATE AS REQUIRED					
<<< Total For Job 3 >>>					50.00
Job# 4		ELECTRICAL CONCERN 2	Tech(s): 308		No Charge
C/S: parking proximity sensor is too sensitive ***** CARRIED OUT SELF TEST FOUND NO CODES AT TIME OF TESTING, RECALIBRATED SENSORS, TEST DROVE FOUND ALL WORKING AT TIME OF TESTING CUSTOMER TO MONITOR.					
Job# 5		ELECTRICAL CONCERN	Tech(s): 308		No Charge
C/S: entertainment display navigation Screen system is intermittently faulting, particularly the Navigation ***** CARRIED OUT INSPECTION FOUND NO MAPS, SUSPECT SYNC MODULE					



JEFFERSON FORD PTY LTD.
ABN 27 005 620 897

MENTONE:
58 Nepean Highway,
Mentone 3194
Ph: 9581 2525 Fax: 9581 2577
Email: jfm_service@jeffersonford.com.au



"The Greatest Car Dealer in the World"

ALL MAIL:
P.O. BOX 206, Mentone 3194

Service TAX Invoice		Page 1 of 3		Doc #: FOHSM778174	
Customer No. 4966129	Customer Name & Address Turf One Pty Ltd U 12/89 Simcock Avenue Spotswood VIC 3015		Advisor Ravneel Prasad 1823	Colour ARCTIC WHITE	Team SERVICE
Doc. Date 09/07/25			Year / Make / Model 19/FORD/RANGER XLT 4x4 DOUBLE 3.2L TDCI 6		Tag No. 21
Reg. No. BAK665			Model No. ANLJ95D	Carline RANGER	Eng./Trans. /A
Stock No.			VIN No. MPBUMFF50KX20648	Kilometres 190686	Prod. Date 09/01/19
				Orig. Del. Date 20/05/19	
Purchase Order No.	Driver	Contract No.	Contract Name	Contract Exp. Kms	Exp. Date
☐ CASH ☐ CHEQUE ☐ CREDIT CARD ☐ ACCOUNT	Home Phone	Business Phone 0418882313	Terms Cash	Selling Dealer 35220	Delivery Kms.
	Vehicle ID. MPBUMFF50KX206480	Engine No.	Date & Time Promised 09/07/25 02:30pm	Delivery Date 20/05/19	Warr. Exp. Date 20/05/24
			Time Received 07:45am	Quote Price	Air Y
				Pwr Y	Turb Y
ROADSIDE ASSISTANCE					

Labour	Operation	Description	Amount
--------	-----------	-------------	--------

Job# 1	195,000km/156mth Service Price Calculator Service	Tech(s): 308	186.53
--------	---	--------------	--------

195000 km Ford Service Price

Customer Instructions:
Carried out 195,000km/156 month Service Price Calculator Service.
Includes- Replaced engine oil & oil filter.
Checked all fluid levels & topped up as required.
Inspected battery condition.
Checked engine compartment hoses for leaks, wear & security.
Checked wiring for security, damage & correct routing.
Pressure tested cooling system.
Checked coolant level & concentration.
Inspected vacuum pump & hoses.
Inspected air intake system.
Inspected drive belt/s.
Inspected suspension & steering components.
Rotated wheels following manufacturers recommended sequence.
Tightened chassis & body bolts & nuts.
Checked drive shafts including CV boots.
Checked all powertrain components for fluid leaks.
Inspected exhaust system for security, leaks & damage.
Inspected fuel lines, hoses & connections.
Inspected brake lines, hoses & connections.
Checked condition of under body PVC coating.
Inspected wheel bearings.
Inspected brake pads, calipers & discs.
Inspected all tyre pressures & checked for wear.
Checked wheel covers (including retainer system).
Checked wheel nuts for correct tension.
Carried out visual body and paint check.
Inspected & lubricated bonnet & door hinges & catches.
Inspected parking brake operation.
Checked instrument cluster & warning lights.
Checked lights, wiper/washers, horn & electrical systems.
Inspected seat belts operation and condition.
Carried out ECU self test including idle speed & ABS check.
Checked vehicle for outstanding recall or service campaigns.
Replaced service reminder sticker.
Reset service indicator (if fitted).
Checked engine performance & driveability.
Checked for noise/wind noise, vibration, squeak, rattle.
Road tested vehicle & reported any defects.