

Date: 18/6/26 **TRAILER SERVICE & INSPECTION**

Customer: Build Group K19 km's: _____ Rego: 486 391

Mechanic to inspect, make adjustment, tighten, correct or add fluids on all operations listed Next Service Due: _____

Consult applicable service information for adjustment specification.

Tick= OK A= Adjust R=Repair

		✓	A/R	NOTES
Check	Wheel Bearing Movement	✓		
Check	Tyre Thread Depth & Condition	✓		
Check	Hub Fluid Levels	✓		
Check	Pins & Brushes	✓		
Check	for Air Leaks	✓		
Check	for Cracks	✓		
Grease	ALL Grease Fittings	✓		
Check	Suspension	✓		
Adjust	Brakes	✓		
Check	King Pin	✓		
Check	Lights & Reflectors	✓		
Check	Brake Condition			
	FRONT ONE AXEL	RH	70%	LH 70%
	FRONT TWO AXEL	RH		LH
	BACK ONE AXEL	RH		LH
	BACK 2 AXEL	RH		LH

TECHNICIAN REMARKS

- X4 AMBER reflectors ✓
- X1 White reflectors ✓
- Rear Safety Signs Faded
- HYDRAULIC SYSTEM BATTERY'S U/S
- Keep clear Signs on RUMPS Faded
- MISSING wheel nut indicators
- HYDRAULICS leaking