Daily Equipment Inspection & Service Record

EQUIPMENT NAME/NUMBER 19-141

Date 20 25		ODOMETER KM ● M ☐	HOUR METER	REPAIRS NEEDED	REPAIRS MADE BY	Date 20 25		INSPECTOR'S SIGNATURE
Sep 11	25			◦ Replaced left lift axle air bag ◦ Replaced left front drive air bag Parts: DCDL switch kit	ET Performance Inv 28326	Sep 11	25	
Nov 17	25				Rush Truck Centres Inv 3043985190	Nov 17	25	
Nov 18	25	495,318		◦ Repaired corroded wires ◦ Replaced pigtail ◦ Replaced first section of box harness ◦ Replaced both rear lights ◦ Replaced back-up beeper ◦ Replaced rest of box harness ◦ Replaced RR back-up light ◦ Replaced yellow side box light ◦ Perform 21-point inspection ◦ Replaced air dryer assembly ◦ Installed new pigtail for purge valve heater ◦ Drain water from tanks & ran alcohol through system ◦ Replaced left slack adjuster ◦ Installed new clevis ◦ Repaired auto greaser for slack adjuster ◦ Greased new slack adjuster	Rush Truck Centres Inv 3044054419	Nov 18	25	
Nov 20	25	494619		◦ Replaced drivers side mirror ◦ Changed fog light ◦ Replaced license plate light ◦ Complete battery service ◦ Replaced Right headlight bulb ◦ Re-pinned box light harness	Rush Truck Centres Inv 3044073026	Nov 20	25	
Nov 25	25	497126		◦ Resecured harness ◦ Perform 21 point inspection	Rush Truck Centres Inv 3044070475	Nov 25	25	
Dec 05	25	499468		◦ Completed Oil Change	In-House	Dec 05	25	
Dec 19	25			◦ Repaired leaking tire	Black Dog TireCraft Inv IM0067714	Dec 19	25	
Dec 31	25			Parts: ◦ Steering seal x2 ◦ Brake shoes x2 ◦ Brake drum x2	Rush Truck Centers Inv 3044944292	Dec 30	25	