

HT EFFICIENCY INC

100 COSTA RD

Concord, ON. L4K1N2

Phone: (647)-956-0852 | Fax: ()-

www.htefficiency.ca | info@htefficiency.ca

Invoice # 001459

Original Est # 1492

HST814786687R0001

Balance Due: \$3,995.23**2015 Isuzu - NPR**

Isuzu 4JJ1 LFB 4 CYL

VIN: JALB4W171 F7F00178

Odometer: In 162,833

License Plate: BZ58199 ON

Work Complete: 06/09/2026

Service Advisor: NASIR SHAHS

Customer ID: 175

Printed Date: 06/09/2026

Type	Description	Part #	Qty/Hr	Sale	Total
2 AXLE UNIT INSPECTION					\$3,895.34
Labor	ANNUAL INSPECTION		4.00 hr		\$400.00
	WHEELS OFF SAFETY INSPECTION				
Labor	OIL CHANGE		1.00 hr		\$125.00
Labor	COMPUTER DIAGNOSTIC		0.50 hr		\$62.50
Labor	1ST CYLINDER GLOW PLUG RENEW		0.75 hr		\$93.75
Labor	2ND CYLINDER GLOW PLUG RENEW		0.75 hr		\$93.75
Labor	R&I REAR LEAF SPRINGS BOTH SIDES		1.00 hr		\$1,140.00
Labor	AC DRIVE BELT ADJUSTMENT		0.25 hr		\$31.25
Part	OIL BULK	10W-30	10.00	\$6.14	\$61.40
Part	DEF	DEF	1.00	\$19.22	\$19.22
Part	RED COOLANT	COOLANT	1.00	\$5.00	\$5.00
Part	WINDSHIELD WASHER FLUID	WWF	2.00	\$2.94	\$5.88
Part	REGULAR LEAFS, CLIPS, CLIP BOLTS, CENTER BOLTS, U-BOLTS, DEEP NUTS	LEAF SPRING	1.00	\$883.12	\$883.12
Part	GLOW PLUG	8-98290-755	2.00	\$180.00	\$360.00
Part	OIL FILTER	2-9451-103-1	1.00	\$64.09	\$64.09
Part	FUEL FILTER	2-94561-105-2	1.00	\$52.10	\$52.10
Part	FUEL FILTER CARTRIDGE KIT	5-87610-157-0	1.00	\$50.14	\$50.14

Parts: \$1,500.95 Labor: \$1,946.25 Tax: \$448.14 Total: \$3,895.34

Order					\$99.89
Misc	Hazardous Materials				\$19.46
Misc	Shop Supplies				\$68.94
Total: \$99.89 Tax: \$11.49					


I hereby authorize the above repair work to be done along with the necessary material and hereby grant you and/or your employees permission to operate the car or truck herein described on street, highways or elsewhere for the purpose to testing and/or inspection. An express mechanic's lien is hereby acknowledged on above car or truck to secure the amount of repairs thereto. Warranty on parts and labor is one years or 12,000 miles whichever comes first. Warranty work has to be performed in our shop & cannot exceed the original cost of repair.

Labor	\$1,946.25
Parts	\$1,500.95
Hazardous Materials	\$19.46
Shop Supplies	\$68.94
Subtotal	\$3,535.60
Taxes	\$459.63
Order Total:	\$3,995.23

Signature _____ Date _____ Time _____
 Technician(s): Lichevetsky, Sergiy; Kozyriev, Oleksandr; PARTY, THIRD; YANKOVSKYY, IHOR




Annual Inspection Certificate
&
Safety Standards Certificate



VEHICLE INFORMATION			
Plate#:	BZ58199	Year:	2015
VIN:	JALB4W171F7F00178	Make:	ISUZU
GVWR (kg):	5897	Model:	NPR
Odometer (km):	162833	Type:	Truck

CERTIFICATE INFORMATION	
Annual Inspection Certificate	Expires at the end of: Jun 2027
Safety Standards Certificate	Expires at the end of: July 15, 2026
Vehicle Inspection Certificate Number	98T0AB13
Inspection Start Date	Jun 4, 2026 System Time: 10 : 06
Inspection End Date	Jun 9, 2026 System Time: 08 : 44

VEHICLE INSPECTION CENTRE	
Vehicle Inspection Centre #: 11070	Technician: SERGIY LICHEVETSKYY
HT EFFICIENCY INC.	
O/A HT EFFICIENCY INC.	
100 COSTA ROAD	
CONCORD, ON L4K1N2	Technician Signature
647-956-0852	Technician ID: 276393
	STO ID/Account: 19014598
	Trade Code: 310T, 310S

I certify that I inspected this vehicle on the inspection date in accordance with the inspection procedures established by directive under s. 100.7 of the Highway Traffic Act and that the vehicle meets the required equipment and performance standards as detailed in the Vehicle Inspection Report with the above referenced Vehicle Inspection Certificate Number.

This Certificate is not a warranty on the condition of the vehicle.

Vehicle Inspection Questions?

Call the Public Contact Centre 1-833-420-2103 or go to

<https://www.ontario.ca/page/driveon-emissions-and-safety-inspection-program>.

MTO Office use only: 22P1V5915829217495T3

MINISTRY OF TRANSPORTATION
SAFETY INSPECTION REPORT



Vehicle Inspection Certificate Number: 98T0AB13

Start Date / Time: Jun 4, 2026, 10:06 AM

End Date / Time: Jun 9, 2026, 8:44 AM

VEHICLE/ENGINE INFORMATION	CHASSIS	ENGINE
Plate#: BZ58199	Year: 2015	Year:
VIN: JALB4W171F7F00178	Make: ISUZU	Make:
GVWR(kg): 5897	Model: NPR	Size (L):
Odometer: 162833	Fleet ID:	

SAFETY INSPECTION RESULT	PASS
--------------------------	------

SAFETY SYSTEM INSPECTION RESULTS

All Safety System Components Passed Inspection
--

MANDATORY ITEMS

Inspection Item	Result	Inspection Item	Result
Axle 1, Driver Side Tire		Axle 1, Passenger Side Tire	
Tire Tread Depth (mm)	8	Tire Tread Depth (mm)	8
Initial Tire Pressure (kPa)	580	Initial Tire Pressure (kPa)	580
Disc Brakes		Disc Brakes	
Inner Friction Material Thickness (mm)	8	Inner Friction Material Thickness (mm)	8
Outer Friction Material Thickness (mm)	8	Outer Friction Material Thickness (mm)	8
Rotor Thickness (mm)	40.08	Rotor Thickness (mm)	40.35
Within OEM specifications?	Yes	Within OEM specifications?	Yes

Inspection Item	Result	Inspection Item	Result
Axle 2, Driver Side, Inner Tire		Axle 2, Passenger Side, Inner Tire	
Tire Tread Depth (mm)	5	Tire Tread Depth (mm)	5
Initial Tire Pressure (kPa)	580	Initial Tire Pressure (kPa)	580
Axle 2, Driver Side, Outer Tire		Axle 2, Passenger Side, Outer Tire	
Tire Tread Depth (mm)	5	Tire Tread Depth (mm)	6
Initial Tire Pressure (kPa)	580	Initial Tire Pressure (kPa)	580
Drum Brakes		Drum Brakes	
Bonded/riveted continuous strip		Bonded/riveted continuous strip	
Shoe Lining Thickness (mm)	7	Shoe Lining Thickness (mm)	7
Drum Inside Diameter (mm)	321.15	Drum Inside Diameter (mm)	321.4
Within OEM specifications?	Yes	Within OEM specifications?	Yes

Vehicle Inspection Centre #: 11070

HT EFFICIENCY INC.

100 COSTA ROAD

CONCORD, ON L4K1N2

647-956-0852

Software Version: 2025.06.18.1

Technician #: 276393

Name: SERGIY LICHEVETSKYY

Report Number: 12

Tablet ID: 8834

STO ID/Account: 19014598

Trade Code: 310T, 310S

Vehicle Inspection Questions? Call the Public Contact Centre 1-833-420-2103 or go to
<https://www.ontario.ca/page/driveon-emissions-and-safety-inspection-program>