

Owner Code/Schedule Number(s): ET09-1

RESIDUE LAST CONTAINED

Company: Camrose County

Consignor Name: _____

Address: 3755 43 Avenue

Phone Number: 780-672-4449

Transporter: Camrose County

Description of tank (including serial number): Hydrovac tank

Tank emptied:

YES ☒ NO ☐

please note all tanks must be emptied

Tank cleaned:

YES ☒ NO ☐

Tank purge/steamed:

YES ☐ NO ☒

3rd Party Certificate provided:

YES ☐ NO ☒

Last Contained:

WATER

☒

SAND

☒

DIESEL

☐

GASOLINE:

☐

Other:

It has been confirmed from operations that the tank was used for a combination of water and

sewer work, along with hydro-excavations, there were never any hydrocarbons in the tank. On the last use,

it could have been deemed a mixed use (water, sewer, dirt) and the tank was emptied and washed out with a Hotsy
pressure washer, but not steamed.

Consignor Signature:



Date:

July 23, 2025

Consignor Print Name:

Zach Mazure

INTERNAL USE ONLY