

Commercial Vehicle Inspection Report

Decal Number: GP36396
Decal Expiry Date: 2027-Feb-28
Inspection Number: 21891861

LV5-1
Inspection Result:
PASS

FACILITY:	Inland Truck & Equipment Ltd / S20220	INSP. TYPE:	Complete	INSP. START:	2026-Aug-21 05:30 PM PDT
INSPECTOR:	KOVACS, HARLEY QUINN / 301732	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2026-Aug-21 07:30 PM PDT
WORK ORDER #:	RA112001092	INSP. REASON:	Semi-annual		

VEHICLE JUR:	British Columbia	REGI:	10279276	VIN:	2FWJAZCV47AX59214
PLATE #:	DE1112	UNIT/FLEET#:		OWNER/LESSEE NAME:	Burnco Rock Products LTD., Burnco Rock Products LTD.
LICENCED GVW(kg):	46500	BODY STYLE:	Truck Tractor	ADDRESS:	5324 Riverbend Dr.
VEHICLE YEAR:	2007	ODOMETER:	221012 KM		Burnaby, British Columbia
MAKE:	STERLING	HUB ODOMETER:			V3N 4P8, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Passed
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Passed
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Passed

Air Brake Chamber Type, Size and Push Rod Stroke (mm)

Axles	Type	Size	Slack Adj.	Left	Right
1	Clamp	20	Automatic	30	30
2	Clamp	30L	Automatic	25	30
3	Clamp	30L	Automatic	30	30

Comment:

Tire Tread Depth (mm)

	Outer L	Inner L	Inner R	Outer R	Steering
1	13			13	✓
2	20	20	20	20	
3	19	19	19	20	

Comment:

Air Brake Camshaft Rotation (degrees)

Axles	Left	Right
1	55	55
2	35	75
3	55	55

Comment:

Brake Lining/Pad (mm)

Lining/Pad	Left	Right
Lining (Shoe)	17	17
Lining (Shoe)	16	12
Lining (Shoe)	15	15

Comment:

Rotor Thickness or Drum Inside Diameter (mm)

Rotor/Drum	Left	Right
Drum		
Drum		
Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No
Inspector: KOVACS, HARLEY QUINN

Road Test Date:
Signature:

Road Tester:

This Inspection Report was submitted to CVSE on 2026-Aug-21 07:30 PM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

CVSE0014

8/21/2026 7:30:45 PM PDT