

03911656

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

Vehicle Standards and Inspection
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba

A911524

Date Inspection Started 13 12 24 DAY MO. YR.
Date Inspection Completed 13 12 24 DAY MO. YR.
Inspection Expiry Date 31 12 25 DAY MO. YR.

Station Number A 6143 Station Name Reeset Truck & Trailer Service W. City
Mechanic Number 10267 Mechanic Signature K. Mysami Station Phone Number 2049524696
Vehicle Owner 9-WAY TRANSPORT INC.
Address 2792 SLOUGH ST City MISSISSAUGA Province ONT Postal Code L4T1G3 Phone 6476604929

Pass/Safe Vehicle ☒ Fail/Unsafe Vehicle ☒ Fail/Hazardous ☐
Licence Number PA90937 Prov. ONT NSC # Odometer Reading 383197 Odom. Type ☒ km ☐ mi
Vehicle Identification Number 3HSDZAPR1RN599200 Make INTL Model L7625 Year 24 Unit # 314
☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☐ GVWR ☐ KGS ☒ Truck Tractor ☐ Trailer ☐ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P R Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section

X Section 1 - Power Train: Defects (if any)

X Section 2 Suspension: Defects (if any)

X X Section 3 - Brake Systems: 3H 3A 15(E) ALL DRIVE Defects (if any) Circle Brake Type Brake Drum Worn out max limit 15 (C) ALL DRIVE Brake Shoes Worn out 13 (A) Both Gland Hand Worn out 14 (A) L-F-D Brake POT Spring Broken Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining		Drum/Rotor		Stroke	
	L	R	L	R	L	R
1	5/8	11/16	16540	16530	1/4	1/4
2	13/16	13/16	16500	16500	1/2	1/2
3	13/16	13/16	16500	16500	1/2	1/2
4						
5						
Final Measurement						

X Section 4 - Steering: Defects (if any)

X X Section 5 - Instruments & Auxiliary Equipment: Defects (if any) 7(Cb) Both Wiper Blade worn out

X Section 6 - Lamps: Defects (if any)

X X Section 7 - Electrical System: Defects (if any) 2(A) Battery cable Cracked 3 (Cb) Trailer EL Cord Plug Cracked

X X Section 8 - Body: Defects (if any) 3(E) Left side cab Shock leaking level 2

X X Section 9 - Tire & Wheel: Defects (if any) 4(A) Tire PSI uneven

Axle	Tread Depth mm				Air Pressure			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1								
2	9	9	11	11	100	86	90	100
3	9	9	10	10	100	100	100	82
4								
5								

X X Section 10 - Coupling Devices: Defects (if any) 7(CD) 8th wheel out of Adjustment

- THIS INSPECTION IS NOT A WARRANTY -
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: All Wheel Rebalance after 100 Km

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: Signature Date: 13-12-24