

04022607

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

Vehicle Standards and Inspection
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba

A911672

Date Inspection Started 14 09 25 DAY MO. YR.	Station Number A 6 1 4 3	Station Name Reed Truck & Trailer Service WPG	City
Date Inspection Completed 15 09 25 DAY MO. YR.	Mechanic Number 1 0 2 6 7	Mechanic Signature K. H. King	Station Phone Number 204 952 4696
Inspection Expiry Date 30 09 26 DAY MO. YR.	Vehicle Owner J-WAY TRANSPORT INC. 2792 SLOUGH ST MISSISSAUGA ONT L4T 1G3 647 535 5500 Address City Province Postal Code Phone		
☒ Pass/Safe Vehicle ☒ Fail/Unsafe Vehicle ☐ Fail/Hazardous	Licence Number PA86889	Prov. ON	NSC #
	Vehicle Identification Number 3HSDZAPR2PIN757993	Make INTL	Model LT625
	☒ Confirmed legible Vehicle Identification Number on vehicle	Year 23	Unit # 292
	Odometer Reading 557914	Odom. Type ☒ km ☐ mi	

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck GVWR KGS ☒ Truck Tractor Trailer Semi-Trailer Bus School Bus Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																						
X		Section 1 - Power Train: Defects (if any)																																																																						
X	X	Section 2 Suspension: Defects (if any) 7CC) ALL Drive Shockers Leaking Level 1																																																																						
X	X	Section 3 - Brake Systems: 3H 3A 18 (F) ALL Drive Defects (if any) Circle Brake Type Brake Pads Worn OUT 13 (A) Both Gland Hand Worn out 14 (A) L.R.D. R.F.D. L.F.D Brake Pot Spring Broken																																																																						
		Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection																																																																						
		<table><thead><tr><th rowspan="2">Axle</th><th colspan="2">Lining</th><th colspan="2">Drum/Rotor</th><th colspan="2">Stroke</th></tr><tr><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th></tr></thead><tbody><tr><td>1</td><td>Y2</td><td>9/16</td><td>1-660</td><td>1-662</td><td></td><td></td></tr><tr><td>2</td><td>3/4</td><td>3/4</td><td>1-668</td><td>1-665</td><td></td><td></td></tr><tr><td>3</td><td>3/4</td><td>3/4</td><td>1-665</td><td>1-672</td><td></td><td></td></tr><tr><td>4</td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>5</td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td colspan="7">Final Measurement</td></tr></tbody></table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	Y2	9/16	1-660	1-662			2	3/4	3/4	1-668	1-665			3	3/4	3/4	1-665	1-672			4							5							Final Measurement																					
Axle	Lining			Drum/Rotor		Stroke																																																																		
	L	R	L	R	L	R																																																																		
1	Y2	9/16	1-660	1-662																																																																				
2	3/4	3/4	1-668	1-665																																																																				
3	3/4	3/4	1-665	1-672																																																																				
4																																																																								
5																																																																								
Final Measurement																																																																								
X		Section 4 - Steering: Defects (if any)																																																																						
X	X	Section 5 - Instruments & Auxiliary Equipment: Defects (if any) 7Cb) Both Wiper Blade Worn out																																																																						
X		Section 6 - Lamps: Defects (if any)																																																																						
X	X	Section 7 - Electrical System: Defects (if any) 3Cb) Trailer ELEC Cord Plug Corroded																																																																						
X		Section 8 - Body: Defects (if any)																																																																						
X	X	Section 9 - Tire & Wheel: Defects (if any) 4(A) Tire PSI Uneven																																																																						
		<table><thead><tr><th rowspan="3">Axle</th><th colspan="4">Tread Depth mm</th><th colspan="4">Air Pressure</th></tr><tr><th colspan="2">Initial</th><th colspan="2">Corrected</th><th colspan="2">Initial</th><th colspan="2">Corrected</th></tr><tr><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th><th>L</th><th>R</th></tr></thead><tbody><tr><td>1</td><td>8</td><td>9</td><td></td><td></td><td>100</td><td>90</td><td></td><td>100</td></tr><tr><td>2</td><td>10</td><td>15</td><td>14</td><td>14</td><td>100</td><td>100</td><td>100</td><td>82</td></tr><tr><td>3</td><td>19</td><td>17</td><td>19</td><td>19</td><td>100</td><td>90</td><td>86</td><td>100</td></tr><tr><td>4</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr><tr><td>5</td><td></td><td></td><td></td><td></td><td></td><td></td><td></td><td></td></tr></tbody></table>	Axle	Tread Depth mm				Air Pressure				Initial		Corrected		Initial		Corrected		L	R	L	R	L	R	L	R	1	8	9			100	90		100	2	10	15	14	14	100	100	100	82	3	19	17	19	19	100	90	86	100	4									5								
Axle	Tread Depth mm				Air Pressure																																																																			
	Initial			Corrected		Initial		Corrected																																																																
	L	R	L	R	L	R	L	R																																																																
1	8	9			100	90		100																																																																
2	10	15	14	14	100	100	100	82																																																																
3	19	17	19	19	100	90	86	100																																																																
4																																																																								
5																																																																								
X		Section 10 - Coupling Devices: Defects (if any)																																																																						

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: ALL Wheel Retorque after 100 km

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by:

Signature

Date: