

XW09HL

ESN	Cust #	Chg	Date	Kms	Invoice #	Value \$	Fac	Description
79890811	130SERV	R6	250924	1387480	8203.82		130	Replace crank gear
79890811	290SERV	R1	260516	46752	7073889	618.66	290	Replace engine oil and filters
79890811	290SERV	R8	271217	507690	7655346	693.00	290	B service at 507,690 Klms
79890811	290SERV	W1	260516	46752	7012352		290	Oil leak at flywheel housing.
79890811	290SERV	W1	310516	48808	7030166		290	Malfunctioning doser pump
79890811	290SERV	W1	270317	7378034			290	LOW POWER
79890811	3211014	R1	280324	1428256	1200916	709.74	130	Carry out Tune up, no adblue flush.
79890811	3211014	R1	150125	1572492	1529227	7571.98	322	FC2372 - Derated, Rail Pressure
79890811	3211014	R8	311023	1383329	9964207	1139.53	212	Replace lube oil thermostat.
79890811	460SERV	R5	150219	779224	8098548	287.00	460	After treatment repairs