



Alberta Government



CV9868279

CERTIFICATE NUMBER

Commercial Vehicle Inspection Certificate
Traffic Safety Act

PART 1 - VEHICLE OWNER AND VEHICLE IDENTIFICATION

Vehicle Type:	Trailer	Seating Capacity:	
GWW:	kg	Brake Type:	Air
Owner Name:	Bar H&H Floris Ventures Ltd.		
Address:	19566 Township Road 492		
City:	Camrose County	Province:	AB
		Postal Code:	T0B2M1
Telephone Number:	(433) 358-4474		
Vehicle Identification Number:	1W9K4453K52278683		
Make:	Wilson	Model:	Tri-axle
Year:	2025	Unit Number:	
Odometer:	KM	License Plate Number:	6PR791
		Province:	AB

IT IS AN OFFENCE TO FALSIFY AN INSPECTION CERTIFICATE

PART 2 - CERTIFICATION

I certify the vehicle described in Part 1 has passed the inspections and tests established under the Traffic Safety Act for a Commercial Vehicle.

Inspection Facility Name:	Maximum Mechanical Repair (Camrose) Ltd.	Facility Number:	13294
Inspection Technician Name:	Bradley George	Technician Number:	C0040
Inspection Technician Signature:			
Inspection Date:	2026/03/20		

COMMERCIAL VEHICLE RECORD OF INSPECTION
TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

Section 10 - Couplers and Hitches			
Component	P	F	NA
10.4. Ball Type Hitch		<input checked="" type="checkbox"/>	
10.5. Ball-Coupling Hitch		<input checked="" type="checkbox"/>	

NOTES:

Certification
The Vehicle for which this Record of Inspection is issued has PASSED (Certificate #898279) the inspection and I certify it has been inspected in accordance with the Vehicle Inspection Regulations, Alberta Regulation 211/0095 and the applicable Inspection Manual.

Date of Inspection	Technician Number	Facility Number	Signature
2026/03/20	C0640	13294	

Customer Acknowledgment
I understand if a vehicle inspection identifies defects and repairs are required, once repaired, the vehicle and this Record of Inspection (ROI) may be presented to any vehicle inspection facility within 10 days of the initial inspection and only the failed items noted on this ROI are required to be re-inspected. If the vehicle is not returned for re-inspection within 10 days of the initial date of inspection, a new inspection must be conducted.

Date (Year/Month/Day)
2026/03/20
Customer Signature