



Vehicle History Summary

Bloomer
Transport

Fleet #	PM19
Registration	BC37RM
Make	Kenworth
Model	T402
VIN / Chassis #	6F5000000AA442267
Build Date	2010

Date	Reading / Units	Type / Repairer Notes	Repairer
XDE2 295/80R Retread T-11			
Retighten Wheels T-733			
14/10/2025	2,585,042 kms	A - A S-15456 Carried out A service as per service checklist	Workshop
07/10/2025	2,584,253 kms	A - A S-15421 Carried out A service as per service checklist	Workshop
30/09/2025	2,583,804 kms	A - A S-15378 Carried out A service as per service checklist	
25/09/2025	2,581,257 kms 2 hrs	air fitting repair R-2815 Installed remote trailer connection point behind cab. Made up new alloy plated and runny air lines and electrical lead to point and connected fitting. Made up new suzi coil. Tested ok.	Workshop
25/09/2025	2,581,257 kms 3 hrs	B - B S-15265 Carried out B service as per service checklist. Changed engine oil and filter. Changed fuel filters. Changed engine air cleaner. Inspected belts and pulleys- ok. Greased and adjusted. Brakes checked. Diff and gearbox oil levels ok. Steam cleaned chassis.	Workshop
25/09/2025		batteries R-2811 Fit four new batteries	R&J Batteries
17/09/2025	2,581,257 kms	A - A S-15205 Carried out A service as per service checklist	
11/09/2025		Pressure protection valve R-2777 Trouble shoot airbag fault. Diagnosed faulty protection valve. Removed and replaced. Tested ok.	workshop
08/08/2025	2,577,862 kms	A - A S-15034 Carried out A service as per service checklist	
16/07/2025	2,575,128 kms	A - A S-14935 Carried out A service as per service checklist	
07/07/2025	2,573,601 kms	A - A S-14902 Carried out A service as per service checklist	
07/07/2025	2,573,601 kms	Leaking diesel. R-2691 Inspected and repaired diesel leak, finding fuel solenoid, removed and replace fuel solenoid and o-rings cleaned and tested - OK.	Workshop
30/06/2025	2,573,059 kms	A - A S-14857 Carried out A service as per service checklist	

Date	Reading / Units	Type / Repairer Notes	Repairer
25/06/2025	2,571,561 kms	L/H head light not working and blinker fault. R-2672 Inspected and repaired L/H low beam fault disassembled checking wiring and connections - OK. Removed and checked bulb - tested OK. Also checked blinker fault finding bare wires in bonnet. Connected to blinkers, repaired wiring and tested OK.	Workshop
23/06/2025	2,571,561 kms	A - A S-14807 Carried out A service as per service checklist	
18/06/2025		cracked leaking CAC hose. R-2644 Inspected and repaired CAC hose hole in hose. Removed and replaced and tested ok.	Workshop
17/06/2025	2,571,134 kms	A - A S-14764 Carried out A service as per service checklist	
11/06/2025	2,569,516 kms	A - A S-14727 Carry out A service as per service checklist	
05/06/2025	2,564,996 kms	Tail shaft bearing kit R-2620 Inspected truck and found that cabin circuit breaker had popped, removed cover to breaker for access, reset and tested wiring inside cab and around breaker, all ok, found that crimp on wire from breaker getting hot, removed and re-crimped wire, re-assembled truck and tested, all ok, re-installed tail shaft and tensioned, return truck to service	Brown And Hurley
03/06/2025	2,563,745 kms	A - A S-14699 Carry out A service as per service checklist	
20/05/2025	2,557,283 kms	B - B S-14771 Carried out B service as per service checklist	
20/05/2025	2,557,283 kms	A - A S-14611 Carried out A service as per service checklist	
30/04/2025	2,551,695 kms	A - A S-14473 Carried out A service as per service checklist	
23/04/2025	2,549,030 kms	A - A S-14448 Carry out A service as per service checklist	
23/04/2025	2,549,030 kms	air leaks , tune up R-2545 Inspected and repaired air leaks ,replacing seat dump valve ,and repairing air leak at heater control on firewall ,also carried out engine tune up setting valves and injectors to spec ,steam cleaned and tested ok	workshop
16/04/2025		Puncture repair T-695 Repair puncture	Clarence Valley Tyres
15/04/2025	2,546,592 kms	A - A S-14409 Carry out A service as per service checklist	
08/04/2025	2,542,950 kms	A - A S-14373 Carry out A service as per service checklist	
25/03/2025	2,535,662 kms	A - A S-14244 Carry out A service as per service checklist	
18/03/2025	2,531,512 kms	B - B S-14210 Carry out B service as per service checklist changing engine oil and filters also carried out repairs on wiper arm assembly replacing arms joints and motor tested ok	
18/03/2025	2,531,512 kms	A - A S-14209 Carry out A service as per service checklist	
13/03/2025	2,529,126 kms	Engine check light R-2498 Replaced new sensor temperature	BROWN & HURLEY

Date	Reading / Units	Type / Repairer Notes	Repairer
13/03/2025	2,155,328 kms	micelin Multi T T-674 Supply and fit two new tyres and two new outside polished rims. Wheel balance and rotate eight tyres.	Clarence Valley Tyres
12/03/2025	2,529,036 kms	A - A S-14055 Carry out A service as per service checklist	Workshop
24/02/2025	2,522,316 kms	A - A S-14007 Carry out A service as per service checklist	Workshop
19/02/2025	2,520,229 kms	A - A S-14157 Carry out A service as per service checklist	
04/02/2025	2,511,583 kms	A - A S-13995 Carry out A service as per service checklist	
30/01/2025	2,510,066 kms	A - A S-13964 Carry out A service as per service checklist	
30/01/2025	2,510,066 kms	B - B S-13965 Carry out B service as per service checklist changing engine oil and filters steam clean chassis	
14/01/2025	2,501,383 kms	A - A S-13886 Carry out A service as per service checklist	
07/01/2025	2,498,138 kms	A - A S-13858 Carry out A service as per service checklist	
07/01/2025	2,498,138 kms	a/c fan blower, adjust clutch, diff oils , front diff out put seal, gearbox oil, reseal rear diff mount, service viesa cooler R-2448 Inspected and repaired diff oil leaks repairing and replacing front diff out put seal ,also drained rear diff and resealed mount seal ,filled with syn oil ,drained and replaced gearbox oil ,replacing diff and gearbox filters ,touuble shoot a/c fault finding a/c fan not working removed and replaced fan unit ,tested ok and tidy up wiring removed to gain access to fan ,greases and adjusted clutch ,serviced and repaired vieas cooler finding loose battery connection ,and water leaking down back of cab wall resealed and reassemble tested ok steam cleaned chassis	Workshop
02/01/2025	2,496,142 kms	A - A S-13836 Carry out A service as per service checklist	
02/01/2025	2,496,142 kms	C - C Service S-13849 Carry out C service as per service checklist also road test checking max road speed limiter set to 100 kms ok	
17/12/2024	2,491,506 kms	A - A S-13775 Carry out A service as per service checklist jacked up front end checking wheel bearings and king pins and adjusting r/h steer to spec and changing hub oils steam clean chassis ,also fitting new tablet cradle due to not charging	
03/12/2024	2,484,317 kms	A - A S-13668 Carry out A service as per service checklist	
03/12/2024	2,484,317 kms	B - B S-13669 Carry out B service as per service checklist changing engine oil and filters steam clean chassis	
03/12/2024	2,484,317 kms	alternator R-2413 Removed and replaced alternator and checked charge rate ok	Workshop
25/11/2024	2,480,053 kms	A - A S-13619 Carry out A service as per service checklist	
20/11/2024	2,477,807 kms	Engine brakes R-2394	Cummins

Date	Reading / Units	Type / Repairer Notes	Repairer
		Check Engine for Rattle in top end . Remove Cab mount bolts , induction piping to turbo Jackup cab for Access to Valve cover . Removed Valve cover , run engine found engine brake levers Levers 2and 6 Detents not Knocking in . Inspected Camshafts OK Camshafts meet reuse Guidelines . Removed Valve Rocker lever assemblies , inspected Engine brake detents , Excessivly worn , inspected engine brake levers , Installed Engine brake tune up kit due to worn Detents and spring compression rate Poor . Installed New rockershaft and Engine brake kit . Set running clearance of engine brake levers . Adjusted Valves Engine brakes and injectors . Connected Insite found Inactive faults for EGP sensor . Replaced Exhaust gas pressure sensor . Refit valve cover , lower cab .tensioned Cab mount bolts . Refit induction pipes . Degreased and roadtest to confirm repairs	
19/11/2024	2,477,803 kms	A - A S-13569 Carry out A service as per service checklist	
12/11/2024	2,473,961 kms	A - A S-13523 Carry out A service as per service checklist	
01/11/2024	2,469,429 kms	A - A S-13496 Carry out A service as per service checklist	
15/10/2024	2,463,078 kms	A - A S-13353 Carryout A service as per service checklist	
15/10/2024	2,463,078 kms	wheel bearing and seal R-2362 Inspected and repaired leaking wheel seal r/h front steer ,removed and replaced bearing and seal adjusted to spec	Workshop
10/10/2024		Tyre fit T-573 Fit tyre and wheel balance	Clarence Valley Tyres
08/10/2024	2,459,700 kms	B - B S-13307 Carry out B service as per service checklist changing engine oil and filters steam clean chassis	
08/10/2024	2,459,700 kms	A - A S-13306 Carryout A service as per service checklist	
01/10/2024	2,455,798 kms	A - A S-13280 Carry out A service as per service checklist also removed and replaced bonnet mount locator steam cleaned chassis	
25/09/2024	2,452,898 kms	A - A S-13245 Carry out A service as per service checklist	
04/09/2024	2,441,395 kms	A - A S-13056 Carry out A service as per service checklist	
04/09/2024		aircon R-2306 Check air con, pressure test, locate leaking hose, make and fit new hose, supply and fit drier and regas	JUSTIN BAILEY
29/08/2024	2,439,309 kms	A - A S-13030 Carry out A service as per service checklist	
22/08/2024	2,432,929 kms 14,225 hrs	aircon repairs R-2300 Justin Bailey inspected and repaired a/c fault	JUSTIN BAILEY
22/08/2024	2,437,087 kms	B - B S-12992 Carry out B service as per service checklist changing engine oil and filters steam clean chassis	
20/08/2024	2,435,772 kms	A - A S-12991 Carry out A service as per service checklist	
19/07/2024	2,422,174 kms 13,994 hrs	tail lights R-2243 Inspected and repaired l/h rear tail light faults ,removing and replacing tail light bulbs and repairing wiring for blinker assemble tested ok	Workshop

Date	Reading / Units	Type / Repairer Notes	Repairer
16/07/2024	2,427,938 kms	A - A S-12804 Carry out A service as per service checklist	
27/06/2024		steering shaft unis R-2221 Inspect vehicle for steering faults, found sized steering shaft unis, removed steering column, replaced unis, reassembled and refit shaft, road tested and realigned steering wheel.	Hughes Heavy Vehicle Maintenance
27/05/2024	2,418,811 kms	A - A S-12574 Carry out A service as per service checklist	
21/05/2024	2,418,799 kms	B - B S-12535 Carry out B service as per service checklist changing engine oil and filters steam clean chassis	
21/05/2024	2,418,799 kms	uni joints R-2186 Removed and replace main drive shaft uni joints and centre bearing ,also removed and replac4ed jackshaft uni joints test run ok	Workshop
21/05/2024	2,418,799 kms	A - A S-12534 Carry out A service as per service checklist	
19/04/2024	2,415,394 kms	A - A S-12276 Carry out A service as per service checklist	
19/04/2024	2,415,399 kms	A - A S-12312 Carry out A service as per service checklist	
10/04/2024	2,410,895 kms	clearance light mirror R-2172 Inspected and repaired drivers side mirror lights not working removed and replaced globs tested ok	Workshop
28/03/2024	2,405,088 kms	A - A S-12227 Carry out A service as per service checklist	
26/03/2024	2,403,218 kms	A - A S-12219 Carry out A service as per service checklist	
12/03/2024	2,396,082 kms	A - A S-12103 Carry out A service as per service checklist also removed and replaced rear engine mounts cleaned and tested ok	
05/03/2024	2,393,674 kms	B - B S-12004 Carry out B service as per service checklist changing engine oil and filters	
05/03/2024	2,393,674 kms	brake linings R-2117 Inspected and repaired low brake linings ,removed and replaced brake linings and run on r/h front steer adjusted to spec	Workshop
05/03/2024	2,393,674 kms	A - A S-12003 Carry out A service as per service checklist	
29/02/2024	2,391,054 kms	A - A S-11995 Carry out A service as per service checklist	
29/02/2024	2,391,054 kms	cab airbags R-2100 Trouble shoot air leak finding rear cab airbags failed removed and replaced 2 x airbags tested ok	Workshop
21/02/2024		puncture T-443 Puncture repair	Carroll Tyres
18/02/2024	2,382,909 kms	guage light R-2159 Inspected and repaired gauge light removed and replaced glob tested ok	Workshop
12/02/2024	2,379,668 kms	A - A S-11933 Carry out A service as per service checklist	

Date	Reading / Units	Type / Repairer Notes	Repairer
07/02/2024	2,377,100 kms	A - A S-11868 Carry out A service as per service checklist	
01/02/2024		BFGoodrich 295/80R T-425 Supply and fit two new tyres and wheel balance	Clarence Valley Tyres
01/02/2024	2,373,742 kms	parker light R-2105 Inspected and repaired parker light fault as required replacing glob	Workshop
26/01/2024	2,368,841 kms	air leak R-2088 Inspected and repaired air leak at front when putting foot on brake ,diagnose faulty front steer dump valve and l/h steer brake booster /24	Workshop
24/01/2024	2,371,121 kms	front tyres R-2084 Truck sent to CVT old steer tyres removed and replaced	Workshop
24/01/2024	371,121 kms	A - A S-11815 Carry out A service as per service checklist	
17/01/2024	2,365,298 kms	B - B S-11770 Carry out B service as per service checklist changing engine oil and filters ,steam clean chassis	
17/01/2024	2,365,298 kms	A - A S-11769 Carry out A service as per service checklist	
03/01/2024	2,356,373 kms	A - A S-11722 Carry out A service as per service checklist also changed out l/h front diff torque rod bushes and repaired air leaks at fire wall cleaned and tested ok	
03/01/2024	2,347,000 kms	drive tyres R-2043 Truck sent to CVT new drive tyres fitted to truck	Workshop
03/01/2024		BF Goodrich 275/70R T-411 Supply and fit eight tyres and dispose of one tyre	Clarence Valley Tyres
28/12/2023	2,356,373 kms	C - C Service S-11977 Carry out C service as per service checklist also checking max road speed limiter set to 100kms set ok	
28/12/2023	2,356,373 kms	A - A S-11699 Carry out A service as per service checklist	
07/12/2023	2,342,857 kms	guage globs R-2024 Removed and replaced blown globs as required in dash	Workshop
07/12/2023	2,334,261 kms	windscreen washers R-2023 Inspected and repaired windscreen washers not working finding pump and electrical stork faulty ,remove and replaced pump and stork tested ok	Workshop
07/12/2023	2,345,043 kms	A - A S-11560 Carry out A service as per service checklist	
01/12/2023	2,343,027 kms	A - A S-11531 Carry out A service as per service checklist	
01/12/2023	2,343,027 kms	B - B S-11532 Carry out B service as per service checklist changing engine oil and filters and steam clean chassis	
08/11/2023	2,330,617 kms	A - A S-11446 Carry out A service as per service checklist	
17/10/2023	2,322,346 kms 12,618 hrs	tail light fault R-1986	Workshop

Date	Reading / Units	Type / Repairer Notes	Repairer
		Inspected and repaired tail light fault finding blown glob removed and replaced l/h stop tail glob tested ok	
17/10/2023	2,322,455 kms	A - A S-11317 Carry out A service as per service checklist	
11/10/2023	2,321,391 kms	B - B S-11291 Carry out B service as per service checklist changing engine oil and filters and steam clean chassis	
11/10/2023	2,321,391 kms	A - A S-11290 Carry out A service as per service checklist	
14/09/2023	2,310,380 kms	wheel bearings R-1950 Inspected and repaired front wheel bearings ,jacked up front end checking finding l/h front steer notchy disassembled and inspected finding bearing failure ,striped and replaced bearings adjusted to spec	Workshop
14/09/2023	2,310,380 kms	A - A S-11018 Carry out A service as per service checklist	
07/09/2023	2,306,117 kms	A - A S-11016 Carry out A service as per service checklist	
31/08/2023	2,302,882 kms	A - A S-10956 Carry out A service as per service checklist also repaired alternator wiring and exhaust leak to egr cooler and steam clean chassis	
16/08/2023		Tyre fit T-353 Fit and wheel balance one tyre	Clarence Valley Tyres
15/08/2023	2,293,346 kms	B - B S-10881 carry out B service as per service checklist changing engine oil and filters also repairing air leak at treddle valve ,and changing diffs and gearbox oils ,cleaned and tested	
15/08/2023	2,293,346 kms	A - A S-10880 Carry out A service as per service checklist	
04/08/2023		puncture T-344 Repair puncture	Clarence Valley Tyres
19/06/2023	2,262,754 kms	A - A S-10621 Carry out A service as per service checklist	
08/06/2023	2,258,390 kms	A - A S-10523 Carry out A service as per service checklist	
02/06/2023	2,254,688 kms	A - A S-10505 Carry out A service as per service checklist	
02/06/2023	2,279,688 kms	B - B S-10506 Carry out B service as per service checklist changing engine oil and filters also changing engine air cleaner	
23/05/2023	2,248,246 kms	A - A S-10488 Carry out A service as per service checklist	
09/05/2023	2,243,001 kms	Radiator recore, Reseal front diff R-1843 Removed and reinstalled radiator re-cord by Western suburbs radiator service also resealed front diff cleaned and test run ok	Workshop
09/05/2023	2,243,001 kms	A - A S-10453 Carry out A service as per service checklist	
19/04/2023	2,239,008 kms	A - A S-10373 Carry out A service as per service checklist	

Date	Reading / Units	Type / Repairer Notes	Repairer
19/04/2023	2,239,008 kms	batteries, shock rubbers , starter motor R-1858 Inspected and repaired noisy and slow starting dianose faulty batteries and noisy starter ,removed and replaced starter ,and batteries tested ok	Workshop
29/03/2023	2,230,374 kms	A - A S-10234 Carry out A service as per service checklist	
24/03/2023	2,229,086 kms	A - A S-10417 Carry out A service as per service checklist	
24/03/2023	2,229,086 kms	B - B S-10418 Carry out B service as per service checklist changing engine oil and filters	
20/03/2023	2,226,018 kms	A - A S-10197 Carry out A service as per service checklist	
09/03/2023	2,222,375 kms	A - A S-10189 Carry out A service as per service checklist	
02/03/2023		Regas air con R-1821 Make and fit hose, supply and fit drier and TX valve, regas system	JUSTIN BAILEY
01/03/2023	2,218,660 kms	A - A S-10173 Carry out A service as per service checklist	
23/02/2023	1,214,086 kms 67 hrs	ENGINE REBUILD R-1816 Carryout Combustion Gas check , Combustion Gas Present . R@R Radiator , coolant Contaminated with Combustion Gases will need replacement . Stripped Engine , measured Counter bores , Liners need to be Removed and Machined Block .Front Housing removed Due to Oil leak . Stripped piston and liner assemblies from Engine . Carryout Counterbore Cut to Suit 20Thou service shims . Reassembled Front gearhousing with New Bolts Gaskets and seals . Replaced Main bearings . Fit APR Liners with 20thou Service shims . Installed Piston / rod assemblies , replaced Big end bearings . Check Valve recession on old cylinder head . Replaced Cylinder head .with Recon unit. Refit Camshaft and carryout Base timing of engine. Replaced Thermostat and seal due to Seal picking-up thermostat. Replaced Block header o'ring . Reassemble Top end of engine Replace Injector Orings and reinstalled . Set running clearance of engine brakes . Carryout valve and injector Adjustment. Replaced Engine brake harness . and new style mounting Bolt and nut . Replaced Heater taps , Control tap leaking on firewall customer to repair . Reassemble Manifold and turbo.VGT actuator OK for reuse . Refit Induction piping ,EGR piping ECM . cooling plate IFSM after cleaning and installed . Cleaned Boost pressure sensor and EGP sensor , inspected EGR cooler and Valve for reuse OK Replaced Furl pro filter , secondary filter .Fuel cap and collar . Repaired Oil cooler mounting pads for transmission cooler . Removed Siezed Lower mounts from Radiator . Flushed Radiator , external and internal . Fit Radiator with new mounting hardware . Customer kitted horton , refit and Accessory mounts and idlers and tensioner and belts , replaced Accessory belt . Replaced All coolant hoses , heater hoses . Replaced Coolant and coolant filter . Replaced Boost hoses and required Clamps . Replaced Oil pressure switches and Gauge sender . Replaced Coolant level sensor . Replace Pyro sender . Replaced Oil filter and primed Lube system . Refit INduction and air cleaner and boost pipes . Lower Cab and refit Cab skirts . Degreased and roadtest . OK Ac regased , reconnected all hoses and brackets . Paint engine , check over and return to depot .	Cummins
23/02/2023	1,214,086 kms	Cooler leaking R-1815 14/02/23 Truck arrived at branch at 16:00 inspected Connected insite , low coolant level faults , FC 1896, 1242 throttle pedal . Removed Cab fender and climb into rear of engine removed EGR cooler connection , Soot and coolant in rear pipe . Removed EGR connection found debri blocking valve from failed EGR cooler , Removed Inlet connection and DP piping mixer Inspected front of EGR cooler , Cracked in front of Cooler cores , due to prevouis engine overheat from low coolant , Drained Coolant approx 8ltrs of coolant loss . Intermitted connection on throttle pedal wiring . 15/02/23 Removed VGT turbo and inspected for reuse . OK Removed EGR cooler , Egr valve . removed EGR cross over pipe , Cleaned crossover pipe for use . attempt to clean EGR Valve unable to Clean , Valve sized Mechanical . Replaced Crossover pipe and egr valve . Clean mixer pipes, DP tubes and sensor , cleaned out Engine inlet pipe . Refit to engine . Replaced EGR cooler and install kit . Refit Turbo and exhaust manifold , no signs of coolant coming from engine cylinders , or head . Cleaned EGP sensor Tube. Refit boost and induction piping . Rewired Throttle Pedal , completely from Pedal to ECM . Filled coolant , top up with 2x 5l containers . Reset Inactive faults . Degreased , road test to confirm repairs . Check over , Reset road relay	Cummins
16/02/2023	2,214,295 kms	A - A S-10038 Carry out A service as per service checklist also removed and replaced heater control valve fire wall	
10/02/2023	2,213,113 kms	A - A S-10032	

Date	Reading / Units	Type / Repairer Notes	Repairer
		Carry out A service as per service checklist also rebuild horton fan assembly ,F35008SD,Cummins Grafton rebuild due to pressurisation ,also replaced egr cooler and valve	
19/01/2023	2,210,171 kms	A - A S-9864	
		Carry out A service as per service checklist	
19/01/2023	2,210,171 kms	B - B S-9865	
		Carry out B service as per service checklist changing engine oil and filters also changed out engine air cleaner	
12/01/2023	2,207,023 kms	A - A S-9823	
		Carry out A service as per service checklist	
20/12/2022	2,199,937 kms	A - A S-9739	
		Carry out A service as per service checklist	
20/12/2022	2,199,937 kms	leaking wheel seal R-1792	Workshop
		Inspected and repaired leaking wheel seal ,removing and replacing r/h rear drive axle ,disassemble cleaned parts ,replacing bearings ,seal brakes and drum , reassemble to spec test run ok	
02/12/2022	2,192,765 kms	B - B S-9597	
		Carry out B service as per service checklist changing engine oil and filters and steam clean chassis	
02/12/2022	2,192,765 kms	C - C Service S-10082	
		Carry out C service as per service checklist	
02/12/2022	2,192,765 kms	A - A S-9596	
		Carry out A service as per service checklist	
14/11/2022	2,184,493 kms	A - A S-9527	
		Carry out A service as per service checklist	
10/11/2022	2,183,219 kms	A - A S-9490	
		Carry out A service as per service checklist	
20/10/2022	2,174,278 kms	A - A S-9412	
		Carry out A service as per service checklist	
12/10/2022	2,169,980 kms	A - A S-9360	
		Carry out A service as per service checklist	
29/09/2022	2,164,058 kms	B - B S-9261	
		Carry out B service as per service checklist changing engine oil and filters also steam clean chassis	
29/09/2022	2,164,058 kms	A - A S-9260	
		Carry out A service as per service checklist	
13/09/2022	2,156,506 kms	A - A S-9175	
		Carry out A service as per service checklist	
13/09/2022	2,156,506 kms	tail light R-1741	Workshop
		Inspected and repaired tail light fault removed and replaced bulb	
24/08/2022	2,152,366 kms	A - A S-8954	
		Carry out A service as per service checklist also adjust clutch and grease bearing and steam clean chassis	
17/08/2022	2,149,363 kms	A - A S-8934	
		Carry out A service as per service checklist	
09/08/2022	2,144,587 kms	Oil pressure R-1690	Cummins
		Replace oil pressure sensor	
09/08/2022	2,147,324 kms	A - A S-8856	

Date	Reading / Units	Type / Repairer Notes	Repairer
		Carry out A service as per service checklist	
02/08/2022	2,146,123 kms	A - A S-8823	
		Carry out A service as per service checklist	
22/07/2022	2,144,595 kms	B - B S-8787	
		Carry out B service as per service checklist changing engine oil and filters ,also change out air cleaner and steam clean chassis	
22/07/2022	2,144,595 kms	A - A S-8786	
		Carry out A service as per service checklist	
12/07/2022	2,143,118 kms	A - A S-8724	
		Cary out A service as per service checklist also adjusted clutch and steam cleaned chassis	
04/07/2022	2,142,344 kms	A - A S-8698	
		Cary out A service as per service checklist	
04/07/2022	2,142,344 kms	A - A S-8659	
		Cary out A service as per service checklist	
23/06/2022	2,137,065 kms	A - A S-8649	
		Carry out A service as per service checklist	
14/06/2022	2,135,780 kms	A - A S-8605	
		Carry out A service as per service checklist	
30/05/2022	2,130,670 kms	A - A S-8532	
		Carry out A service as per service checklist	
16/05/2022	2,129,110 kms	A - A S-8474	
		Carry out A service as per service checklist	
02/05/2022	2,126,684 kms	A - A S-8407	
		Carry out A service as per service checklist	
22/04/2022	2,123,175 kms	B - B S-8342	
		Carry out B service as per service checklist changing engine oil and filters also grease clutch and tighten up pitman arm steam clean chassis	
20/04/2022	2,121,569 kms	A - A S-8341	
		Carry out A service as per service checklist	
06/04/2022	103,836 kms	Pressure sensor R-1617	Cummins Grafton
		Replaced sensor, pressure temp.	
06/04/2022	1,056,612 kms	R & R turbo R-1615	Cummins
		Drive to gundagai, inspect truck for engine noise Fund turbo compressor wheel to be hitting on housing & seal between turbo & actuator to have failed. Remove intake piping, heat shield & steering shaft, Drain coolant, R&R turbo, Calibrate actuator, refill coolant, refit intake piping, heat shield & steering shaft. Fit new air filter, tart & run engine - all ok, Return travel & fill out paperwork	
05/04/2022	2,117,872 kms	high beam inserts R-1613	Workshop
		Inspected and replaced high beam inserts in bonnet due to reflector missing tested ok	
05/04/2022	2,117,872 kms	A - A S-8267	
		Carry out A service as per service checklist	
16/03/2022	2,106,239 kms	A - A S-8206	
		Carry out A service as per service checklist	
07/03/2022	2,100,833 kms	A - A S-8112	

Date	Reading / Units	Type / Repairer Notes	Repairer
		Carry out A service as per service checklist	
28/02/2022	2,100,706 kms	B - B S-8078	
		Carry out B service as per service checklist changing engine oil and filters also repairing turntable handle bent ,steam clean chassis	
28/02/2022	2,100,706 kms	A - A S-8077	
		Carry out A service as per service checklist	
22/02/2022	2,097,668 kms	wipers /washers R-1583	Workshop
		Inspected and repaired wiper washers finding split tube repaired and tested ok also replaced wiper blades and repaired side mirror clearance lights	
22/02/2022	2,097,668 kms	A - A S-8018	
		Carry out A service as per service checklist	
11/02/2022	2,091,996 kms	A - A S-7960	
		Carry out A service as per service checklist	
28/01/2022	2,083,358 kms	A - A S-7877	
		Carry out A service as per service checklist	
18/01/2022	2,077,037 kms	B - B S-7850	
		Carry out B service as per service checklist changing engine oil and filters also steam clean chassis	
18/01/2022	2,077,037 kms	A - A S-7849	
		Carry out A service as per service checklist also replaced a/c belt -6pk1625	
29/12/2021	2,071,633 kms	batteries, steer wheel seal R-1562	Workshop
		Inspected and repaired hard starting ,dianose faulty batteries removed and replaced 4 x batteries , leaking l/h front steer wheel seal dissassemble cleaned parts finding bearing failure ,reassembled replacing bearings and seal and adjusting to spec	
29/12/2021	2,071,633 kms	C - C Service S-8143	
		Carry out C service as per service checklist also checking max road speed limiter ok	
29/12/2021	2,071,633 kms	A - A S-7764	
		Carry out A service as per service checklist	
13/12/2021	2,065,507 kms	A - A S-7698	
		Carry out A service as per service checklist topped up oil 5 ltr	
29/11/2021	2,057,618 kms	A - A S-7640	
		Carry out A service as per service checklist	
23/11/2021	2,054,180 kms	B - B S-7612	
		Carry out B service as per service checklist changing engine oil and filters also repairing front diff oil leak output seal ,and changing gearbox and front diff oil filters and changing air compressor signal lines cleaned and tested	
12/11/2021	2,049,213 kms	A - A S-7574	
		Carry out A service as per service checklist also steam clean chassis and adjust and grease clutch	
04/11/2021	2,043,968 kms	airbags , shocko R-1523	Workshop
		Inspected and repaired old perished air bags ,removing and replacing 4 x front diff airbags ,also replacing l/h front drive shocko	
04/11/2021	2,043,968 kms	A - A S-7513	
		Carry out A service as per service checklist	
27/10/2021	2,038,532 kms	A - A S-7471	
		Carry out A service as per service checklist also steam clean chassis	
12/10/2021	2,030,275 kms	B - B S-7390	

Date	Reading / Units	Type / Repairer Notes	Repairer
		Carry out B service as per service checklist changing engine oil and filters	
12/10/2021	2,030,275 kms	A - A S-7389	
		Carry out A service as per service checklist also steam clean chassis	
22/09/2021	2,019,239 kms	A - A S-7336	
		Carry out A service as per service checklist	
09/09/2021		a/c repairs R-1478	Briskair
		CARRY OUT REPAIR AND SERVICE ON VIESA LOCATE & REPLACE FAULTY FAN MOTOR LOCATE & REPLACE FAULTY FLOAT SENSOR LOCATE AND REPLACE FAULTY REAR DOOR REMOVE & CLEAN OUT EVAPORATOR TRAY SUPPLY & INSTALL 1 X NEW EVAPORATOR FLUSH OUT ALL LIQUID LINES FLUSH OUT WATER TANK FILL WITH FRESH WATER AND ADD VIESA ANTI BACTERIAL RUN SYSTEM CHECK OPERATION OK	
09/09/2021	2,010,948 kms	A - A S-7267	
		Carry out A service as per service checklist also steam clean chassis	
24/08/2021	2,001,096 kms	A - A S-7218	
		Carry out A service as per service checklist	
20/08/2021	1,999,582 kms	B - B S-7202	
		Carry out B service as per service checklist changing engine oil and filters also steam clean chassis	
11/08/2021	1,994,964 kms	A - A S-7142	
		Carry out A service as per service checklist	
03/08/2021	1,989,354 kms	airbags, starter motor R-1445	Workshop
		Inspected and repaired starting fault dianose faulty starter ,removing and replacing tested ok also remove and replace 4 x air bags rear axle	
26/07/2021	1,984,134 kms	A - A S-7089	
		Carry out A service as per service checklist	
26/07/2021	1,984,134 kms	turntable jaw rekit R-1438	Workshop
		Inspected and repaired turntable ,removed turntable stripped cleaned and re kitted replacing jaw kit and slide setting to spec ,refit to truck and adjusted to spec ,also replacing fuel line from engine to cooler	
12/07/2021	1,977,962 kms	A - A S-7037	
		Carry out A service as per service checklist	
30/06/2021	1,974,711 kms	B - B S-6980	
		Carry out B service as per service checklist changing engine oil and filters ,steam clean chassis	
29/06/2021	1,974,433 kms	A - A S-6978	
		Carry out A service as per service checklist also c/o 2 x cac hoses on turbo side	
23/06/2021	1,973,848 kms	A - A S-6940	
		Carry out A service as per service checklist also adjusting clutch	
08/06/2021	1,964,711 kms	A - A S-6877	
		Carry out A service as per service checklist	
19/05/2021	1,953,423 kms	B - B S-6811	
		Carry out B service as per service checklist changing engine oil and filters steam clean chassis	
14/05/2021	1,950,684 kms	A - A S-6733	
		Carry out A service as per service checklist	
14/05/2021	1,950,684 kms	A - A S-6803	
		Carry out A service as per service checklist	
06/05/2021	943,774 kms	Throttle potentiometer R-1363	Cummins Grafton

Date	Reading / Units	Type / Repairer Notes	Repairer
		Connected insite found one count of Throttle pedal data erratic. 3 counts of Battery fault FC1117 . Inspected Battery connection OK. Check starter connection Ok. Check Alternator connection, found exciter wire broken and shorting out on alternator Body . Repaired wiring and reconnected . Inspected throttle wiring from Ecm to Pedal . Replaced throttle pot . Road test , no faults	
05/05/2021	942,663 kms	Turbo actuator R-1362	Cummins
		Load parts and tooling then travel to site at Yass Service Centre. Arrive on site, complete paperwork, connect to ECM and read faults. Found fault code 2636 active (red stop engine light), check VGT actuator plug and harness = no damage found, check cylinder block and starter earth stud = good connection, check resistance of actuator J1939 datalink = 120ohms = ok, check power supply to VGT actuator = 12.35v. check ECM connector = ok, check engine harness datalink = 122 ohms = ok, check wiring for shorts = no short circuits. Drain coolant and remove VGT actuator, found coolant leaking internally through actuator, install and calibrate new VGT actuator, all faults inactive, refill coolant and run to temp, clear all faults and return vehicle	
22/04/2021	1,939,699 kms	A - A S-6689	
		Carry out A service as per service checklist	
22/04/2021	1,939,699 kms	input seal front diff, steering king pin R-1365	workshop
		Inspected and repaired excessive movement ,jacked up front end checking for movement finding r/h front steer king pin worn ,disassembled inspected and replaced king pin assembly setting and shimming to spec also replacing front diff input seal	
09/04/2021	1,932,371 kms	A - A S-6625	
		Carry out A service as per service checklist	
25/03/2021	1,925,352 kms	A - A S-6570	
		Carry out A service as per service checklist	
25/03/2021	1,925,352 kms	wheel seal R-1332	Workshop
		Inspected and repaired leaking r/h rear axle wheel seal ,disassembled cleaned parts and reassembled replacing ,bearings brakes and seal adjusting to spec also replacing 1 x shocko	
25/03/2021	1,925,352 kms	B - B S-6571	
		Carry out B service as per service checklist changing engine oil and filters also changing various torque rod bushes	
11/03/2021	911,676 kms	Replace rear main seal R-1317	Cummins Grafton
		Removed rear main seal and replaced with new seal. Fit flywheel and tension.	
08/03/2021	1,915,279 kms	A - A S-6521	
		Carry out A service as per service checklist	
24/02/2021	1,911,676 kms	cab air bags, clutch R-1303	workshop
		Removed and replaced clutch ,and gearbox install kit ,cummins grafton removed and replace rear seal and refitted flywheel also replacing rear cab air bags	
24/02/2021	1,911,676 kms	A - A S-6449	
		Carry out A service as per service checklist	
18/02/2021	1,908,711 kms	a/c fault, fan belt , fan tensioner R-1301	workshop
		Inspected and repair a/c fault Justin Bailey repaired a/c replacing compressor also replacing fan belt and tesioner	
09/02/2021	1,903,623 kms	A - A S-6402	
		Carry out A service as per service checklist	
06/02/2021	1,902,804 kms	B - B S-6378	
		Carry out B service as per service checklist changing engine oil and filters also changing air cleaner	
30/01/2021	1,898,647 kms	A - A S-6329	
		Carry out A service as per service checklist also carry out clutch adjustment and replacing exhaust flex under cab	
13/01/2021	1,890,194 kms	A - A S-6253	
		Carry out A service as per service checklist	
07/01/2021	884,277 kms	Sensor pressure R-1278	Cummins

Date	Reading / Units	Type / Repairer Notes	Repairer
		Connected insite check fault codes , high counts of 2764. Check EGP sensor circuit response OK Check EGP sensor supply tube OK Replaced Exhaust gas pressure sensor . Check DP tubes for blockage - OK Check boost pressure sensor OK Roadtest to confirm Repairs ,OK No active faults or derate . Reset inactive faults . Returned to service	
23/12/2020	1,884,271 kms	C - C Service S-6351 Carry out C service as per service checklist changing gearbox and diffs oils refilling with full syn oil also checking roas speed limit ok	
17/12/2020	1,881,714 kms	A - A S-6204 Carry out A service as per service checklist	
10/12/2020		bunk cooler R-1264 Truck sent to Briskair Brisbane inspected and serviced for repair	Briskair
10/12/2020	1,877,803 kms	A - A S-6177 Carry out B service as per service checklist changing engine oil and filters steam clean chassis	
03/12/2020		wiring fault R-1267 Inspected and repaired r/h side bonnet indicator	workshop
30/11/2020	1,871,378 kms	wheel seal R-1254 Inspected and repaired leaking wheel seal ,replacing l/h rear drive axle seal ,disassembled inspected and cleaned ,reassembled to spec	workshop
30/11/2020	1,871,378 kms	A - A S-6152 Carry out A service as per service checklist	
24/11/2020	1,867,975 kms	A - A S-6108 Carry out A service as per service checklist	
02/11/2020	1,854,765 kms	A - A S-6049 Carry out A service as per service checklist also steam clean chassis	
27/10/2020	1,876,729 kms	B - B S-6015 Carry out B service as per service checklist changing engine oil and filters also changing out a/c belt 6pk1625	
22/10/2020	1,849,507 kms	A - A S-5987 Carry out A service as per service checklist	
22/10/2020	1,849,507 kms	shocko R-1208 Removed and replaced leaking shock ,replacing r/h rear shock	Workshop
09/10/2020	1,843,061 kms	A - A S-5940 Carry out A service as per service checklist	
24/09/2020	1,834,448 kms	COOLANT LEVEL FAULT, PYRO FAULT R-1189 Inspected and trouble shoot coolant level fault ,replacing prob and wiring harness to modual ,also inspecting pyro not working fault replacing prob with second hand unit also repairing wiring at connection pint tested ok	Workshop
23/09/2020	1,834,448 kms	A - A S-5882 Carry out A service as per service checklist	
09/09/2020	1,827,167 kms	B - B S-5804 Carry out B service as per service checklist changing engine oil and filters also replace air cleaner	
09/09/2020	1,827,167 kms	A - A S-5803 Carry out A service as per service checklist	
28/08/2020	1,822,340 kms	A - A S-5753 Carry out A service as per service checklist	
10/08/2020	1,817,363 kms	A - A S-5707	

Date	Reading / Units	Type / Repairer Notes	Repairer
		Carry out A service as per service checklist	
22/07/2020	1,813,771 kms	A - A S-5606	
		Carry out A service as per service checklist	
03/07/2020	1,802,739 kms	B - B S-5531	
		Carry out B service as per service checklist changing engine oil and filters also steam clean chassis	
29/06/2020	1,799,512 kms	A - A S-5530	
		Carry out A service as per service checklist	
16/06/2020	1,791,376 kms	A - A S-5482	
		Carry out A service as per service checklist	
03/06/2020	1,784,292 kms	A - A S-5431	
		Carry out A service as per service as per service checklist	
19/05/2020	1,776,215 kms	A - A S-5378	
		Carry out A service as per service checklist	
19/05/2020	1,776,215 kms	coolant leak , diff seal , wheel seal R-1098	Workshop
		Inspect and repair leaking seals replacing front diff output seal and replacing front diff oil ,also replacing l/h front steer wheel seal and adjusting to spec ,also repairing coolant leak side of block under turbo tested ok	
19/05/2020	1,776,215 kms	B - B S-5379	
		Carry out B service as per service checklist changing engine oil and filters	
04/05/2020	1,766,929 kms	A - A S-5307	
		Carry out A service as per service sheet checklist	
04/05/2020	1,766,929 kms	leaking wheel seal R-1086	Workshop
		Inspect and repaired leaking wheel seal l/h front drive axle ,dissassemble clean parts ,replacing wheel seal and adjusting to spec	
29/04/2020	1,765,001 kms	leaking wheel seal R-1076	Workshop
		Inspected and repaired leaking wheel seal ,disassemble r/h front steer wheel seal clean parts and replace seal and bearings adjusting to spec	
29/04/2020	1,765,001 kms	A - A S-5268	
		Carry out A service as per service sheet checklist	
09/04/2020	1,755,270 kms	A - A S-5213	
		Carry out A service as per service checklist	
27/03/2020	1,748,423 kms	B - B S-5168	
		Carry out B service as per service checklist changing engine oil and filters	
24/03/2020	1,746,229 kms	A - A S-5167	
		Carry out A service as per service checklist	
11/03/2020	1,739,795 kms	A - A S-5095	
		Carry out A service as per service checklist	
25/02/2020	1,729,859 kms	A - A S-5024	
		Carry out A service as per service checklist also repairing coolant leak	
12/02/2020	1,724,407 kms	B - B S-4980	
		Carry out B service as per service checklist changing engine oil and filters	
12/02/2020	1,724,407 kms	A - A S-4979	
		Carry out A service as per service checklist	
28/01/2020	1,715,302 kms	A - A S-4937	

Date	Reading / Units	Type / Repairer Notes	Repairer
		Carry out A service as per service checklist	
18/01/2020	1,712,693 kms	A - A S-4893	
		Carry out A service as per service checklist topped up coolant and added 2 ltr oil cummins	
06/01/2020	1,707,969 kms	C - C Service S-5126	
		Carry out C service as per service checklist changing gearbox and diffs oils ,also checking road speed ok	
06/01/2020	1,707,969 kms	A - A S-4861	
		Carry out A service as per service checklist	
17/12/2019	1,702,462 kms	A - A S-4819	
		Carry out A service as per service checklist also repairing wiring to alternator	
17/12/2019	1,702,462 kms	light bulb R-979	Workshop
		Inspected and repaired blown light bulb r/h front H4	
07/12/2019	1,697,849 kms	A - A S-4757	
		Carry out A service as per service sheet checklist	
07/12/2019	1,697,849 kms	B - B S-4758	
		Carry out B service as per service checklist changing engine oil and filters	
18/11/2019	1,685,684 kms	A - A S-4711	
		Carry out A service as per service sheet checklist	
18/11/2019	1,685,684 kms	batteries R-967	Workshop
		Inspect and repair hard to start dianose faulty batteries ,removed and replaced 4 x batteries supplied by battery barn	
14/11/2019	1,684,323 kms	king pin R-953	Workshop
		Jacked up inspected slight wear ,disassembled cleaned parts and re kitted r/h side king pin with ream less kit greased and tested ok	
04/11/2019	1,679,117 kms	A - A S-4663	
		Carry out A service as per service checklist also repairing clutch linkage replacing lever	
26/10/2019	1,699,556 kms	B - B S-4608	
		Carry out B service as per service checklist changing engine oil and filters	
22/10/2019	1,671,727 kms	A - A S-4605	
		Carry out A service as per service checklist	
09/10/2019	1,665,537 kms	A - A S-4555	
		Carry out A service as per service checklist	
26/09/2019	1,658,427 kms	A - A S-4516	
		Carry out A service as per service checklist	
24/09/2019		Repair and service on viesia R-919	Briskair
		Carry out repair and service on Viesa. Locate and repair faulty wiring. Remove and clean evaporator tray. Supply and install a new evaporator tray. Flush out all liquid lines. Flush out water tank. Fill with fresh water and add anti bacterial.	
12/09/2019	1,649,960 kms	A - A S-4465	
		Carry out A service as per service checklist	
12/09/2019	1,649,960 kms	B - B S-4466	
		Carry out B service as per service checklist changing engine oil and filters also replacing cac clamp and hoses	
27/08/2019	1,640,557 kms	A - A S-4374	
		Carry out A service as per service checklist also replacing 1 x shock r/h rear axle	

Date	Reading / Units	Type / Repairer Notes	Repairer
17/08/2019	1,634,983 kms	A - A S-4332 Carry out A service as per service checklist 2 ltr oil added cummins	
05/08/2019	1,627,248 kms	B - B S-4288 Carry out B service as per service checklist changing engine oil and filters Justin Bailey regased A/C steamed cleaned	
31/07/2019	1,625,645 kms	A - A S-4287 Carry out A service as per service checklist also check and adjusted clutch and repaired various air leaks	
17/07/2019	1,619,092 kms	wippers R-866 Inspect and repair wipper faults finding excessive wear in arms remove wipper arm assembly strip down and rekit refit to truck test run ok	Workshop
17/07/2019	1,619,092 kms	A - A S-4240 Carry out A service as per service checklist	
06/07/2019	1,613,066 kms	A - A S-4201 Carry out A service as per service checklist	
17/06/2019	1,600,444 kms	air dryer, valve set R-843 Carry out V & I adjustment set to spec also rekitting air dryer	Workshop
17/06/2019	1,600,444 kms	A - A S-4155 Carry out A service as per service checklist	
17/06/2019	1,600,444 kms	wiring R-844 inspected and repaired wiring fault for jacob ,and a/c not working also repaired wiring to mirrors ,parts ordered for l/h mirror heater	JUSTIN BAILEY, Workshop
17/06/2019	1,600,444 kms	B - B S-4156 Carry out B service as per service checklist changing engine oil and filters	
08/06/2019	1,596,515 kms	A - A S-4099 Carry out A service as per service checklist	
21/05/2019	1,584,662 kms	A - A S-4054 Carry out A service as per service checklist also repairing wiring at starter signal wire	
07/05/2019	1,576,337 kms	A - A S-4003 Carry out A service as per service checklist	
04/05/2019	1,575,015 kms	B - B S-3997 Carry out B service as per service checklist changing engine oil and filters	
04/05/2019	1,575,015 kms	horton fan rekit R-812 Inspect and repair leaking horton ,removed striped cleaned and rekit refit to engine ,also replacing solenoid and hoses tested ok	Workshop
27/04/2019	1,571,082 kms	A - A S-3960 Carry out A service as per service check list	
27/04/2019	1,571,082 kms	Starter Motor R-808 Inspect and repair slow to start dianose faulty starter remove and replace starter ,starter supplied by Justin Bailey also replacing key switch ignition and bunk tool box locks and keys both sides	Workshop
16/04/2019	1,566,483 kms	a/c belt adjuster idler R-809 Inspect and repair a/c fault replacing belt ,idler and adjuster tested ok	Workshop
13/04/2019	1,565,660 kms	leaking wheel seal R-802 Inspected and repaired leaking l/h rear drive axle wheel seal ,disassemble cleaning parts reassemble replacing ,bearings ,seal,brakes ,drum and adjusting to spec	Workshop

Date	Reading / Units	Type / Repairer Notes	Repairer
13/04/2019	1,565,660 kms	A - A S-3902 Carry out A service as per service check list	
28/03/2019	1,555,838 kms	shocko, STEERING BOX, Torque Rod Bushes R-789 Inspect and repair l/h front torque rod bushes ,remove and replace 2 x bushes, replacing 1 x shocko r/h rear ,also replacing power steering box and pitman arm ,servicing steering fluid test run ok	Workshop
28/03/2019	1,555,838 kms	A - A S-3860 Carry out A service as per service check list	
16/03/2019	1,549,645 kms	A - A S-3809 Carry out A service as per service checklist	
16/03/2019	1,549,645 kms	B - B S-3810 Carry out B service as per service sheet changing engine oil and filters	
25/02/2019	1,537,385 kms	steer tyres R-752 Inspect and repair vibration in steer clearance valley tyres fitted 2 x new steer tyres	Workshop
25/02/2019	1,537,385 kms	clutch adjustment R-753 Inspect and repair adjusting clutch to spec	Workshop
18/02/2019	1,533,293 kms	clutch linkage R-741 Inspect and repair clutch rod ends replacing 2 x pivot bearings and 2 x rod ends test and adjusted clutch ok	Workshop
11/02/2019	1,530,628 kms	temp guage R-739 Inspect and repair faulty guage fault dianose guage remove and replace test run ok	Workshop
11/02/2019	1,530,628 kms	C - C Service S-3782 Carry out C & D service as per service checklist	
11/02/2019	1,530,628 kms	A - A S-3701 Carry out A service as per service checklist	
31/01/2019	1,529,900 kms	A - A S-3655 Carry out A service as per service checklist also repaired l/h mirror lights and removed rear lights cab	
31/01/2019	1,529,900 kms	B - B S-3656 Carry out B service as per service checklist changing engine oil and filters	
29/01/2019		tyres R-712 Tyre to be monited TYRE HAS BEEN CHANGED OUT	Workshop
29/01/2019	1,483,860 kms	Speed sensor R-717 Inspect for codes. nil relating to derate roas test. Monitor vehicle speed, eratic return fit test ecm no vss only 1500RPM. Fit test ECM no change in data. Rewire vss and road test ok inspect parameters ok return to service.	Cummins Grafton
29/01/2019		tyres R-709 Remove and replace 2 x tyres	Workshop
16/01/2019	1,517,961 kms	A - A S-3583 Carry out A service as per service check list	
02/01/2019	1,512,635 kms	A - A S-3549 Carry out A service as per service check list	
02/01/2019	1,512,635 kms	A - A S-3504 Carry out A service as per service check list	
02/01/2019	1,512,635 kms	air compressor lines, gearbox cooler lines R-686	Workshop

Date	Reading / Units	Type / Repairer Notes	Repairer
		Remove and replace leaking gearbox oil filter/cooler lines also replacing air compressor lines to dryer start and test run ok also repairing gearbox range change /slow clean out lines and lubricate valves tested ok also resealed front diff mounting refilled with oil and replacing out put seal test run ok	
06/12/2018	1,503,580 kms	A - A S-3458 Carry out A service as per service check list	
30/11/2018	1,499,795 kms	MUFFLER R-669 Inspect and repair noisy exhaust dianose loose baffle remove and replace exhaust muffler r/h side test run ok	Workshop
24/11/2018	1,496,212 kms	A - A S-3409 Carry out A service as per service check list	
24/11/2018	1,496,212 kms	B - B S-3410 Carry out B service as per service check list changing engine oil and filters	
05/11/2018	483,824 kms	A - A S-3358 Carry out A service as per service checklist	
05/11/2018	1,483,824 kms	leaking wheel seal R-645 Inspect and repair leaking wheel seal r/h front drive axle dissassemble clean parts replacing brake shoes ,drum and seal , reassemble adjusting to spec ,also replacing exhaust pipe elbow behing turbo and under truck	Workshop
23/10/2018	1,476,746 kms	A - A S-3304 Carry out A service as per service checklist also investigate l/h door faults dissassemble clean and lubricate locking mechanism tested ok	
09/10/2018	1,468,221 kms	steering shaft R-629 Inspect and repair excessive movement in steering shaft ,remove and replace bottom section of steering shaft to steering box ,grease up ,test run ok	Workshop
08/10/2018	467,372 kms	A - A S-3258 Carry out A service as per service checklist	
06/10/2018	1,467,371 kms	B - B S-3326 Carry out B service as per service check list changing engine oil and filters	
28/09/2018	1,463,350 kms	A - A S-3239 Carry out A service as per service check list	
28/09/2018	1,463,350 kms	a/c repairs R-625 Trouble shoot a/c fault dianose split evaportaor Justin Bailey carried out repair	Workshop
15/09/2018	454,795 kms	A - A S-3126 Carry out A service as per service checklist	
30/08/2018	1,423,675 kms	Oil consumption R-596 Replaced main bearings during oil consumption repair. replaced big end bearings. Replaced oil temp sensor. Replaced all radiator mounts.Replaced engine fan.Replaced engine oil and filter. Repaired wiring from Pyro sensor due to gauge. Replaced heater tap lower. Replaced oring in block heater position.	Cummins Grafton
28/08/2018	444,554 kms	A - A S-3087 Carry out A service as per service checklist	
24/08/2018	1,443,647 kms	B - B S-3056 Carry out B service as per service check list changing engine oil and filters	
24/08/2018	1,443,647 kms	range change R-597 Trouble shoot slow range change dianose low air supply and parts leaking air c/o range change gear nob in cab,air regulator valves and piston seal back of gearbox test run still slow but quicker run for a while testing	Workshop
20/08/2018		Wheel Balance T-275 Wheel balance steer.	CVT

Date	Reading / Units	Type / Repairer Notes	Repairer
18/08/2018	1,439,619 kms	Fitted new fridge slide R-593 Install draw fridge under sleeper	Workshop
18/08/2018	1,439,619 kms	D S-3184 Carry out D service as per service checklist	
18/08/2018	1,439,619 kms	A - A S-3043 Carry out A service as per service check list added 6 ltr oil cummins	
18/08/2018	1,439,619 kms	leaking wheel seal R-591 Inspect and repair leaking r/h front steer wheel seal disassemble clean parts resemble replacing seal only adjusted to spec	Workshop
03/08/2018	1,431,725 kms	A - A S-3001 Carry out A service as per service check list	
03/08/2018	1,431,725 kms	heater core R-578 Remove and replace heater core and heater control valve test run ok	Workshop
27/07/2018		Run out tyre T-267 Run out drive tyre fitted	CVT
21/07/2018	424,456 kms	A - A S-2950 Carry out A service as per service check list	
09/07/2018		puncture T-255 repair puncture	CVT
05/07/2018	1,405,570 kms	Recon turbo R-560 Gain access to remove turbo from engine. Inspect actuator to find seized/seizing in operation. clean out intake and replace air cleaner. Reassemble recon turbo and actuator back to truck and callibrate. Fill cooling system. Clear fault codes and road test.	Cummins Grafton
04/07/2018	1,407,335 kms	A - A S-2908 Carry out A service as per service sheet also replaced tacho and turbo prob	
23/06/2018	1,411,576 kms	A - A S-2861 Carry out A service as per service sheet 7 ltr oil added cummins	
07/06/2018	1,403,772 kms	A - A S-2820 Carry out A service as per service sheet 8 ltr oil added cummins oil	
07/06/2018	1,403,772 kms	air leak R-551 inspect and repair leaking air replacing yellow park brake valve in cab	Workshop
21/05/2018	1,392,822 kms	A - A S-2774 Carry out A service as per service sheet 6 ltr oil added	
15/05/2018	1,390,386 kms	engine oil R-555 4 ltr oil added cummins oil	
09/05/2018	1,387,136 kms	B - B S-2734 Carry out B service as per service sheet changing engine oil and filters	
09/05/2018	1,387,136 kms	A - A S-2733 Carry out A service as per service checklist	
26/04/2018	1,381,214 kms	A - A S-2676 Carry out A service as per service checklist 6 ltr oil added cummins	
18/04/2018	1,377,778 kms	ENGINE OIL R-554 Oil added 4 cummins oil	Workshop

Date	Reading / Units	Type / Repairer Notes	Repairer
14/04/2018	1,374,578 kms	A - A S-2636 Carry out A service as per service sheet 6 ltr oil added cummins	
29/03/2018	1,367,238 kms	A - A S-2602 Carry out A service as per service sheet 4 ltr oil added cummins	
22/03/2018	1,363,549 kms	BRAKE SLACK ADJUSTER R-499 Remove and replace l/h front steer brake slack adjuster adjust to spec	Workshop
22/03/2018	1,363,549 kms	EXHAUST FLEX R-497 Remove and replace exhaust flex at the back of engine pipe also replacing clamps/ also replacing input seal to front diff drain and refill front diff only	Workshop
22/03/2018	1,363,549 kms	B - B S-2542 Carry out B service as per service sheet changing engine oil and filters also changing air cleaner steam clean chassis	
19/03/2018	1,361,953 kms	A - A S-2856 Carry out A service as per service sheet 6 ltr oil added	
07/03/2018	1,355,472 kms	Starter Motor R-493 Trouble shoot hard starting finding faulty starter loose centre housing remove and replace starter test run ok starter supplied by justin bailey	Workshop
27/02/2018	351,417 kms	A - A S-2476 Carry out A service as per service checklist	
27/02/2018	1,351,417 kms	D S-2578 Carry out C&D services as per service sheet	
12/02/2018	1,344,209 kms	A - A S-2437 Carry out A service as service sheet	
09/02/2018	1,344,208 kms	Treddie Value R-484 Remove and replaced treddie valve	Workshop
29/01/2018	1,337,583 kms	A - A S-2388 Carry out A service as service sheet	
29/01/2018	1,337,583 kms	B - B S-2389 Carry out B service as per service sheet changing engine oil and filters	
19/01/2018	1,335,933 kms	A - A S-2320 Carry out A service as per service sheet	
02/01/2018	331,064 kms	Brake R-477 Remove and replace l/h front drive axle brake linings and drum reassemble and adjust to spec steam clean chassis	Workshop
02/01/2018	1,331,064 kms	A - A S-2295 Carry out A service as per service sheet	
09/12/2017	1,324,886 kms	A - A S-2254 Carry out A service as per service check list	
20/11/2017	1,314,187 kms	B - B S-2195 Carry out B service as per service sheet changing engine oil and filters	
20/11/2017	1,314,187 kms	A - A S-2194 Carry out A service as per service sheets	
09/11/2017	308,396 kms	A - A S-2145	

Date	Reading / Units	Type / Repairer Notes	Repairer
		Carry out A service as per service check list, 2.3 Cummins oil	
27/10/2017	1,301,886 kms	A - A S-2111	
		Carry out A service as per service check list	
14/10/2017	1,294,834 kms	A - A S-2036	
		Carry out A service as per service check list	
28/09/2017	1,290,327 kms	A - A S-1997	
		carry out A service as per service sheet	
16/09/2017	1,286,789 kms	B - B S-1950	
		Carry out B service as per service check list changing engine oil and filters	
16/09/2017	1,286,789 kms	A - A S-1949	
		Carry out A service as per service check list 4ltr oil added cummins	
31/08/2017	1,278,035 kms	A - A S-1906	
		Carry out A service as per service sheet	
30/08/2017		D S-2071	
		Carry out D service as per service check list	
16/08/2017	1,270,608 kms	A - A S-1857	
		Carry out A service, as per service checklist	
14/08/2017		CAB AIRBAG R-401	Workshop
		Removed and replaced x2 cab airbags	
03/08/2017	1,261,432 kms	B - B S-1805	
		Carry out B service as per service sheet changing engine oil and filters needed about 4 ltr to top up	
03/08/2017	1,261,432 kms	AIR SYSTEM R-394	Workshop
		Inspect and repair air leaks replacing 3 x air regulators williams also replacing cab height control valve test system ok	
03/08/2017	1,261,432 kms	A - A S-1804	
		Carry out A service as per service sheets	
31/07/2017	1,261,432 kms	Replace 4 new batteries R-383	Workshop
		Inspect and repair hard to start dianose faulty batteries remove and replace 4 x batteries supplied by battery barn	
19/07/2017	1,253,453 kms	tune up R-379	Workshop
		Carry out V & I adjustment set to spec also replacing horton supply line and headlight globs, also added 2 Litres of Cummins Engine Oil	
18/07/2017	1,253,453 kms	A - A S-1779	
		Carry out A service as per service check list	
08/07/2017	1,248,697 kms	A - A S-1735	
		Carry out A service as per service checklist	
24/06/2017	1,239,630 kms	B - B S-1670	
		Carry out B service as per service check list changing engine oil and filters	
20/06/2017	1,236,987 kms	A - A S-1655	
		Carry out A service as per service check list	
17/06/2017	1,235,866 kms	ENGINE OIL R-362	Workshop
		Added 6 Litres of Cummins Oil	
09/06/2017	1,232,288 kms	A - A S-1622	
		Carry out A service as per service check list	

Date	Reading / Units	Type / Repairer Notes	Repairer
27/05/2017	1,223,640 kms	A - A S-1562 Carry out A service	
13/05/2017	1,215,069 kms	A - A S-1531 Carry out A service	
13/05/2017	1,215,069 kms	B - B S-1532 Carry out B service as per service checklist, Change engine oil and filters	
06/05/2017	1,212,221 kms	engine oil R-330 topped up engine oil 6 ltr cummins oil	Workshop
26/04/2017	1,206,838 kms	A - A S-1476	
13/04/2017	1,202,647 kms	A - A S-1441	
30/03/2017	1,195,743 kms	A - A S-1365	
30/03/2017	1,195,743 kms	B - B S-1366 Change out x3 steering aim UNI joints. Remove & replace x3 diff torque rod bushes Change out tail shaft centre bearing Relign R/H rear axle brake & drum	
24/03/2017	119,200 kms	MICHELIN MULTI Z T-77 New steer tyres fitted & balanced. Drive tyres rotated.	CVT
18/03/2017	1,188,256 kms	A - A S-1410	
28/02/2017	1,177,368 kms	D S-1099 Replace R/H window winder and clutch pedal rubber	
28/02/2017	1,177,368 kms	A - A S-1322 Window winder door lock rear diff leak input seal	
18/02/2017		D S-1098 Fit custom steering wheel	
15/02/2017	1,168,780 kms	AIRCON R-322 CARRY OUT REPAIR AND SERVICE ON VIESA DIAGNOSE VIESA EVAP.AIR SYSTEM FAULT LOCATE AND REPLACE FAULTY REAR VENT MICRO SWITCH,DRIVE MOTOR AND DOOR REMOVE & CLEAN OUT EVAPORATOR TRAY SUPPLY & INSTALL 1 X NEW EVAPORATOR FLUSH OUT ALL LIQUID LINES FLUSH OUT WATER TANK FILL WITH FRESH WATER AND ADD VIESA ANTI BACTERIAL RUN SYSTEM CHECK OPERATION OK	Briskair
15/02/2017	1,172,489 kms	A - A S-1226	
08/02/2017	1,169,228 kms	D S-1097 Remove horton fan and rekit horton	
04/02/2017	1,167,173 kms	B - B S-1096	
04/02/2017		B - B S-1192	
04/02/2017		A - A S-1191	
02/02/2017		Recalibrate load scales R-308	
14/01/2017	1,156,439 kms	A - A S-1123	
17/12/2016	146,109 kms	A - A S-1039 CARRY OUT A SERVICE	

Date	Reading / Units	Type / Repairer Notes	Repairer
10/12/2016	141,809 kms	B - B S-1028 CARRY OUT B SERVICE AND CLEAN CHASSIS ENGINE OIL AND FILTERS 43 LTRS CUMMINS OIL LF14000NN FF2200 FS19729	
06/12/2016		AIR CONDITINING R-286 (JUSTIN BAILEY) INSPECTED AND REPAIRED FAULTY AIRCOBN WIRING AND HARD WIRED FRIDGE POWER SUPPLY	
03/12/2016	138,394 kms	A - A S-993 1 LT CUMMINS OIL	
24/11/2016	134,308 kms	AIR CONDITINING R-276 REMOVE AND REPLACE A/C CONDENSER SPLIT PIPE (JUSTIN BAILEY FITTED). REMOVE AND REPLACE 1 X HEATER TAP TOPPED UP COOLANT	
16/11/2016	131,402 kms	A - A S-942 CARRY OUT A SERVICE AS PER SERVICE CHECK LIST	
11/11/2016	131,402 kms	BRAKE SLACK ADJUSTER R-273 REMOVE AND REPLACE ALL SLACK ADJUSTER STEER AND DRIVE RESHIM AND ADJUST TO SPEC	
05/11/2016	125,311 kms	A - A S-900 CARRY OUT A SERVICE	
20/10/2016	117,776 kms	A - A S-865	
20/10/2016	117,776 kms	MUFFLER R-259 RENEW MUFFLER LHS	
08/10/2016	112,350 kms	A - A S-822 CARRY OUT A SERVICE 8LTR CUMMINS OIL	
23/09/2016	105,829 kms	A - A S-774 CARRY OUT A SERVICE	
10/09/2016	100,460 kms	A - A S-726 CARRY OUT A SERVICE	
27/08/2016	94,261 kms	A - A S-689 CARRY OUT A SERVICE	
24/08/2016	93,341 kms	B - B S-680 CARRY OUT B SERVICE AND CLEAN CHASSIS CHANGE ENGINE OIL AND FILTERS 43 LTRS CUMMINS OIL LF14000NN FF2200 FS19729	
08/08/2016	84,598 kms	C - C Service S-602 DIFF OILS CHANGED/ DIFF FILTER RENEWED/TRANSMISSION OIL CHANGED/TRANSMISSION FILTER RENEWED/COOLANT FILTER CHANGED/WHEEL BEARINGS CHECKED/KING PINS CHECKED/SPEED LIMITER CHECKED/ TURNTABLE CHECKED/ELECTRICAL CHECKED/CHECK ALL BRAKES FOR WEAR/CHECK SPRINGS AND SHACKLE PINS/CHECK AIRBAGS/CHECK SHOCKOS.	
29/07/2016	79,234 kms	A - A S-584	
16/07/2016	74,092 kms	A - A S-552	
15/07/2016	74,092 kms	AIR CONDITINING, ELECTRICAL R-167 RENEW AIR CON COMPRESSOR AND HOSES REPAIR WIRING R/H DOOR LOCK.	
06/07/2016	69,000 kms	B - B S-507	
06/07/2016		ELECTRICAL R-155 RENEW MIRROR BULBS AND LENS L/H AND R/H / RENEW 2X ROD ENDS CLUTCH LINKAGE.	

Date	Reading / Units	Type / Repairer Notes	Repairer
06/07/2016	69,000 kms	A - A S-506	
18/06/2016	56,256 kms	A - A S-465 2 LITRES ENGINE OIL TOPPED UP DIFFS POWER STEERING OIL LEAK REPAIRED	
15/06/2016	56,256 kms	POWER STEERING R-147 RENEW SUCTION HOSE POWER STEERING	
09/06/2016		Engine R-118 Remove oil engine from chassis. Change over parts to new engine. Fit new clutch. Replace fuel cooler lines and air govoner lines. Fit new engine.	Cummins Grafton
06/06/2016	52,809 kms	PYRO PROBE R-146 RENEW PYRO PROBE	
04/06/2016	48,998 kms	A - A S-425 2 LITRES OIL	
27/05/2016	48,996 kms	engine renew R-80 new crate motor fitted by cummins grafton	Cummins Grafton
21/05/2016		A - A S-399	
07/05/2016	41,820 kms	A - A S-333	
07/05/2016	41,820 kms	B - B S-334	
23/04/2016	37,532 kms	A - A S-302	
08/04/2016	27,956 kms	A - A S-249	
25/03/2016	21,703 kms	A - A S-175 1 LT OIL 1 LT COOLANT	
19/03/2016	18,361 kms	B - B S-165	
12/03/2016	13,209 kms	A - A S-120	
12/03/2016	13,209 kms	A - A S-207	
05/03/2016		engine oil R-20 top up engine oil	
27/02/2016	6,099 kms	A - A S-53	
07/06/2015	6,099 kms	C - C Service S-54	

Signed: _____

Name: _____

Date: _____