

03841034

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

mo2-1

Vehicle Standards and Inspection
Box 45064 Regent Postal Centre
Winnipeg, MB, R2C 5G7
1-204-985-0920

Manitoba

A942040

Date Inspection Started 24 03 25
DAY MO. YR.

Date Inspection Completed 24 03 25
DAY MO. YR.

Inspection Expiry Date 31 03 26
DAY MO. YR.

Station Number A6069

Mechanic Number M14576

Station Name Schwan Farmstead

Mechanic Signature [Signature]

Station Phone Number

Vehicle Owner Box 404

Address

Country Grove Farmstead

City Morris

Province MB

Postal Code R0G-1K0

Phone

- ☒ Pass/Safe Vehicle
- ☐ Fail/Unsafe Vehicle
- ☐ Fail/Hazardous

Licence Number 5H7683

Prov. MB

NSC #

Odometer Reading

Odor Type km mi

Vehicle Identification Number

37113778

Make High-Way

Model Postbus

Year 1971

Unit #

☒ Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck ☐ GVWR ☐ KGS ☐ Truck Tractor ☐ Trailer ☒ Semi-Trailer ☐ Bus ☐ School Bus ☐ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P R Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section

Section 1 - Power Train: Defects (if any)

Section 2 Suspension: Defects (if any)

Section 3 - Brake Systems: Defects (if any)

Section 4 - Steering: Defects (if any)

Section 5 - Instruments & Auxiliary Equipment: Defects (if any)

Section 6 - Lamps: Defects (if any)

Section 7 - Electrical System: Defects (if any)

Section 8 - Body: Defects (if any)

Section 9 - Tire & Wheel: Defects (if any)

Section 10 - Coupling Devices: Defects (if any)

Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining		Drum/Rotor		Stroke	
	L	R	L	R	L	R
1	11/16	11/16			1 1/4	1 1/4
2	5/8	5/8			1 1/4	1 1/4
3						
4						
5						
Final Measurement						

Axle	Tread Depth				Air Pressure			
	Initial		Corrected		Initial		Corrected	
	L	R	L	R	L	R	L	R
1								
2	7/32	6/32	1 1/2	1 1/2	100	100	100	100
3	6/32	9/32	1 1/2	8/32	100	100	100	100
4								
5								

Section 10 - Coupling Devices: Defects (if any)



THIS INSPECTION IS NOT A WARRANTY - inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a