



Vehicle Standards and Inspection

## Semi-Trailer Inspection Certificate

This Certificate is issued under the authority of the Province of Saskatchewan

Decal # A353735

Station #: 71944

Station Name: Bannerman Heavy Duty Repair

Technician #: 91716

Technician Name: Patrick Bannerman

Signing Officer #: 88221

Signing Officer Name: Joelle Bannerman

**Customer Details:**

Name: Just A Little Farm

Address: Box 460, Turtleford, Saskatchewan, S0M 2Y0

Inspection Completed Date: 08Jun2026

Inspection Expiry Date: 30Jun2027

**Vehicle Details:**

VIN: 2LDHG3029MF069901

Hubometer Reading:

Year: 2021

Vehicle Make/Model: LOAD KING/TRAILER

Plate: 610LXI

Jurisdiction: Saskatchewan

Unit:

Message(s): VIN has been validated.

This certificate does not warranty or guarantee the condition of this vehicle's components and systems for any period of time.



Vehicle Standards and Inspection

### Semi-Trailer Record of Inspection

The Record of Inspection must be given to the customer regardless of whether the vehicle passes or fails.

Station #: 71944

Station Name: Bannerman Heavy Duty Repair

Technician #: 91716

Technician Name: Patrick Bannerman

Signing Officer #: 88221

Signing Officer Name: Joelle Bannerman

**Customer Details:**

Name: Just A Little Farm

Address: Box 460, Turtleford, Saskatchewan, S0M 2Y0

**Vehicle Details:**

VIN: 2LDHG3029MF069901

Hubometer Reading:

Year: 2021

Vehicle Make/Model: LOAD KING TRAILER

**Inspection Details:**

Pass	Rejected	Corrected	Req Attn	DRIVERS COMPARTMENT	Comments
x				Vehicle Identification (5)	
x				Fire Extinguisher (5)	
x				Auxiliary Controls/Equip (5)	

Pass	Rejected	Corrected	Req Attn	BODY EXTERIOR	Comments
x				Lamps (6)	
x				Reflex Reflectors (6)	
x				Retro Reflective Markings (6)	
x				Trailer Hitch (10)	
x				Attached Equipment (8)	
x				Cargo Bodies/Vessels (8)	
x				Mud Flaps/Fenders (8)	
x				Landing Gear (8)	
x				Rear Impact Guard (8)	
x				Trailer Power Cord (7)	

Pass	Rejected	Corrected	Req Attn	ENGINE COMPARTMENT	Comments
x				Fuel System (1)	
x				Battery/Wiring Condition (7)	

Pass	Rejected	Corrected	Req Attn	CHASSIS	Comments
x				Hyd Brake System/Components (3.1)	
x				Air Brake System/Components (3.2)	
x				Elec Brake System/Components (3.1)	
x				Wheel Bearings (9)	
x				Tires/Wheels (9)	
x				Self-Steering Axle (2&4)	
x				Frame/Crossmembers/Mounts (8)	
x				Suspension/Axles (2)	
x				Exhaust/Emission System (1)	
x				Sliding Axle Assembly (if equipped) (8)	

**Brake/Tire Measurements**

**Axle 1-Pass**

Wheel1 : Tire Tread Depth: 9 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 9 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 44 degrees • Brake Stroke: 1.25 in

Wheel3-On : Tire Tread Depth: 5 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 44 degrees • Brake Stroke: 1.25 in

Wheel4 : Tire Tread Depth: 5 mm

Brake(1): No Brake

N/A

**Axle 2-Pass**

Wheel1 : Tire Tread Depth: 13 mm

Brake(1): No Brake

N/A

Wheel2-On : Tire Tread Depth: 13 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 44 degrees • Brake Stroke: 1.25 in

Wheel3-On : Tire Tread Depth: 5 mm

Brake(1): S-CAM Brake

• Min Brake Lining/Pad: 11/16 in • Cam Rotation: 44 degrees • Brake Stroke: 1.25 in

Wheel4 : Tire Tread Depth: 5 mm

Brake(1): No Brake

N/A

PASS - vehicle passes inspection

Decal # A353735

Inspection Completed Date: 08Jun2026