04117838

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba

Vehicle Safety
Box 45064 Regent Postal Outlet
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba C100200

	DAY	MO.	YR.
Date Inspection Started	20	10	26
Date Inspection Completed	20	10	26
Inspection Expiry Date	31	10	27

Station Number: A3017 Station Name: Lucky Star Wash & Service City: Brandon

Mechanic Number: M12220 Mechanic Signature: [signature] Station Phone Number: 204-571-1537

Vehicle Owner: Renaissance Transport LTD

Address: Site 145 Box 46 RR1 City: Brandon Province: MB Postal Code: R7A 5Y4 Phone:

- [x] Pass/Safe Vehicle
- [ ] Fail/Unsafe Vehicle
- [ ] Fail/Hazardous

Licence Number: UNAT Prov.: MB NSC #: N/A Odometer Reading: N/A Odom. Type: [ ] km [ ] mi

Vehicle Identification Number: 4DLC0061103 Make: Freightliner Model: Century Year: 1998 Unit #: A39

[x] Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

____Truck GVWR ____ KGS ____Truck Tractor ____Trailer ✓Semi-Trailer ____Bus ____School Bus ____Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
X		**Section 1 - Power Train:** Defects (if any)
X		**Section 2 Suspension:** Defects (if any)
X		**Section 3 - Brake Systems:** 3H (3A) Defects (if any) Circle Brake Type
X		**Section 4 - Steering:** Defects (if any)
X		**Section 5 - Instruments & Auxiliary Equipment:** Defects (if any)
X		**Section 6 - Lamps:** Defects (if any)
X		**Section 7 - Electrical System:** Defects (if any)
X		**Section 8 - Body:** Defects (if any)
X		**Section 9 - Tire & Wheel:** Defects (if any)
X		**Section 10 - Coupling Devices:** Defects (if any)

Brake Inspection Type: A (B) C D E Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining L	Lining R	Drum/Rotor L	Drum/Rotor R	Stroke L	Stroke R
1	11	11	16.531	16.517	1 1/2	1 1/2
2	11	11	16.535	16.564	1 1/2	1 1/2
3		16"				
4						
5						
	Final Measurement					

Axle	Tread Depth Initial L		Tread Depth Initial R		Tread Depth Corrected L		Tread Depth Corrected R		Air Pressure Initial L		Air Pressure Initial R		Air Pressure Corrected L		Air Pressure Corrected R	
1	16	16	15	16					100	100	100	100				
2	8	7	8	8					100	100	100	100				
3																
4		5	11													
5																

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: _____ Signature Date: _____

FVS0022-01-(R-06/25)

Ce document peut être obtenu en français sur demande.

COPY IN CAB - PLEASE ENSURE CERTIFICATE IS SIGNED - NOT FOR REGISTRATION