

04077977

PERIODIC MANDATORY VEHICLE
INSPECTION CERTIFICATE

Manitoba

M04-2

Vehicle Safety
Box 45064 Regent Post
Winnipeg, MB, R2C 5C7
1-204-985-0920

Manitoba

C067688

Date Inspection Started DAY 15 MO. 10 YR. 26	Station Number A6213	Station Name By's Transport.	City St. Adolphe
Date Inspection Completed DAY 17 MO. 10 YR. 28	Mechanic Number 10025	Mechanic Signature <i>[Signature]</i>	Station Phone Number 204-883-2382
Inspection Expiry Date DAY 31 MO. 10 YR. 27	Vehicle Owner By's Transport.	Address Box 369 St. Adolphe MB	Postal Code R5A-1A2

☒ Pass/Safe Vehicle	Licence Number TJ7898	Prov. MO	NSC #	Odometer Reading	Odom. Type km ☐ mi ☐
☒ Fail/Unsafe Vehicle	Vehicle Identification Number 2LDHG2839DF056301	Make Load King	Model Hopper	Year 13	Unit # B-54
☐ Fail/Hazardous	☒ Confirmed legible Vehicle Identification Number on vehicle				

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck GVWR KGS Truck Tractor Trailer ☒ Semi-Trailer Bus School Bus Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section
		Section 1 - Power Train: Defects (if any)
☒	☒	Section 2 Suspension: Defects (if any) 7-B
☒	☒	Section 3 - Brake Systems: 3H 3A Defects (if any) Circle Brake Type 13-A 15-E
		Section 4 - Steering: Defects (if any)
☒		Section 5 - Instruments & Auxiliary Equipment: Defects (if any)
☒	☒	Section 6 - Lamps: Defects (if any) 1-L, 1-C, 3-A
☒		Section 7 - Electrical System: Defects (if any)
☒	☒	Section 8 - Body: Defects (if any) 21-A
☒	☒	Section 9 - Tire & Wheel: Defects (if any) 4-A +/- 1-B
		Section 10 - Coupling Devices: Defects (if any)

Axle	Tread Depth				Air Pressure								
	Initial		Corrected		Initial		Corrected						
	L	R	L	R	L	R	L	R					
1	2	3	9	9	15	16	100	90	88	90	100	100	100
2	9	13	13	12			85	90	90	75	100	100	100
3	8	7	10	11			80	78	85	95	100	100	100
4													
5													

Brake Inspection Type: A B C D E Circle appropriate Letter for Internal Brake Component Inspection

Axle	Lining		Drum/Rotor		Stroke	
	L	R	L	R	L	R
1	9/16	9/16	16.542	16.563	1 1/2	1 1/2
2	9/16	9/16	16.501	16.582	1 1/2	1 1/2
3	1 1/16	1 1/16	16.562	16.542	1 1/2	1 1/2
4						
5						
	Final Measurement					

- THIS INSPECTION IS NOT A WARRANTY -

This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks:

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: Signature Date:

