



BRITISH COLUMBIA

Commercial Vehicle Inspection Report

Decal Number: PY16208
 Decal Expiry Date: 2026-Mar-31
 Inspection Number: 21504669

Inspection Result:
PASS

M04-4

FACILITY: NORTHERN B.C. TRUCKERS' / NS398
 INSPECTOR: LOCKYER, JAMES BRENT / 105221
 WORK ORDER #:

INSP. TYPE: Complete
 INSP. CLASS: Class 2 - Heavy Vehicle with LGVW 5501 kg or more
 INSP. REASON: Semi-annual

INSP. START: 2025-Sep-21 08:30 AM PST
 INSP. COMPLETE: 2025-Sep-21 09:30 AM PST

VEHICLE JUR: British Columbia
 PLATE #: PV8903
 LICENCED GWV(kg): 52500
 VEHICLE YEAR: 2003
 MAKE: KENWORTH
 MODEL:

REGI: 12533686
 UNIT/FLEET#: 245
 BODY STYLE: Truck Tractor
 ODOMETER: 99736 KM
 HUB ODOMETER:
 BRAKE TYPE: Air
 FUEL TYPE:

VIN: 1XKWDB0XGR968408
 OWNER/LESSEE NAME: POINTS NORTH CONTRACTING LTD.,
 ADDRESS: BOX 6638
 Fort St John, British Columbia
 V1J4J1, Canada

| | |
|---|----------------|
| Vehicle Identification (VIN) | Passed |
| Section 1 - Power Train | Passed |
| Section 2 - Suspension | Passed |
| Section 3 - Brake System | Passed |
| Section 3A - Air Brakes | Passed |
| Section 3H - Hydraulic Brakes | Not Applicable |
| Section 4 - Steering | Passed |
| Section 5 - Instruments and Auxiliary Equipment | Passed |
| Section 6 - Lamps | Passed |
| Section 7 - Electrical System | Passed |
| Section 8 - Frame and Body | Passed |
| Section 9A - Tires | Passed |
| Section 9B - Wheels | Passed |
| Section 10 - Coupling Devices | Passed |
| Section 11 - Other Vehicle Components | Not Applicable |

NEW WINDSHIELD

| Air Brake Chamber Type, Size and Push Rod Stroke (mm) | | | | Tire Tread Depth (mm) | | | | | | |
|---|-------|------|------------|-----------------------|-------|---------|---------|---------|---------|----------|
| Axles | Type | Size | Slack Adj. | Left | Right | Outer L | Inner L | Inner R | Outer R | Steering |
| 1 | Clamp | 24 | Automatic | 30 | 30 | 20 | | | 20 | ✓ |
| 2 | Clamp | 30 | Automatic | 30 | 31 | 18 | 18 | 18 | 18 | |
| 3 | Clamp | 30 | Automatic | 31 | 30 | 17 | 17 | 17 | 17 | |

| Air Brake Camshaft Rotation (degrees) | | | Brake Lining/Pad (mm) | | | Rotor Thickness or Drum Inside Diameter (mm) | | |
|---------------------------------------|------|-------|-----------------------|------|-------|--|--------|--------|
| Axles | Left | Right | Lining/Pad | Left | Right | Rotor/Drum | Left | Right |
| 1 | 0 | 0 | Lining (Shoe) | 21 | 21 | Drum | 419.00 | 419.00 |
| 2 | 0 | 0 | Lining (Shoe) | 21 | 21 | Drum | 419.00 | 419.00 |
| 3 | 0 | 0 | Lining (Shoe) | 21 | 21 | Drum | 419.00 | 419.00 |

Inspection Comments:
 Has this Vehicle been road tested? No
 Inspector: LOCKYER, JAMES BRENT
 Road Test Date:
 Signature: *James Brent Lockyer*
 Road Tester:

This Inspection Report was submitted to CVSE on 2025-Sep-21 03:36 PM PST
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement:

CVSED014
 9/22/2025 9:54:28 AM PST