



Commercial Vehicle Inspection Report

Decal Number: PY12154
 Decal Expiry Date: 2026-Jun-30
 Inspection Number: 21378565

Inspection Result:
PASS

M04-5

FACILITY: NORTHERN B.C. TRUCKERS' / N5398
 INSPECTOR: LOCKYER, JAMES BRENT / 105221
 WORK ORDER #:
 INSP. TYPE: Complete
 INSP. CLASS: Class 3 - Trailer and Semi-Trailer
 INSP. REASON: Annual
 INSP. START: 2025-Jun-02 08:30 AM MST
 INSP. COMPLETE: 2025-Jun-02 09:30 AM MST

VEHICLE JUR: British Columbia
 PLATE #: 82862U
 LICENCED GVW(kg): 999999
 VEHICLE YEAR: 2012
 MAKE: **LODE-KING**
 MODEL:
 REGI: 11512630
 UNIT/FLEET#:
 BODY STYLE: LOWBOY TRAILER
 ODOMETER:
 HUB ODOMETER:
 BRAKE TYPE: Air
 FUEL TYPE:
 VIN: 2LDS5331CS052384
 OWNER/LESSEE NAME: POINTS NORTH CONTRACTING LTD.,
 ADDRESS: BOX 6638
 Fort St John, British Columbia
 V1J4J1, Canada

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Not Applicable
Section 3A - Air Brakes	Repaired (same day) REPLACED POT #1 RH
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed NEW TIRES
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)						Tire Tread Depth (mm)				
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	30	31	17	17	17	17	
2	Clamp	30	Automatic	31	30	17	17	17	17	
3	Clamp	30	Automatic	30	31	17	17	17	17	

Comment: Comment:

Air Brake Camshaft Rotation (degrees)				Brake Lining/Pad (mm)				Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right		Left	Right	Left	Right	Rotor/Drum	Left	Right	
1	63	68		Lining/Pad		17	16	Drum			
2	76	63		Lining (Shoe)		15	17	Drum			
3	80	63		Lining (Shoe)		14.5	17	Drum			

Comment: Comment: Comment: Air Brake Camshaft Rotation performed, Rotor Thickness or Drum Diameter not measured.

Inspection Comments:
 Has this Vehicle been road tested? No
 Inspector: LOCKYER, JAMES BRENT
 Road Test Date: James Brent
 Signature: _____ Road Tester:

This Inspection Report was submitted to CVSE on 2025-Jun-04 02:49 PM MST
 The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.
 The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSOVP at the Commercial Vehicle Safety Enforcement
 CVSE0014
 6/4/2025 2:49:30 PM MST