

Vehicle Service Records (VSR Explorer)

Repair history D-203254

Registration nr:	657WPA	Chassis ID:	D-203254	VIN:	YV5RG40D2GD203254
Market type:	-	Country:	-	Delivery date:	2016-07-26

(A) 2026-06-01 | Mileage: 1338384 km | Order No: 8654416

PC	Type	Code	Description (Original)	#
R	Other	K	CONTACT PH: DARYL 0409 340 793	
R	Operation	LO-210	ENGINE FAN LOCKING IN	6
R	Operation	LO-250	EXHAUST BRAKE LEAK	2.5
R	Part	VO-24017083	FAN ENG	1
R	Part	VO-22889891	ACTUATOR SERVICE K	1
R	Part	VO-23532368	AVU VALVE	1
	Description / Note		Carry out warm hold test.	
R	Part	VO-22696301	IDLER PULLEY	1
R	Part	VO-21479276	D13 BELT TENSIONER USA10	1
R	Part	VO-23686532	ENG BELT	1
R	Part	VO-3979639	GASKET PRE HEAT	2
R	Part	VO-21389923	PIPE	1
	Description / Note		Connect diagnostic tool and check fault codes.	
	Description / Note		EX WACOL	
	Description / Note		Found AVU actuator leaking.	
	Description / Note		R&R new actuator.	
	Description / Note		Carry out another actuator test.	
	Description / Note		Found AVU valve leaking.	
	Description / Note		R&R AVU valve.	
	Description / Note		Found active code for engine fan.	
	Description / Note		Check engine fan plug - Found OK.	
	Description / Note		Drain coolant, remove header tank, intercooler line and	
	Description / Note		remove discharge line.	

PC	Type	Code	Description (Original)	#
	Description / Note		Check all tensioners and belts, found fan side belt and	
	Description / Note		tensioners worn.	
	Description / Note		Remove fan hub and R&R engine fan.	
	Description / Note		R&R fan belt, idler and tensioners.	
	Description / Note		Replace header tank pipe.	
	Description / Note		Refit all parts, refill coolant and wash engine bay down.	
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2025-12-01 | Mileage: 1326728 km | Order No: 8330916

PC	Type	Code	Description (Original)	#
R	Other	ACC	PLEASE FILL IN	
R	Operation	LO-871	A/C NOT COLD	3.5
	Description / Note		A/C BLOWES AIR NOT COLD	
R	Part	VO-82348991	EVAPORATOR	1
R	Part	VO-23847736	DECAL	1
R	Part	VO-23858694	ACCUMULATOR	1
R	Part	VO-82386482	O-RING	1
R	Part	OTH-84191414	ORIFICE TUBE VALVE	1
R	Part	VO-82356760	O-RING	1
R	Part	VO-82386482	O-RING	1
R	Part	VO-23437874	CONDENSER	1
R	Part	VO-979652	CLEAR HOSE	0.7
	Description / Note		Contact: KEN 0419 753 701	
	Description / Note		- Performance tested the A/C.	
	Description / Note		- Found it blowes air but not cold.	
	Description / Note		- Connect A/C machine. The gauge read 0.	
	Description / Note		Therefore no gas was in the system indicating a leak.	
	Description / Note		- Inspected the system and found that the evaporator was	
	Description / Note		leaking. As there was dye in the drain tube.	
	Description / Note		- Everything else was good.	

PC	Type	Code	Description (Original)	#
	Description / Note		- Recovered the system 100g came out.	
	Description / Note		- Pressurised with nitrogen and couldnt hear or see	
	Description / Note		anything as the evaporator is inside the cab.	
	Description / Note		- Removed the dash to access the unit.	
	Description / Note		- Under the bonnet, removed the accumulator and other	
	Description / Note		bolts to removed the unit.	
	Description / Note		- Removed took apart to access evaporator and used UV	
	Description / Note		light to find leak.	
	Description / Note		- Installed new evaporator.	
	Description / Note		- Reinstalled everything else.	
	Description / Note		- Removed the orifice pipe and removed oriface.	
	Description / Note		- Installed new orifice.	
	Description / Note		- Reinstalled orifice pipe.	
	Description / Note		- Removed condensor.	
	Description / Note		- Installed new condensor.	
	Description / Note		- Vaccumed down system.	
	Description / Note		- No leaks detected.	
	Description / Note		- Recharged system with 650g of refrigerant.	
	Description / Note		- Completed another performace test.	
	Description / Note		- All is good and blowing cold air.	
R	Other	97	ENVIRONMENTAL CHARGE	
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2025-06-10 | Mileage: 1215083 km | Order No: 4281496

PC	Type	Code	Description (Original)	#
W	Operation	VO-5611600	Air drier, replace	2.7
W	Part	VO-85023466	AIR DRIER, EXCH	1

PC	Type	Code	Description (Original)	#
	Description / Note		Repair not building air - air dumping out of APM exhaust	
	Description / Note		New APM has just been fitted	
W	Operation	VO-5602100	APM, status	0.3
W	Operation	VO-1709200	Replace hardware, programming	0.2

(A) 2025-05-22 | Mileage: 1305119 km | Order No: 8500044

PC	Type	Code	Description (Original)	#
W	Operation	VO-5611600	Air drier, replace	2.7
W	Part	VO-85023466	APM, EXCH	1
W	Operation	VO-1701000	Connect-disconnect of diagnostic tool	0.2
W	Operation	VO-1701200	Fault codes, reading	0.2
W	Operation	VO-3710200	Electric wires and connections, check	0.4

(A) 2025-04-11 | Mileage: 1297796 km | Order No: 8325420

PC	Type	Code	Description (Original)	#
R	Other	ACC	PLEASE FILL IN	
R	Operation	LO-510	Rear axle on trailer r/h/s	4
	Description / Note		brakes heating up	
	Description / Note		Contact:KEN SAWTELL 07 5534 2844 / KEN 0419 753 701 Next Service:	
	Description / Note		CREDIT LIMIT: BALANCE: Mileage: 1297796Hrs: 20953Defect sheet complete	
	Description / Note		Y/N _____	
R	Part	UNK-NTH10280KP	Calliper D313461R	1
R	Part	VO-FREIGHT	FREIGHT	50
R	Other	97	ENVIRONMENTAL CHARGE	
	Description / Note		with fertalizer contamination	
	Description / Note		JACKED UP WHEEL AND CHECKED OPERATION OF BRAKES. FOUND	
	Description / Note		BRAKES LOCKED ON WITH PARK BRAKE OFF.	
	Description / Note		REMOVE WHEEL AND BOOSTER AND FOUND BRAKE CALIPER SEIZED IN	
	Description / Note		APPLIED POSTION.	
	Description / Note		REMOVE AND REPLACE CALIPER	
	Description / Note		REFIT WHEEL AND CHECKED OPERATION.	

PC	Type	Code	Description (Original)	#
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2025-02-27 | Mileage: 2150581 km | Order No: 8448857

PC	Type	Code	Description (Original)	#
I	Operation	VO-3986000	Telematics Gateway, install	2.5
	Description / Note		2.5hrs	
	Description / Note		Rego: 657WPA	
	Description / Note		Chassis: D203254	
	Description / Note		Install new telematics kit, sim card, cable and calibrate	
	Description / Note		*****	

(A) 2025-02-26 | Mileage: 0 km | Order No: 8448755

PC	Type	Code	Description (Original)	#
	Description / Note		Repair without detail info	

(A) 2025-02-25 | Mileage: 1296607 km | Order No: 8448731

PC	Type	Code	Description (Original)	#
R	Operation	LO-870	A/C FAN NOT BLOWING & A/C WARM	4.5
R	Part	VO-24219966	BLOWER MOTOR	1
R	Part	VO-22131014	SWITCH PANEL	1
	Description / Note		Connect diagnostic tool and check faults.	
	Description / Note		Update software for CCM.	
	Description / Note		Disassemble LHS dash components.	
	Description / Note		Check blower motor fuse - Found OK.	
	Description / Note		Check resistance at blower motor - Found high resistance.	
	Description / Note		R&R blower motor.	
	Description / Note		Test blower motor operation - Found to be working but	
	Description / Note		changing speeds control panel sticks.	
	Description / Note		R&R A/C switch panel.	

PC	Type	Code	Description (Original)	#
	Description / Note		Refit dash components.	
	Description / Note		Test A/C operation - Found OK.	
R	Other	91	WORKSHOP CONSUMABLES	
	Description / Note		L5184 VOLVO FH, FM POST 2016W3 TELEMATICS 3G SUNSET	
W	Other	3982400	Telematics connectivity, check and	
	Description / Note		activation, test	
W	Part	VO-23544009	TELEMATICS CONTROL	1
W	Part	VO-23004613	SIM CARD	1
W	Part	VO-85166246	CONVERSION KIT	1
	Description / Note		INITIATIVE	

(A) 2024-07-22 | Mileage: 1233154 km | Order No: 8319529

PC	Type	Code	Description (Original)	#
R	Other	M	PLEASE FILL IN	
	Description / Note		Contact:KEN SAWTELL 07 5534 2844 / 0419 753 701	
R	Operation	LO-250	exhaust noise when under power	0.5
R	Other	97	ENVIRONMENTAL CHARGE	
R	Part	VO-22907383	V-CLAMP	1
	Description / Note		replace leaking V clamp on exhaust pipe	
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2024-06-04 | Mileage: 1218323 km | Order No: 8444951

PC	Type	Code	Description (Original)	#
R	Other	K	MAIN CONTACT/PH:	
	Description / Note		KLM.....	
	Description / Note		HRS.....	
R	Operation	LO-192	VEHICLE BROKEN DOWN, TRAVEL TO VEHICLE AT	3
	Description / Note		SAWTELLS YARD, CURRUMBIN	
R	Other	92	UTE MILEAGE 48 km's @ \$2.50/km.	
R	Operation	LO-561	Handbrake not responding	2
	Description / Note		Drove to breakdown site	
	Description / Note		Connected techtool, fault codes found	

PC	Type	Code	Description (Original)	#
	Description / Note		Handcontrol unit missing message & LIN12 communication	
	Description / Note		Carried out electrical resistance tests on wiring	
	Description / Note		Ground White - ok	
	Description / Note		Signal Grey - ok	
	Description / Note		Supply Red - not ok	
	Description / Note		removed wiring harness bracket and conduit, removed cable	
	Description / Note		ties	
	Description / Note		Tested resistance between xc203:12 - x1:18 found	
	Description / Note		resistance fluctuating when harness moved.	
	Description / Note		Issue in wiring under cab.	
	Description / Note		Carried out wiring repair on 7054 and removed and	
	Description / Note		replaced section of wire with high resistance.	
	Description / Note		Refitted all removed parts fitted new cable ties - tested	
	Description / Note		and operation all ok	
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2024-05-22 | Mileage: 1215083 km | Order No: 8444716

PC	Type	Code	Description (Original)	#
W	Operation	LO-19400	Travel for WARRANTY breakdowns ONLY	1.5
	Description / Note		DARRYL 0409 340 793	
W	Operation	VO-5611600	Air drier, replace	2.7
W	Part	VO-85023466	AIR DRIER, EXCH	1
	Description / Note		Repair not building air - air dumping out of APM exhaust	
	Description / Note		New APM has just been fitted	
W	Operation	VO-5602100	APM, status	0.3
W	Operation	VO-1709200	Replace hardware, programming	0.2

(A) 2024-05-10 | Mileage: 2150581 km | Order No: 8444624

PC	Type	Code	Description (Original)	#
R	Other	K	MAIN CONTACT/PH:	
	Description / Note		KLM.....	
	Description / Note		HRS.....	
R	Operation	LO-560	APM FAULT	5
R	Part	VO-85023466	AIR DRIER, EXCH	1
R	Part	VO-992234	NIPPLE BRASS - 16X2 x 22mm	1
R	Part	VO-991082	SWIVEL 12m	1
R	Part	VO-952627	P CLAMP	2
	Description / Note		16/5/24 - Checked all wiring from park brake switch down	
R	Operation	LO-510	REPAIR PARK BRAKE NOT APPLYING	1
	Description / Note		10/05/2024 - Connect Laptop, checked for faults, updated	
	Description / Note		software for APM , road tested all ok.	
	Description / Note		to the APM unit and found all ok. Further testing	
	Description / Note		indicated internal fault found in APM unit.	
	Description / Note		Removed complete apm, removed all connected airlines	
	Description / Note		Fitted New APM uni refitted airlines, replaced 2x airline	
	Description / Note		fittings due to air leak found, tested operation all ok	
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2024-05-10 | Mileage: 0 km | Order No: 8444568

PC	Type	Code	Description (Original)	#
	Description / Note		Repair without detail info	

(A) 2024-03-06 | Mileage: 1193772 km | Order No: 8443672

PC	Type	Code	Description (Original)	#
R	Operation	LO-720	BROKEN STEER SPRINGS	12
R	Part	VO-22944256	FLANGE NUT M24	8
R	Part	VO-22935392	U-BOLT 225mm	4
R	Part	VO-23236847	FRONT SPRING	2
R	Part	MK-NARV56306	CABLE TIES SMALL	1
R	Part	VO-984739	BOLT M8X50	1
	Description / Note		Jacked up vehicle then removed muffler and RHS steer guard	

PC	Type	Code	Description (Original)	#
	Description / Note		for access. Had to oxy cut off all u bolts due to seizing.	
	Description / Note		Replaced both sides springs then refitted muffler and	
	Description / Note		refitted guard. Had to drill out and extract broken bolt	
	Description / Note		in RHS guard. Tensioned all bolts and road tested ok.	
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2023-11-10 | Mileage: 1172447 km | Order No: 8442252

PC	Type	Code	Description (Original)	#
R	Operation	LO-250	DIAGNOSE LOW POWER	5
R	Part	VO-20920705	SILENCER	1
R	Part	VO-60112470	HEX. SOCKET SCREW M8X85	2
R	Part	VO-8150742	PIN - THREADED	1
R	Part	MK-NARV56306	CABLE TIES	1
	Description / Note		OUTSIDE	
	Description / Note		Conencted laptop	
	Description / Note		Downloaded fault codes	
	Description / Note		Road tested and monitored exhaust back pressure	
	Description / Note		Found exhaust back pressure to high	
	Description / Note		Muffler blocked	
	Description / Note		Started to removed muffler and found strap bolts rusted	
	Description / Note		Cut off strap bolts	
	Description / Note		Removed anbd replaced muffler	
	Description / Note		Swapped over sensor to new miffler	
	Description / Note		Cleared codes	
	Description / Note		Roas tested - all ok	
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2023-02-18 | Mileage: 1093746 km | Order No: 8169806

PC	Type	Code	Description (Original)	#
R	Other	M	PLEASE FILL IN	
	Description / Note		Contact: 5534 2844	
R	Operation	LO-560	AIR COMPRESSOR OVER USE	4
	Description / Note		ONLY LET HIM BULD UP TO 6-8 BARS AND CANT RELEASE MAXXIS.	
R	Other	192	VEHICLE BROKEN DOWN,TRAVEL TO VEHICLE AT	
	Description / Note		CUNNINGHAM HWY HEADING EAST TO BRISBANE	
	Description / Note		JUST NEAR MDTAPILLY	
R	Other	92	UTE MILEAGE 38 km's @ \$2.20/km.	
	Description / Note		Mileage: 1096348	
	Description / Note		Hrs: 17272	
I	Part	VO-20538793	SEAL STRIP, R/COVER GASKET	1
R	Part	MK-FT1862X4	QC JOINER 1/4	1
	Description / Note		parts booked to wrong job	
	Description / Note		CAN HEAR UADIBLE AIR LEAK AROUND ENGINE	
	Description / Note		Drove out to truck, could hear air leaking around starter	
	Description / Note		motor. Found airline in chassis near starter has melted	
	Description / Note		though and is leaking, melting caused by malfunctioning	
	Description / Note		starter motor getting hot and melting through everything	
	Description / Note		around it, put joiner in airline, built up air, no leaks	
	Description / Note		present, informed driver about starter issue.	
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2022-12-20 | Mileage: 1084541 km | Order No: 8438207

PC	Type	Code	Description (Original)	#
R	Operation	LO-250	EXHAUST PIPE CAME OFF AND MELTED LINES	3
	Description / Note		FOR ADBLUE ? CHECK AND REPAIR AS REQUIRED	
R	Part	VO-20744599	CONNECTOR,5/16 ADBLUE 45deg	1
R	Part	VO-20748166	CONNECTOR, 3/8 ADBLUE 45 deg	1
R	Part	VO-21706081	CABLE HARNESS	1
R	Part	MK-NARV56306	CABLE TIES	1

PC	Type	Code	Description (Original)	#
R	Part	VO-21574984	DOSAGE VALVE	1
	Description / Note		Removed covers for access	
	Description / Note		Removed adblue wiring harness	
	Description / Note		Removed and replaced adblue dosage valve	
	Description / Note		Fit up new adblue wiring harness	
	Description / Note		Replaced adblue fittings as required	
	Description / Note		Repositioned exhaust pipe and secured in place	
	Description / Note		Carroed out dosage valve test - all ok	
	Description / Note		Carried out road test - all ok	
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2022-09-07 | Mileage: 1048130 km | Order No: 8302319

PC	Type	Code	Description (Original)	#
R	Other	ACC	PLEASE FILL IN	
	Description / Note		Contact:KEN SAWTELL 07 5534 2844 / 0419 753 701	
R	Operation	LO-250	engine brake fualt on dash	2.2
R	Part	VO-20378934	FUSE 10 AMP MINI	2
R	Part	VO-23871484	CONTROL VALVE	1
	Description / Note		2140	
R	Other	97	ENVIRONMENTAL CHARGE	
	Description / Note		checked fault code print out fault	
	Description / Note		checked and found fuse 40 blown	
	Description / Note		checked and wiring ok	
	Description / Note		found oil thermostat valve faulty	
	Description / Note		R&R OIL THERMOSTAT VALVE	
	Description / Note		FIITED NEW FUSE	
	Description / Note		CLEARED FAULT CODE AND ROAD TEST OK	
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2022-07-15 | Mileage: 1022099 km | Order No: 8300912

PC	Type	Code	Description (Original)	#
	Description / Note		Repair without detail info	

(A) 2022-07-13 | Mileage: 1022099 km | Order No: 3019949

PC	Type	Code	Description (Original)	#
	Description / Note		Repair without detail info	

(A) 2022-05-25 | Mileage: 1007060 km | Order No: 8299438

PC	Type	Code	Description (Original)	#
R	Other	M	PLEASE FILL IN	
	Description / Note		Contact:Ken 0755342844	
R	Operation	LO-260	CHECK RADIATOR	6
R	Part	VO-85021957	EXCH RADIATOR	1
R	Part	VO-20592783	INTER.HOSE CLAM	2
R	Part	VO-948980	O-RING	1
R	Operation	LO-510	rectify brake fault showing on dash	1.5
R	Part	MK-NARV56306	CABLE TIE 1=25PC	1
R	Part	VO-22560373	HOSE	1
R	Part	VO-984758	BOLT M10*70 FL GR10.9	4
R	Part	VO-21313188	CONNECTOR 45 deg	1
R	Part	VO-20722710	HOSE CLAMP	1
R	Part	VO-993977	HOSE CLAMP	2
R	Part	MK-NARV82098	24V 7 PIN EBS	1
R	Part	AU2-AMP22567321	VOLVO VCS COOLANT 5LTR	1
R	Other	97	ENVIRONMENTAL CHARGE	
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2022-04-19 | Mileage: 1001341 km | Order No: 8298640

PC	Type	Code	Description (Original)	#
R	Operation	LO-870	a/c not working	6
R	Part	VO-23858694	ACCUMULATOR	1
R	Part	VO-23847736	DECAL	1
R	Part	VO-23515346	VENTILATION FILTER	1
R	Part	VO-82348991	EVAPORATOR	1
R	Part	VO-82356760	O-RING	1
R	Part	VO-82386482	O-RING	1
R	Part	VO-979652	HOSE	1

PC	Type	Code	Description (Original)	#
R	Part	VO-23515329	VENTILATION FILTER	1
R	Part	VO-78544873	HOSE	1
R	Part	VO-984733	BOLT M8*16 FL	1
R	Part	VO-984725	BOLT M6*16	1
R	Part	VO-84223447	HEAT CONTROL VALVE	1
R	Part	VO-82464711	CLIP KIT	1
	Description / Note		check AC no gas check for leaks found evaporator leaking	
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2022-03-28 | Mileage: 1001122 km | Order No: 8298178

PC	Type	Code	Description (Original)	#
R	Other	M	PLEASE FILL IN	
	Description / Note		Contact:KEN SAWTELL 07 5534 2844 / 0419 753 701	
R	Operation	LO-460	clutch fault check and report	10
R	Part	VO-85013166	CYLINDER	1
R	Part	VO-85022461	CLUTCH KIT	1
R	Part	VO-22327063	SOLENOID VALVE	1
R	Part	VO-25339078	NUT M14 FINE PITCH	4
R	Part	VO-995906	BOLT M14*46 THREAD LOCKER	4
R	Part	VO-1652986	SPIGOT BRG	1
R	Part	VO-85108352	R/M SEAL F16 & FH12/16	1
R	Other	40	Sublet machine flywheel	
R	Part	VO-20992763	AIR HOSE	1
R	Part	AU2-WUR089010810	BRAKE CLEAN	2
R	Part	VO-21052612	CONNECTOR	1
R	Part	VO-20566049	FITTING 1/4TU X M12 STRAIGHT	1
R	Part	AU2-AMP22567321	VOLVO VCS COOLANT 5LTR	1
R	Other	40	Sublet repairs PTO	
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2021-10-09 | Mileage: 970749 km | Order No: 8294346

PC	Type	Code	Description (Original)	#
R	Other	M	KEN SAWTELL 07 5534 2844 / 0419 753 701	
R	Operation	LO-261	COOLANT LEAKING COOLING SYSTEM	4.5
R	Part	VO-23653292	RADIATOR	1
R	Part	AU2-AMP22567321	5 LTR VOLVO VCS COOLANT	1

PC	Type	Code	Description (Original)	#
	Description / Note		Checked over engine for coolant leak, unable to locate	
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2021-09-15 | Mileage: 966487 km | Order No: 8432683

PC	Type	Code	Description (Original)	#
R	Operation	LO-218	REAR ENGINE MOUNTS	7
R	Part	VO-21416525	RUBBER CUSHION	2
R	Part	VO-995906	BOLT M14X46	4
R	Part	VO-984050	HEXAGON NUT	4
R	Part	MK-NARV56306	CABLE TIES	1
	Description / Note		Removed driveshaft	
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2021-06-08 | Mileage: 911874 km | Order No: 7616122

PC	Type	Code	Description (Original)	#
	Description / Note		KEN SAWTELL 07 5534 2844	
R	Operation	LO-565	INSPECT AIR LEAKS	1.5
R	Part	VO-20545485	DIAPHRAGM	1
R	Part	VO-984735	BOLT M8*25 FLANGE 8.8G	4
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2021-05-13 | Mileage: 899392 km | Order No: 8431271

PC	Type	Code	Description (Original)	#
R	Other	20	Engine light on / Repaired at JT Fossey	
	Description / Note		Warning on dash Attention pulling power reduced. Adblue	

(A) 2020-10-12 | Mileage: 785835 km | Order No: 8428987

PC	Type	Code	Description (Original)	#
R	Operation	LO-260	ENGINE FAN STUCK IN	3.5
R	Operation	LO-560	REPLACE COMPRESSOR (LEAKING)	2.5
R	Operation	LO-600	POWER STEERING PUMP LEAKING	1.5
	Description / Note		(WATER PUMP)	
R	Part	VO-85003294	FAN	1
R	Part	VO-85013941	COMPRESSOR, EXCH	1
R	Part	VO-471708	SEAL RING	1
R	Part	VO-992065	O-RING	1

PC	Type	Code	Description (Original)	#
R	Part	VO-21488833	STEERING PUMP	1
R	Part	VO-85013425	WATER PUMP EXCHANGE	1
R	Part	VO-21103569	SEALING RING	1
R	Part	VO-977030	O'RING	1
R	Part	VO-1161995	ATF OIL	1
R	Part	VO-20852765	GASKET	2
R	Part	VO-21479276	D13 BELT TENSIONER USA10	1
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2020-10-01 | Mileage: 779930 km | Order No: 3007302

PC	Type	Code	Description (Original)	#
R	Operation	LO-645	Power steering leak on passenger side	1.1
R	Part	VO-22835610	SERVO PIPE	1
R	Part	VO-21349444	SOCKET	1
R	Part	VO-85122800	ATF DEX 3 1 LTR	1
	Description / Note		Complaint: Power steering leak	
R	Other	91	Workshop Consumables	

(A) 2019-07-26 | Mileage: 575568 km | Order No: 8424431

PC	Type	Code	Description (Original)	#
W	Operation	VO-1706800	36 Months ECU download and oil sample. O	0.9
	Description / Note		Only valid for Australian market	
W	Part	VO-23448457	OIL SAMPLING KIT	4

(A) 2019-05-29 | Mileage: 544584 km | Order No: 8423841

PC	Type	Code	Description (Original)	#
I	Operation	LO-810	Repair Accident damage	3.14
I	Part	VO-82943948	REAR VIEW MIRROR	1

(A) 2019-05-28 | Mileage: 544530 km | Order No: 8423789

PC	Type	Code	Description (Original)	#
W	Operation	VO-2630600	Thermostat fan, replace	2.9
W	Part	VO-85003294	FAN	1
W	Operation	VO-1790600	Diagnostic with Tech Tool/GD. Connect-di	0.5
	Description / Note		Connect-disconnect of diagnostic tool included	
W	Operation	VO-2840700	Sensor values, check	0.2
W	Operation	VO-3710200	Electric wires and connections, check	0.4
W	Operation	VO-2632500	Engine cooling fan, test	0.2

PC	Type	Code	Description (Original)	#
W	Operation	LO-170	Road test	0.5
W	Operation	VO-1702600	Program control unit	0.1

(A) 2019-03-19 | Mileage: 514046 km | Order No: 8423110

PC	Type	Code	Description (Original)	#
I	Operation	LO-220	Rectify oil leak at rear of engine	4
I	Part	VO-21447682	GASKET	1
I	Part	AU2-9718-240002743	BBC4 BRAKE CLEANER	1
I	Part	MK-NARV56306	CABLE TIE 1=25PK	1
	Description / Note		Trace leak to upper timing cover gasket leaking.	

(A) 2019-01-09 | Mileage: 480114 km | Order No: 8422376

PC	Type	Code	Description (Original)	#
W	Operation	VO-1706700	30 Months ECU download and oil sample. O	0.9
	Description / Note		Only valid for Australian market	
W	Part	VO-8394887	KIT OIL TEST Sample	4

(A) 2018-11-29 | Mileage: 446215 km | Order No: 8422017

PC	Type	Code	Description (Original)	#
W	Other	2112600	Cylinder head, replace	
W	Other	20	SUBLET - BARNES	
	Description / Note		PO: 422804 INV: Å1780.63 INCL GST	

(A) 2018-10-04 | Mileage: 446215 km | Order No: 8421431

PC	Type	Code	Description (Original)	#
W	Operation	VO-2112600	Cylinder head, replace	8.4
W	Part	VO-21834205	OUTER AIR FILTER	1
W	Part	VO-21115501	INNER AIR FILTER	1
W	Part	VO-21510072	CYLINDER HEAD GASK	1
W	Part	VO-20855371	GASKET	6
W	Part	VO-21282255	GASKET	1
W	Part	VO-276948	O RING KIT	6
W	Part	VO-21447682	GASKET	1
W	Part	VO-20538793	SEALING STRIP	1
W	Part	VO-21613426	THERMOSTAT	1
W	Part	VO-21503575	SEALING RING	1
W	Part	VO-20479636	SEAL	1

PC	Type	Code	Description (Original)	#
W	Part	VO-1547254	O-RING T/STAT	2
W	Part	VO-20852765	GASKET	2
W	Part	VO-8192804	SCREW	8
W	Part	VO-21344774	BOLT M10X50	6
W	Part	VO-85013271	UNIT INJECTOR, EXC Ä5	1
W	Part	VO-85020372	TURBOCHARGER, EXCH	1
W	Part	VO-20784537	GASKET TURBO MOUNT	1
W	Part	VO-22718180	KIT EX Man Kit D13A D13C D13K	1
W	Part	VO-22206133	GASKET	1
W	Part	VO-21940615	SEALING RING	1
W	Part	VO-469601	TURBO O-RING	1
W	Part	VO-420643	GASKET Turbo Drain	1
W	Part	VO-994447	FLANGE SCREW	8
W	Part	VO-990810	FLANGE SCREW	4
W	Part	VO-21532258	SEALING RING	1
W	Part	VO-21261987	GASKET	6
W	Part	VO-85013933	EXCH CYLINDER HEA	1
W	Part	VO-22879257	CAMSHAFT BEARING K	1
W	Part	VO-22879256	CAMSHAFT BEARING K	6
W	Part	AU2- WUR0547350070	Hose Clamp 50-70mm	1
W	Part	VO-3979639	GASKET PRE HEAT	2
W	Part	VO-1547252	SEAL RING AIR COMP INTAKE FH12	1
W	Part	AU2- WUR0547335050	Hose Clamp 35-50mm	1
W	Part	VO-982724	DOWDY WASHER	2
	Description / Note		Old: 1512121079 New: 1803234063	
W	Operation	VO-1790600	Diagnostic with Tech Tool/GD. Connect-di	0.5
W	Operation	VO-2840700	Sensor values, check	0.2
W	Operation	VO-2170800	Oil sump, install	0.6
W	Operation	VO-2170600	Oil sump, remove	0.2
W	Operation	LO-221	Oil pump, remove-install. Sump removed	1.1
W	Operation	VO-2118400	Cylinder head, install and remove from o	0.8
W	Operation	VO-2117700	Cylinder head, transfer parts	0.5
W	Operation	VO-2100600	Cylinder Compression, test	0.2
W	Operation	VO-2301600	Cylinder balancing, check	0.2
W	Operation	VO-2161100	Connecting rod bearings, replace (all).	1.5
W	Operation	VO-2160300	Main bearings, replace (all). Oil sump r	2.8
W	Operation	LO-170	STEAM CLEAN	0.4
W	Operation	VO-2371200	Injector shut off, manual	0.2

(A) 2018-08-21 | Mileage: 426261 km | Order No: 8420643

PC	Type	Code	Description (Original)	#
W	Operation	VO-1706600	24 Months ECU download and oil sample. O	0.9
	Description / Note		Only valid for Australian market	
W	Operation	VO-8100500	24 Months cab inspection	0.4
W	Operation	VO-1774600	Annual service	2.4
W	Part	VO-8394887	KIT OIL TEST	4

(A) 2018-07-05 | Mileage: 395378 km | Order No: 8264361

PC	Type	Code	Description (Original)	#
W	Other	2580700	Pump unit, replace..	
W	Part	VO-21516229	FILTER	1
W	Part	VO-21954674	STRAINER	1
W	Part	VO-22670998	TANK	1
W	Part	VO-22716720	COMBINED TANK UNIT	1
W	Part	VO-22851845	PUMP UNIT	0.6
I	Part	MK-NARV56310	CABLE TIE 1=10PK	2
I	Part	VO-984734	BOLT M8*20 FL	8
I	Part	VO-20428158	CABLE TIE	8
W	Operation	VO-2580700	Pump unit, replace	0.8
W	Operation	VO-1701000	Connect-disconnect of diagnostic tool	0.2
W	Operation	VO-2584600	SCR system, test	0.5
W	Other	2580700	Pump unit, replace.	
W	Other	2591700	AST 25 259 02, check. Campaign only	
W	Operation	VO-2580300	AdBlue tank, replace	1.3
W	Operation	VO-2589500	Ad Blue tank, level warning, update. Cam	0.3
	Description / Note		Campaign only	
W	Operation	VO-2582200	Filter, AdBlue, replace	0.2
W	Operation	VO-2584800	Strainer, replace. Pump unit	0.2

(A) 2018-06-21 | Mileage: 388820 km | Order No: 8419892

PC	Type	Code	Description (Original)	#
	Description / Note		CCM, SW UPDATE. FH/FM (4)	
W	Operation	VO-1701000	Connect-disconnect of diagnostic tool	0.2
W	Operation	VO-8711300	CCM, SW Updating. Campaign only	0.2
W	Operation	VO-7218200	Front spring, both side, replace. only c	5.4
W	Part	VO-84433698	AIRBAG MODULE light	1
W	Part	VO-257913	FRONT SPRING	2
W	Part	VO-22935392	U-BOLT 225mm	4

PC	Type	Code	Description (Original)	#
W	Operation	VO-8842000	Airbag module, replace	0.3

(A) 2018-06-04 | Mileage: 346211 km | Order No: 8420119

PC	Type	Code	Description (Original)	#
W	Operation	VO-2510400	Gaskets, exhaust manifold, replace	1.8
W	Operation	VO-5611100	Compressor, replace	1.7
W	Part	VO-85013941	COMPRESSOR, EXCH	1
W	Part	VO-471708	SEAL RING	1
W	Part	VO-992065	O-RING	1
W	Other	20	SUBLET - FASTBRAKE MACHINING	
W	Part	VO-20855371	GASKET	6
W	Part	VO-22718180	KIT EX Man Kit D13A D13C D13K	1
W	Part	VO-20784537	GASKET TURBO MOUNT	1
W	Part	VO-21940615	SEALING RING	1
W	Part	VO-469601	TURBO O-RING	1
W	Part	VO-420643	GASKET Turbo Drain	1
W	Part	VO-22206133	GASKET	1
	Description / Note		PO: 422538 INV: 25193 Å88.00 INCL GST	

(A) 2018-04-03 | Mileage: 343665 km | Order No: 8261650

PC	Type	Code	Description (Original)	#
R	Operation	LO-19400	TRAVEL TO VEHICLE AT	0.2
R	Operation	LO-310	JUMP START VEHICLE AS REQUESTED	1
	Description / Note		TINGIRA STREET, PINKENBA & RETURN TO WORKSHOP	
R	Other	92	UTE MILEAGE 8 km's Ö Å1.48/km.	
R	Other	91	WORKSHOP CONSUMABLES	

(A) 2018-03-29 | Mileage: 342610 km | Order No: 8099911

PC	Type	Code	Description (Original)	#
R	Other	M	PLEASE FILL IN	
	Description / Note		Contact:tiffaney 02 42729755	
R	Other	3000	cab tilt alarm fault	
R	Other	20	sublet to southern truck centre	

(A) 2018-01-30 | Mileage: 322510 km | Order No: 8418864

PC	Type	Code	Description (Original)	#
W	Operation	VO-1706500	18 Months ECU download and oil sample. O	0.9

PC	Type	Code	Description (Original)	#
	Description / Note		Only valid for Australian market	
I	Operation	LO-610	RECTIFY STEERING WHEEL NOT STRAIGHT	4.26

(A) 2018-01-17 | Mileage: 302859 km | Order No: 35348

PC	Type	Code	Description (Original)	#
W	Operation	VO-7200000	Springs, general. Secondary operation number.ADDITIONAL LABOUR AS APPROVED, CHECK LHS SPRING. CHECK SHACKLES	2
W	Operation	VO-7211100	Front spring, replace (right hand side)	2.4
W	Part	VO-257938	FRONT SPRING	1

(A) 2018-01-17 | Mileage: 0 km | Order No: 8096869

PC	Type	Code	Description (Original)	#
	Description / Note		Repair without detail info	

(A) 2017-11-11 | Mileage: 285350 km | Order No: 8418222

PC	Type	Code	Description (Original)	#
W	Operation	VO-2373100	Sleeve, unit injector, replace (Others e	0.4
W	Part	VO-21351717	INJECTOR SLEEVE	6
W	Part	VO-20526428	VEB O-RING	1
W	Part	VO-1677370	VEB O-RING	2
W	Part	VO-1161963	RUBBER GREASE fett	1
W	Part	VO-21344774	BOLT M10X50	6
W	Part	VO-990073	CABLE TIE	6
W	Operation	VO-4132000	Clutch cylinder, replace. Gearbox remove	0.2
W	Other	20	Machine flywheel	
	Description / Note		Fastbrake Machining	
W	Part	VO-85013766	CLUTCH KIT, EXCH	1
W	Part	VO-1652986	SPIGOT BEARING	1
W	Part	VO-22327063	SOLENOID VALVE	1
W	Part	VO-85020472	CLUTCH CYLINDER, E	1
W	Part	VO-20483426	SEALING RING	1
W	Part	VO-22352397	INPUT SHAFT	1
W	Part	VO-21344746	BOLT M16X82	14
W	Part	VO-21626057	ROLLER BEARING	1
W	Part	VO-20766774	CONTROL PLUNGER	6
W	Part	VO-21140387	SPRING	6
W	Part	VO-3092340	SEALANT GREY	1
W	Part	VO-20860677	SEALING RING	1

PC	Type	Code	Description (Original)	#
W	Part	VO-20992763	CLUTCH CYLINDER AIR HOSE	1
W	Part	VO-20497205	GASKET	1
W	Operation	VO-2373600	Unit injector, replace (all)	3.7
W	Operation	VO-2373300	Sleeve, unit injector, replace. Unit inj	0.3
W	Operation	VO-2601200	Cooling system, drain and refill	0.8
W	Operation	VO-4319700	Input shaft, overhaul. Unit removed	0.9
W	Operation	VO-4318700	Gearbox, disassemble-inspect-assemble. G	7.6
W	Operation	VO-4317000	Gearbox, remove	0.8
W	Operation	VO-4317200	Gearbox, install	1.5
W	Operation	VO-2580400	AdBlue tank, remove	0.8
W	Operation	VO-2580500	AdBlue tank, install	0.7
W	Operation	VO-2160700	Flywheel bearing, replace. Clutch remove	0.2
W	Operation	VO-2163100	Flywheel, check. Pressure plate removed	0.3
W	Operation	VO-2162100	Flywheel, replace. Gearbox and clutch re	0.6
W	Operation	VO-2123500	Flywheel housing run-out, check. Clutch	0.4
W	Operation	VO-2500500	Response, test drive	0.4
W	Operation	VO-4118300	Valve assembly, clutch, replace	0.5
W	Part	VO-995906	BOLT M14X46	4
W	Part	VO-25339078	NUT M14	4
W	Operation	VO-4008300	PWM valves, clutch, test	0.2
W	Operation	VO-1701000	Connect-disconnect of diagnostic tool	0.2
W	Operation	VO-4136100	Air hose, replace. CVU/CCA	0.5

(A) 2017-08-17 | Mileage: 223702 km | Order No: 8417511

PC	Type	Code	Description (Original)	#
I	Operation	VO-6431200	Link rod, replace	1.2
I	Part	VO-21554115	BALL JOINT	1

(A) 2017-07-20 | Mileage: 205741 km | Order No: 8417236

PC	Type	Code	Description (Original)	#
W	Operation	VO-1774600	Annual service. Chassis lubrication and	2.4
	Description / Note		oil changes included only in some models	
W	Operation	VO-1706400	12 Months ECU download and oil sample. O	0.9
W	Operation	VO-8100300	12 Months cab inspection	0.4
I	Other	5610000	Inspected air compressor for an oil	
I	Other	600	Check RH tie rod end	
W	Operation	VO-2580000	Emissions after-treatment. Secondary ope	0.7
W	Operation	VO-5620000	Compressed-air tank and mounting. Second	0.5
W	Part	VO-8394887	KIT OIL TEST	4

PC	Type	Code	Description (Original)	#
W	Part	VO-21480006	FILLER NECK	1
W	Part	VO-23121198	FILLER NECK	1

(A) 2017-06-20 | Mileage: 188263 km | Order No: 8416969

PC	Type	Code	Description (Original)	#
W	Operation	VO-1701000	Connect-disconnect of diagnostic tool	0.2
W	Operation	VO-2800800	EMS and ACM, sw , update. Only campaign	0.4
	Description / Note		NOTE FOR S3224: Please reference AST 28 202 01	
W	Operation	VO-4651400	Pinion sealing ring, replace	2
W	Part	VO-8171338	LOCK NUT	1
W	Part	VO-21448461	DIFF SEAL	1
W	Part	VO-995906	BOLT M14X46	4
W	Part	VO-25339078	NUT M14	4
W	Operation	VO-4650000	Final drive (front and rear). Secondary	0.45

(A) 2017-05-17 | Mileage: 167915 km | Order No: 8416433

PC	Type	Code	Description (Original)	#
W	Operation	VO-2611100	Radiator hose, replace (lower). Coolant	0.1
	Description / Note		drained	
W	Operation	VO-2601200	Cooling system, drain and refill	0.8
W	Part	VO-22560373	HOSE	1
W	Part	VO-21312237	CHARGE AIR HOSE	1

(A) 2017-02-07 | Mileage: 111585 km | Order No: 8250876

PC	Type	Code	Description (Original)	#
W	Operation	VO-8740800	Condenser, replace	0.7
I	Other	210	TURN OFF DAYTIME RUNNING LIGHTS	
W	Part	VO-82693739	ACCUMULATOR	1
W	Part	VO-22768926	CONDENSER	1
W	Operation	VO-8701100	Refrigerant, draining for re-using	0.2
W	Operation	VO-8700700	Refrigerant, filling	0.3
W	Operation	VO-8741400	Cooling unit, performance test	0.3

(A) 2017-01-24 | Mileage: 103957 km | Order No: 8250560

PC	Type	Code	Description (Original)	#
W	Operation	VO-1706300	6 Months ECU download and oil sample. Only valid for Australian market	0.9
W	Part	VO-8394887	OIL TEST KIT	4
W	Operation	VO-3540800	Interior lights, cable harness, install. Campaign only	0.5

PC	Type	Code	Description (Original)	#
W	Part	VO-22935545	WIRES	8
W	Operation	VO-4307200	Inspection cover, install	0.4
W	Part	VO-3192319	LEVEL INSP. GLASS	1
W	Operation	VO-1701000	Connect-disconnect of diagnostic tool	0.2
W	Operation	VO-2549400	ACM, SW, update. only campaign	0.2

(A) 2017-01-23 | Mileage: 103957 km | Order No: 8250493

PC	Type	Code	Description (Original)	#
W	Operation	VO-8743300	A/C compressor, replace	1.2
W	Part	VO-82348991	EVAPORATOR	1
W	Part	VO-82356760	O-RING	1
W	Part	VO-82386482	O-RING	1
W	Part	VO-82354791	VENTILATION FILTER	1
W	Part	VO-82348995	VENTILATION FILTER	1
W	Part	VO-84180960	HOSE	1
W	Part	VO-3090885	O-RING KIT A/C	1
W	Part	VO-85013654	COMPRESSOR, EXCH	1
W	Operation	VO-8746800	High pressure hose, replace	0.7
W	Operation	VO-8743100	Evaporator, replace	0.5
W	Operation	VO-8741400	Cooling unit, performance test	0.3

(A) 2016-12-16 | Mileage: 103957 km | Order No: 8250560

PC	Type	Code	Description (Original)	#
W	Operation	VO-1706300	6 Months ECU download and oil sample. On	0.9
	Description / Note		Only valid for Australian market	
W	Operation	LO-3540800	Interior Lights, Cable Harness, Install	0.5
W	Operation	LO-4307200	Inspection cover, install	0.4
W	Operation	VO-1701000	Connect-disconnect of diagnostic tool	0.2
W	Operation	VO-2549400	ACM, SW, update. only campaign	0.2
W	Part	VO-8394887	OIL TEST KIT	4
W	Part	VO-22935545	WIRES	8
W	Part	VO-3192319	LEVEL INSP. GLA	1

(A) 2016-10-22 | Mileage: 52845 km | Order No: 8415101

PC	Type	Code	Description (Original)	#
W	Operation	VO-3531000	Tail light complete, replace (One side)	0.3
W	Part	VO-84195505	TAIL LAMP CLUSTER	1

(A) 2016-09-07 | Mileage: 23922 km | Order No: 8414753

PC	Type	Code	Description (Original)	#
I	Other	K	346 hr	
I	Operation	LO-882	LHS roof scoop rattling / loose	0.58
I	Operation	LO-210	Oil filler splout not pulling out	0.27
I	Operation	LO-460	Clinging in drive line	0.7
	Description / Note		Drilled bracket and installed two screws.	

(A) 2016-08-18 | Mileage: 9599 km | Order No: 8414626

PC	Type	Code	Description (Original)	#
W	Operation	VO-1721000	Warranty service. After 4 weeks or maxim	1.9
	Description / Note		maximum 10 000 km.	

(A) 2016-06-22 | Mileage: 99 km | Order No: 8074616

PC	Type	Code	Description (Original)	#
W	Other	8430000	Glass windscreen sealing	
	Description / Note		WATER LEAK TOP RIGHT OF WINDSCREEN	
W	Other	80	Sublet Alpha glass	
I	Operation	LO-843	Diagnose leak	0.37

(A) 2016-06-14 | Mileage: 68 km | Order No: 8073813

PC	Type	Code	Description (Original)	#
I	Operation	LO-171	PRE DELIVERY WITH PLATES	6.5
I	Other	MTELEC186	RIVETS	
I	Other	10	VEHICLE DETAIL	
I	Other	10	TARE WEIGHT	
I	Other	10	CUSTOM BADGE	
I	Operation	LO-360	DISABLE LOW AMP WARNING PARAMETER	1
	Description / Note		WITH AIR, POWERED, EARTHED AND WORKING	
I	Operation	LO-852	SHEEP SKIN SEAT COVERS	1
I	Other	10	WINDOW TINT	
I	Operation	LO-350	FIELD SERVICE TIP TO HEADLAMP PANELS	2
I	Operation	LO-810	FIT AERO KIT	3
I	Part	OTH-66306550	FORCH SEALANT BLACK K127 290ML	1
I	Part	VO-984734	FLANGE BOLT M8 x 20mm Black	4
I	Part	OTH-VSHEEPPAIRV1BV4	VOLVO SHEEP PAIR V4	1
I	Part	VO-990060	CABLE TERMINAL	2
I	Part	OTH-T2449	BUTANE GAS REFILL	1

PC	Type	Code	Description (Original)	#
I	Operation	LO-610	STRAIGHTEN STEERING WHEEL	0.6
I	Operation	LO-772	SET K-FACTOR TRUCK ONLY DOING 97KM/H	1

(A) 2016-06-13 | Mileage: 71 km | Order No: 8074304

PC	Type	Code	Description (Original)	#
W	Other	601	GENERAL - WHEEL ALIGNMENT	
W	Other	60	Sublet repairs wheel, Brett Steele	