

M06-1



Commercial Vehicle Inspection Report

Decal Number: **GJ70220**
Decal Expiry Date: **2026-Jun-30**
Inspection Number: **21411188**

Inspection Result:
PASS

FACILITY: MACCABEE TANKS LTD / S16900 INSP. TYPE: Complete INSP. START: 2025-Jun-30 02:00 PM PDT
INSPECTOR: Sluggett, Ryan / 202690 INSP. CLASS: Class 3 - Trailer and Semi-Trailer INSP. COMPLETE: 2025-Jun-30 03:00 PM PDT
WORK ORDER #: CVIP729 INSP. REASON: Annual

VEHICLE JUR: British Columbia REG: 14271086 VIN: 2AFASWBH1CR000173
PLATE #: 52675K UNIT/FLEET#: HT016 OWNER/LESSEE NAME: Aggressive Contracting Ltd., A.C.L. Construction Ltd.
LICENCED GWV(kg): 0 BODY STYLE: Tank Trailer ADDRESS: P.O. Box 6297
VEHICLE YEAR: 2012 ODOMETER: Fort St John, British Columbia
MAKE: ADVANCE HUB ODOMETER: V1J 4H7, Canada
MODEL: BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Repaired (same day) Replaced #2 axle both sides brake pots.
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed with Caution Monitor some very low.
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Repaired (same day) Repaired upper coupler.
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	26	26	4	5	9	10	
2	Clamp	30	Automatic	22	26	16	16	8	8	
3	Clamp	30	Automatic	27	23	7	9	3	4	

Comment:

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	70	45	Lining (Shoe)	16	16	Drum		
2	60	65	Lining (Shoe)	16	16	Drum		
3	80	80	Lining (Shoe)	14	14	Drum		

Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: _____ Road Tester: _____
Inspector: Sluggett, Ryan Signature:

This Inspection Report was submitted to CVSE on 2025-Jul-02 12:19 PM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorizing inspectors, and designating inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement.

CVSE011
7/2/2025 12:20:02 PM PDT