

04626294

PERIODIC MANDATORY VEHICLE INSPECTION CERTIFICATE

Manitoba  M06-1

Vehicle Standards and Inspection  
Box 45064, Regent Postal Outlet  
Winnipeg, MB, R2C 5C7  
1-204-985-0920

Manitoba 

Date Inspection Started: 14 01 26  
Date Inspection Completed: 19 01 26  
Inspection Expiry Date: 31 01 27

Station Number: A6007 Northline Service St. J. R. ...  
Mechanic Number: M751911  
Mechanic Signature: *[Signature]*  
Station Phone Number: 2043343535

Vehicle Owner: Shortline Moving Solutions Inc.  
Address: \_\_\_\_\_ City: \_\_\_\_\_ Province: \_\_\_\_\_ Postal Code: \_\_\_\_\_ Phone: \_\_\_\_\_

Pass/Safe Vehicle  
 Fail/Unsafe Vehicle  
 Fail/Hazardous

License Number: CRIN704 Prov. MB NSC # 1610436 Odometer Reading: 918279 Odom. Type:  km  ml

Vehicle Identification Number: 3HISDIZAIPIR9LIN16713325 Make: INT Model: LT Year: 19 Unit #: 103

Confirmed legible Vehicle Identification Number on vehicle

THE FACILITY AND INSPECTOR MUST BOTH BE AUTHORIZED FOR CLASS OF VEHICLE INSPECTED

Truck <sup>GWR</sup> 316207 KGS \_\_\_\_\_ Truck Tractor \_\_\_\_\_ Trailer \_\_\_\_\_ Semi-Trailer \_\_\_\_\_ Bus \_\_\_\_\_ School Bus \_\_\_\_\_ Coach Bus

List of applicable items to be inspected is in the Table of Contents of National Safety Code Standard 11 Part B

P	R	Mark "X" under "R" when item Rejected "XX" under "R" when item Hazardous "X" under "P" when item Corrected or No Defects found in Section																																																																						
X	X	Section 1 - Power Train: Defects (if any) CEL illuminated - Coolant leak @ Top Rad Hose Coolant Reservoir Cracked Leaking																																																																						
✓		Section 2 Suspension: Defects (if any)																																																																						
X	X	Section 3 - Brake Systems: 3H <u>3A</u> Defects (if any) Circle Brake Type LFS Brake Hose Leaking Air Leak @ Fire Wall Air Leak with Brake App																																																																						
		Brake Inspection Type: A B C D <u>E</u> Circle appropriate letter for Internal Brake Component Inspection																																																																						
		<table border="1"> <thead> <tr> <th rowspan="2">Axle</th> <th colspan="2">Lining</th> <th colspan="2">Drum/Rotor</th> <th colspan="2">Stroke</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>5/8</td> <td>5/8</td> <td>1.682</td> <td>1.680</td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>5/8</td> <td>5/8</td> <td>1.651</td> <td>1.660</td> <td></td> <td></td> </tr> <tr> <td>3</td> <td>5/8</td> <td>5/8</td> <td>1.650</td> <td>1.655</td> <td></td> <td></td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Lining		Drum/Rotor		Stroke		L	R	L	R	L	R	1	5/8	5/8	1.682	1.680			2	5/8	5/8	1.651	1.660			3	5/8	5/8	1.650	1.655			4							5																												
Axle	Lining			Drum/Rotor		Stroke																																																																		
	L	R	L	R	L	R																																																																		
1	5/8	5/8	1.682	1.680																																																																				
2	5/8	5/8	1.651	1.660																																																																				
3	5/8	5/8	1.650	1.655																																																																				
4																																																																								
5																																																																								
✓		Section 4 - Steering: Defects (if any)																																																																						
X	X	Section 5 - Instruments & Auxiliary Equipment: Defects (if any) No unwashed washers - No washer fluid																																																																						
✓		Section 6 - Lamps: Defects (if any)																																																																						
X	X	Section 7 - Electrical System: Defects (if any) Clean Batt. Connections																																																																						
X	X	Section 8 - Body: Defects (if any) Gb Shocks Blown																																																																						
X	X	Section 9 - Tire & Wheel: Defects (if any) Low Tire Pressure - LFS Wheel Seal Check Steer Bearings																																																																						
		<table border="1"> <thead> <tr> <th rowspan="3">Axle</th> <th colspan="4">Tread Depth</th> <th colspan="4">Air Pressure</th> </tr> <tr> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> <th colspan="2">Initial</th> <th colspan="2">Corrected</th> </tr> <tr> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> <th>L</th> <th>R</th> </tr> </thead> <tbody> <tr> <td>1</td> <td>13</td> <td>13</td> <td></td> <td></td> <td>105</td> <td>100</td> <td></td> <td></td> </tr> <tr> <td>2</td> <td>25</td> <td>25</td> <td>25</td> <td>25</td> <td>85</td> <td>80</td> <td>90</td> <td>85</td> </tr> <tr> <td>3</td> <td>25</td> <td>25</td> <td>26</td> <td>25</td> <td>90</td> <td>90</td> <td>90</td> <td>100</td> </tr> <tr> <td>4</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> <tr> <td>5</td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> </tr> </tbody> </table>	Axle	Tread Depth				Air Pressure				Initial		Corrected		Initial		Corrected		L	R	L	R	L	R	L	R	1	13	13			105	100			2	25	25	25	25	85	80	90	85	3	25	25	26	25	90	90	90	100	4									5								
Axle	Tread Depth				Air Pressure																																																																			
	Initial			Corrected		Initial		Corrected																																																																
	L	R	L	R	L	R	L	R																																																																
1	13	13			105	100																																																																		
2	25	25	25	25	85	80	90	85																																																																
3	25	25	26	25	90	90	90	100																																																																
4																																																																								
5																																																																								
X	X	Section 10 - Coupling Devices: Defects (if any) 5th Wheel Adjustment																																																																						

- THIS INSPECTION IS NOT A WARRANTY -  
This inspection addresses standards of safety and repair that a vehicle must meet as prescribed by the Vehicle Safety Inspection Regulation but does not guarantee these components will comply with the standards for any unspecified future period of time.

Remarks: \_\_\_\_\_

I am aware that the above-noted vehicle is unsafe to be operated on a highway until repairs or adjustments have been made to restore it to safe condition and an inspection mechanic has re-inspected the vehicle. Operating a vehicle with a Hazardous defect may result in further enforcement action if confirmed by a Peace Officer. If this vehicle is not returned within 14 days for re-inspection a complete inspection will be required.

Vehicle received without repairs by: \_\_\_\_\_ Signature \_\_\_\_\_ Date: \_\_\_\_\_

FV5022-01 (R-09/15)

Ce document peut être obtenu en français sur demande.

PRESENT THIS COPY WHEN REGISTERING VEHICLE