



Commercial Vehicle Inspection Report

Decal Number: GM02729
Decal Expiry Date: 2027-Jan-31
Inspection Number: 21649567

Inspection Result:
PASS

M06-2

FACILITY: MACCABEE TANKS LTD / S16900 INSP. TYPE: Complete INSP. START: 2026-Jan-31 09:15 AM PST
INSPECTOR: Sluggett, Ryan / 202690 INSP. CLASS: Class 3 - Trailer and Semi-Trailer INSP. COMPLETE: 2026-Jan-31 09:45 AM PST
WORK ORDER #: CVP841 INSP. REASON: Annual

VEHICLE JUR: British Columbia REGI: 13520403 VIN: 2A9TD1014MN125039
PLATE #: 90814J UNIT/FLEET#: HT-006 OWNER/LESSEE NAME: ACL Constructions Ltd., ACL Constructions Ltd.
LICENCED GVW(kg): 0 BODY STYLE: Booster Trailer ADDRESS: 9611-112 Street
VEHICLE YEAR: 2021 ODOMETER: Fort St John, British Columbia
MAKE: ASPEN HUB ODOMETER: V1J7C7, Canada
MODEL: BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Passed
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Repaired (same day) Repaired left marker light
Section 7 - Electrical System	Passed
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	20	22	12	12	0	9	
Comment:						Comment:				

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)			Rotor Thickness or Drum Inside Diameter (mm)		
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	31	38	Lining (Shoe)	16	16	Drum		
Comment:			Comment:			Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.		

Inspection Comments:
Has this Vehicle been road tested? No Road Test Date: _____ Road Tester:
Inspector: Sluggett, Ryan Signature: _____

This Inspection Report was submitted to CVSE on 2026-Jan-31 04:18 PMPST
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.