



Commercial Vehicle Inspection Report

Decal Number: **GM02785**
Decal Expiry Date: **2026-Nov-30**
Inspection Number: **21792410**

Inspection Result:
PASS

MO6-7

FACILITY: MACCABEE TANKS LTD / S16900 INSP. TYPE: Complete INSP. START: 2026-May-29 09:00 AM PDT
INSPECTOR: Sluggett, Ryan / 202690 INSP. CLASS: Class 3 - Trailer and Semi-Trailer INSP. COMPLETE: 2026-May-29 09:45 AM PDT
WORK ORDER #: CVIP901 INSP. REASON: Semi-annual

VEHICLE JUR: British Columbia REGI: 13948939 VIN: 2C9SBT3W9PM183409
PLATE #: 94267K UNIT/FLEET#: **HT013** OWNER/LESSEE NAME: A.C.L. Construction Ltd., A.C.L. Construction Ltd.
LICENCED GVW(kg): 0 BODY STYLE: Dump Trailer ADDRESS: P.O. Box 6297
VEHICLE YEAR: 2023 ODOMETER: Fort St John, British Columbia
MAKE: CROSS COUN HUB ODOMETER: V1J 4H7, Canada
MODEL: SIDE BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Repaired (same day) Replaced air lines rubbing on frame.
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Repaired (same day) Repaired ABS doesn't cycle.
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	21	23	8	13	16	16	
2	Clamp	30	Automatic	25	25	13	13	13	14	
3	Clamp	30	Automatic	25	24	11	10	11	13	
Comment:				Comment:						

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)		Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	84	95	Lining (Shoe)	12	10	Drum		
2	85	95	Lining (Shoe)	12	10	Drum		
3	78	90	Lining (Shoe)	12	12	Drum		
Comment:			Comment:		Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.			

Inspection Comments:
Has this Vehicle been road tested? No Road Test Date: _____ Road Tester:
Inspector: Sluggett, Ryan Signature:

This Inspection Report was submitted to CVSE on 2026-May-29 07:39 PM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.