



Commercial Vehicle Inspection Report

Decal Number: **GM02786**
Decal Expiry Date: **2026-Dec-31**
Inspection Number: **21796500**

Mob-8
Inspection Result:
PASS

FACILITY: MACCABEE TANKS LTD / S16900 INSP. TYPE: Complete INSP. START: 2026-Jun-02 08:00 AM PDT
INSPECTOR: Sluggett, Ryan / 202690 INSP. CLASS: Class 3 - Trailer and Semi-Trailer INSP. COMPLETE: 2026-Jun-02 09:00 AM PDT
WORK ORDER #: CVIP903 INSP. REASON: Semi-annual

VEHICLE JUR: British Columbia REGI: 14182975 VIN: 2C9SBT3W7PM183442
PLATE #: 94269K UNIT/FLEET#: **HT-017** OWNER/LESSEE NAME: A.C.L. Construction Ltd., A.C.L. Construction Ltd.
LICENCED GVW(kg): 0 BODY STYLE: Dump Trailer ADDRESS: P.O. Box 6297
VEHICLE YEAR: 2023 ODOMETER: Fort St John, British Columbia
WAKE: CROSS COUN HUB ODOMETER: V1J 4H7, Canada
WODEL: TRIDE BRAKE TYPE: Air
FUEL TYPE:

Vehicle Identification (VIN)	Passed
Section 1 - Power Train	Not Applicable
Section 2 - Suspension	Passed
Section 3 - Brake System	Passed
Section 3A - Air Brakes	Passed
Section 3H - Hydraulic Brakes	Not Applicable
Section 4 - Steering	Not Applicable
Section 5 - Instruments and Auxiliary Equipment	Not Applicable
Section 6 - Lamps	Passed
Section 7 - Electrical System	Repaired (same day) Repaired ABS, doesn't cycle.
Section 8 - Frame and Body	Passed
Section 9A - Tires	Passed
Section 9B - Wheels	Passed
Section 10 - Coupling Devices	Passed
Section 11 - Other Vehicle Components	Not Applicable

Air Brake Chamber Type, Size and Push Rod Stroke (mm)				Tire Tread Depth (mm)						
Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	30	Automatic	24	21	11	10	10	10	
2	Clamp	30	Automatic	22	22	10	14	9	10	
3	Clamp	30	Automatic	22	22	12	9	10	9	

Comment: Comment:

Air Brake Camshaft Rotation (degrees)			Brake Lining/Pad (mm)		Rotor Thickness or Drum Inside Diameter (mm)			
Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	67	76	Lining (Shoe)	14	14	Drum		
2	66	81	Lining (Shoe)	14	12	Drum		
3	61	70	Lining (Shoe)	14	12	Drum		

Comment: Comment: Comment: Air Brake Camshaft Rotation performed, Rotor Thickness or Drum Diameter not measured.

Inspection Comments:
Has this Vehicle been road tested? No
Inspector: Sluggett, Ryan
Road Test Date: 
Road Tester: Signature:

This Inspection Report was submitted to CVSE on 2026-Jun-02 10:33 AM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 25 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSCVIP at the Commercial Vehicle Safety Enforcement

CVSE014
3/2/2026 10:33:06 AM PDT