M08-2 ~~K10-2~~

Commercial Vehicle Inspection Report

Decal Number: GP27496
Decal Expiry Date: 2027-Jan-31
Inspection Number: 21863332 ~~282~~ 2026~~3~~93

Inspection Result: PASS

FACILITY:	HARKO HEAVY DUTY LTD. / S17130	INSP. TYPE:	Complete	INSP. START:	2026-Jul-28 07:00 AM PDT
INSPECTOR:	KRAJNC, HAYDEN / 202196	INSP. CLASS:	Class 2 - Heavy Vehicle with LGVW 5501 kg or more	INSP. COMPLETE:	2026-Jul-28 08:25 AM PDT
WORK ORDER #:	ROCKIRL UNIT 108	INSP. REASON:	Semi-annual		

VEHICLE JUR:	British Columbia	REGI:	13431791	VIN:	3HSLGAPR1MN263279
PLATE #:	84412P	UNIT/FLEET#:	108	OWNER/LESSEE NAME:	P.A WALKER CAPITAL, LTD
LICENCED GVW(kg):	63500	BODY STYLE:	Truck Tractor	ADDRESS:	2-734 LAVAL CRES
VEHICLE YEAR:	2021	ODOMETER:	429196 KM		Kamloops, British Columbia
MAKE:	INTERNATNA	HUB ODOMETER:			V2C 5P3, Canada
MODEL:		BRAKE TYPE:	Air		
		FUEL TYPE:			

Vehicle Identification (VIN)	Passed	
Section 1 - Power Train	Passed	
Section 2 - Suspension	Repaired (same day)	REPLACED AXLE 3 SHOCKS.
Section 3 - Brake System	Passed	
Section 3A - Air Brakes	Repaired (same day)	REPLACED 3L BRAKE POT.
Section 3H - Hydraulic Brakes	Not Applicable	
Section 4 - Steering	Passed	
Section 5 - Instruments and Auxiliary Equipment	Passed	
Section 6 - Lamps	Passed	
Section 7 - Electrical System	Passed	
Section 8 - Frame and Body	Repaired (same day)	SECURED FENDERS.
Section 9A - Tires	Passed	
Section 9B - Wheels	Passed	
Section 10 - Coupling Devices	Passed	
Section 11 - Other Vehicle Components	Passed	

Air Brake Chamber Type, Size and Push Rod Stroke (mm) / Tire Tread Depth (mm)

Axles	Type	Size	Slack Adj.	Left	Right	Outer L	Inner L	Inner R	Outer R	Steering
1	Clamp	24	Automatic	37	37	12			12	✓
2	Clamp	30L	Automatic	40	41	6	6	6	6	
3	Clamp	30L	Automatic	41	40	8	8	8	8	

Comment: Comment:

Air Brake Camshaft Rotation (degrees) / Brake Lining/Pad (mm) / Rotor Thickness or Drum Inside Diameter (mm)

Axles	Left	Right	Lining/Pad	Left	Right	Rotor/Drum	Left	Right
1	60	60	Lining (Shoe)	17	17	Drum		
2	75	65	Lining (Shoe)	14	18	Drum		
3	55	40	Lining (Shoe)	17	18	Drum		

Comment: Comment: Comment: Air Brake Camshaft Rotation performed. Rotor Thickness or Drum Diameter not measured.

Inspection Comments:

Has this Vehicle been road tested? No Road Test Date: Road Tester:

Inspector: KRAJNC, HAYDEN Signature:

This Inspection Report was submitted to CVSE on 2026-Jul-28 02:53 PM PDT
The Inspector's signature above is certification that this vehicle has been inspected to the requirements of the Motor Vehicle Act and Regulations.

NOTICE: KEEP THIS VEHICLE INSPECTION REPORT WITH VEHICLE REGISTRATION.

The personal information collected on this form is collected under the authority of section 216 of the Motor Vehicle Act and Division 29 of the Motor Vehicle Act Regulations. It is collected for the purpose of processing this vehicle inspection and for generally administering the Vehicle Inspection Program and the National Safety Code (e.g. regulating carriers, authorized inspectors, and designated inspection facilities). If you have any questions about the collection of this information, you may contact the Sr. Manager, NSC/VIP at the Commercial Vehicle Safety Enforcement.

CVSB014
7/28/2026 2:53:33 PM PDT