

575 Wagga Road
Lavington NSW 2641
Phone: (02) 6049 5500
Email: lavingtonservice@blacklocks.com.au
Bank Account Details
BSB: 334-040
Account Number: 553 703 312
Please email all remittances to
accounts@blacklocks.com.au



A Division of Frolad Pty. Ltd. LMD 16586 LMCT 7494
ACN 080 868 953 ABN 96 603 230 104

www.blacklocks.com.au

190 Melbourne Road
Wodonga Vic 3690
Phone: (02) 6057 8777
Email: service@blacklocks.com.au

Service TAX Invoice		Page 1 of 2		Doc #: ISCST428707				
Customer No.	Customer Name & Address		1015	Colour white/grey	Team Service			
Doc. Date 20/02/20			Year / Make / Model 16/ISUZU/FSD 140/120-260 LWB (AW)		Tag No.			
Reg. No. 04217P			Model No. FH-FSDCG-D28	Carline FH SERIES	Eng./Trans. 6HK1/M			
Stock No.			Chassis No. JALFSR347G7000004	Kilometres 64061	Prod. Date 12/10/16	Orig. Del. Date		
Purchase Order No.			Driver	Contract No.	Contract Name	Contract Exp. Kms	Exp. Date	
☐ CASH ☐ CHEQUE ☐ CREDIT CARD ☐ ACCOUNT	Home Phone	Business Phone	Terms Cash	Selling Dealer	Delivery Kms.	Delivery Date 12/10/16	Warr. Exp. Date 11/10/19	
	Vehicle ID. JALFSR347G7000046	Engine No.	Date & Time Promised 20/02/20 06:00pm	Time Received 08:00am	Quote Price	Air Y	Pwr Y	Turb Y

Labour	Operation	Description	Units	Amount
--------	-----------	-------------	-------	--------

Job#1	50ISZZ0012	FR-FS 6HK1 60k Svc	Tech(s): 1102	1040.00
-------	------------	--------------------	---------------	---------

Carry out service as per Isuzu 60,000km schedule
Check and adjust brakes
Service due on KM or time
Completed service as per Isuzu schedule
Roller brake test - passed

IS8979125310	GASKET DRAIN P	1	2.19
IS8943910494	ELEMENT OIL FI	1	76.97
IS8976063180	ELEMENT KIT PCV	1	19.34
IS8980924811	ELEMENT FUEL FILTER	1	93.29
IS92956471	FILTER FUEL,2 MICRON	1	24.41
IS8976038890	GASKET COOLER	1	51.88
IS8976001670	GASKET EGR PIP	1	16.05
IS8943913790	GASKET HD TO COVER	1	42.04
IS92956076	ISUZU DOT 4 - 500ML	1	9.20
NGA90320-1	W/SCREEN WASHER FL	1	1.67
IS8980714210	FILTER ACL-OUTER	1	132.47
IS8980714220	FILTER ACL-INNER	1	81.43

Petrol, Oils, Lubricants and Supplies	Amount
---------------------------------------	--------

Job# 1	Isuzu NextGen Plus	120.75
Job# 1	Castrol Axle 85W/140	53.42
Job# 1	Isuzu S-Trans	77.29
Job# 1	Castrol PHD grease	9.38

<<< Total For Job 1 >>> 1851.78

Misc: WSHOP	Workshop Consumables	31.20
Misc: ENVIR	Workshop/Admin Chrg/Enviro	20.80
Misc: CENT	ROUNDING	-0.01

Recommendations

Front tyres show signs of under inflation wear.

575 Wagga Road
Lavington NSW 2641
Phone: (02) 6049 5500
Email: lavingtonservice@blacklocks.com.au

Bank Account Details
BSB: 334-040
Account Number: 553 703 312

Please email all remittances to
accounts@blacklocks.com.au



A Division of Frolad Pty. Ltd. LMD 16586 LMCT 7494
ACN 080 868 953 ABN 96 603 230 104

www.blacklocks.com.au

190 Melbourne Road
Wodonga Vic 3690
Phone: (02) 6057 8777
Email: service@blacklocks.com.au

Service TAX Invoice				Page 2 of 2		Doc #: ISCST428707			
Customer No.				Advisor	1015	Colour	white/grey	Team	Service
Doc. Date	20/02/20			Year / Make / Model	16/ISUZU/FSD 140/120-260 LWB (AW)				Tag No.
Reg. No.	04217P			Model No.	FH-FSDCG-D28		Carline	FH SERIES	
Stock No.				Chassis No.	JALFSR347G7000004		Kilometres	64061	Prod. Date
								12/10/16	Orig. Del. Date
Purchase Order No.	Driver	Contract No.		Contract Name	Contract Exp. Kms		Exp. Date		
☐ CASH	Home Phone	Business Phone	Terms	Selling Dealer	Delivery Kms.		Delivery Date	Warr. Exp. Date	
☐ CHEQUE			Cash				12/10/16	11/10/19	
☐ CREDIT CARD	Vehicle ID.	Engine No.		Date & Time Promised	Time Received		Quote Price	Air	Pwr
☐ ACCOUNT	JALFSR347G7000046			20/02/20 06:00pm	08:00am			Y	Y

Total Labour 1040.00
Total Parts 550.94
Total POL 260.84
Total Sublet 0.00
Total Misc 51.99

Total Tax 190.38

Total Invoice 2094.15

TOTAL AMOUNT INCLUDING GST

575 Wagga Road
Lavington NSW 2641
Phone: (02) 6049 5500
Email: lavingtonservice@blacklocks.com.au
Bank Account Details
BSB: 334-040
Account Number: 553 703 312
Please email all remittances to
accounts@blacklocks.com.au



A Division of Frolad Pty. Ltd. LMD 16586 LMC7 7494
ACN 080 868 953 ABN 96 603 230 104

www.blacklocks.com.au

190 Melbourne Road
Wodonga Vic 3690
Phone: (02) 6057 8777
Email: service@blacklocks.com.au

Service TAX Invoice				Page 1 of 2		Doc #: ISCST472003				
Customer No.	Customer Name & Address			Advisor	1186	Colour	white/grey		Team	Service
Doc. Date				Year / Make / Model	16/ISUZU/FSD 140/120-260 LWB (AW)				Tag No.	HERE
Reg. No.				Model No.	FH-FSDCG-D28				Eng./Trans.	6HK1/M
Stock No.				Chassis No.	JALFSR347G7000004		Kilometres	93790	Prod. Date	12/10/16
Purchase Order No.	Driver	Contract No.		Contract Name	Contract Exp. Kms		Exp. Date			
☐ CASH	Home Phone	Business Phone	Terms	Selling Dealer	Delivery Kms.		Delivery Date		Warr. Exp. Date	
☐ CHEQUE			Cash				12/10/16		11/10/19	
☐ CREDIT CARD	Vehicle ID.	Engine No.		Date & Time Promised	Time Received		Quote Price		Air	Pwr
☐ ACCOUNT	JALFSR347G7000046			07/12/21	04:00pm		08:00am		Y	Y

Labour	Operation	Description	Units	Amount
--------	-----------	-------------	-------	--------

Job#1	50ISZZ0010	FR-FS 6HK1 20k Svc	Tech(s): 936	520.00
-------	------------	--------------------	--------------	--------

Carry out Isuzu service as per Isuzu 20,000km schedule
Check and adjust brakes
Service due on KM or time
Completed service as per Isuzu schedule
Roller brake test - passed

IS1096230570	GASKET PLUG,OIL DRAIN	1	3.94
IS8943910494	ELEMENT OIL FI	1	78.50
IS8976063181	ELEMENT KIT PCV	1	32.78
IS92956471	FILTER FUEL,2 MICRON	1	26.32
IS8980924811	ELEMENT FUEL FILTER	1	97.54
NGA90320-1	W/SCREEN WASHER FL	1	1.69
NGITWRPW710	8MMX710MM WIPER BL	2	9.22

Petrol, Oils, Lubricants and Supplies			Amount
---------------------------------------	--	--	--------

Job# 1	Isuzu NextGen Plus	155.25
Job# 1	Castrol PHD grease	10.16
	Misc: SCAN	DIAGNOSTIC SCAN TOOL FEE.
		40.00

<<< Total For Job 1 >>> 975.40

Job#2	52ISZZ0002	Loan Car	Tech(s): 1226	No Charge
-------	------------	----------	---------------	-----------

Loan Car, Please fill and sign paper work
Loan car Insurance accepted - YES

Misc: TLCER	Loan Vehicle Insurance Excess	22.00
-------------	-------------------------------	-------

<<< Total For Job 2 >>> 22.00

Job#3	80ISADDWORK5	Shackle Pins	Tech(s): 936	780.00
-------	--------------	--------------	--------------	--------

Replace worn shackle pins and bushes

575 Wagga Road
Lavington NSW 2641
Phone: (02) 6049 5500
Email: lavingtonservice@blacklocks.com.au
Bank Account Details
BSB: 334-040
Account Number: 553 703 312
Please email all remittances to
accounts@blacklocks.com.au



A Division of Frolad Pty. Ltd. LMD 16586 LMCT 7494
ACN 080 868 953 ABN 96 603 230 104

www.blacklocks.com.au

190 Melbourne Road
Wodonga Vic 3690
Phone: (02) 6057 8777
Email: service@blacklocks.com.au

Service TAX Invoice				Page 2 of 2		Doc #: ISCST472003					
Customer No.	Customer Name & Address			Advisor	1186	Colour	white/grey		Team	Service	
Doc. Date	07/12/21			Year / Make / Model	16/ISUZU/FSD 140/120-260 LWB (AW)					Tag No.	HERE
Reg. No.	04217P			Model No.	FH-FSDCG-D28		Carline		FH SERIES		
Stock No.				Chassis No.	JALFSR347G7000004		Kilometres	93790	Prod. Date	12/10/16	
Purchase Order No.	Driver	Contract No.		Contract Name		Contract Exp. Kms		Exp. Date			
☐ CASH	Home Phone	Business Phone	Terms	Selling Dealer		Delivery Kms.		Delivery Date		Warr. Exp. Date	
☐ CHEQUE			Cash					12/10/16		11/10/19	
☐ CREDIT CARD	Vehicle ID.	Engine No.		Date & Time Promised		Time Received		Quote Price		Air	
☐ ACCOUNT	JALFSR347G7000046			07/12/21 04:00pm		08:00am				Pwr	
										Turb	
										Y	
										Y	
										Y	

Put vehicle on chassis stands
Removed bushes and pins
Right hand top bushes were extremely hard to get out
Spent extra time removing
Replaced with new pins and bushes
Removed vehicle from chassis stand
Road test- okay

IS8983742800	WASHER LK PIN	4	37.44
IS8983742810	PIN FRT SPR-FRT	4	95.60
IS8980821760	BUSHING SHACKLE,RR SPR	4	69.68

<<< Total For Job 3 >>>

982.72

Misc: WSHOP	Workshop Consumables	39.00
Misc: CENT	ROUNDING	0.02
Misc: ENVIR	Workshop/Admin Chrg/Enviro	26.00

Comments

Jack 0429 049 802

Recommendations

UNROADWORTHY
936 Windscreen has a large crack
REQUIRES URGENT ATTENTION
936 Rear tyres are worn to the treadwear indicators- requires
replacing before next service

Total Labour	1300.00
Total Parts	452.71
Total POL	165.41
Total Sublet	0.00
Total Misc	127.02

Total Tax	204.51
-----------	--------

TOTAL AMOUNT INCLUDING GST

Total Invoice	2249.65
---------------	---------

BLACKLOCKS TRUCK CENTRE

Frolad Pty Ltd ATF Tony White Albury Trust T/A's Blacklocks Truck Centre
ACN 080 868 953 | ABN 96 603 230 104 | LMCT 7494

190 Melbourne Road Wodonga VIC 3690
Phone: (02) 6057 8777
Email: truckservice@blacklocks.com.au
Website: www.blacklockstrucks.com.au



Bank Account Details
BSB: 334-040
Account Number: 553 703 312
Account Name: Blacklocks

Please email all remittances to:
accounts@blacklocks.com.au

Warranty Claim				Page 1 of 3		Doc #: ISWST542400			
Customer No. [REDACTED]	Customer Name & Address [REDACTED]			Advisor [REDACTED] 1308	Colour white/grey	Team Service			
Doc. Date 11/07/24	[REDACTED]			Year / Make / Model 16/ISUZU/FSD 140/120-260 LWB (AW)			Tag No. HERE		
Reg. No. 04217P	[REDACTED]			Model No. FH-FSDCG-D28	Carline FH SERIES		Eng./Trans. 6HK1/M		
Stock No. [REDACTED]	[REDACTED]			Chassis No. JALFSR347G7000004	Kilometres 140542	Prod. Date 12/10/16	Orig. Del. Date		
Purchase Order No.	Driver [REDACTED]	Contract No.		Contract Name		Contract Exp. Kms	Exp. Date		
☐ CASH ☐ CHEQUE ☐ CREDIT CARD ☐ ACCOUNT	Home Phone	Business Phone	Terms Cash	Selling Dealer		Delivery Kms.	Delivery Date 12/10/16	Warr. Exp. Date 11/10/19	
	Vehicle ID. JALFSR347G7000046	Engine No.		Date & Time Promised 19/07/24 04:00pm	Time Received 08:00am	Quote Price	Air Y	Pwr Y	Turb Y

Labour	Operation	Description	Units	Amount
--------	-----------	-------------	-------	--------

Job# 2	58ISZZ0010	Transmission	Tech(s): 1048	3809.38
--------	------------	--------------	---------------	---------

Customer concern vehicle jumping out of 6th gear- investigate and report

internal fault in gearbox

took vehicle for a test drive to confirm customer concern
inspected gear oil viscosity - bad quality
drained gear oil and topped up with new oil
performed download
recommend to remove gearbox and inspect gearing and shift housing
Vehicle jumping out of 6th
internal fault in gearbox
took vehicle for test drive found jumping out of 6th
performed download
recommend removing gearbox and inspect gearing and shift housing
inspected gear shifting cable and selector cable
inspected gear oil viscosity, bad gear oil thicker.
drained trans gear oil and put new gear oil
drove the vehicle to check gear position. 6th gear needs more diagnosing
disassembled gearbox, inspected all components
Removed driveshaft
removed transmission
removed shift housing
removed rear housing and intermediate housing
inspected 5th and 6th synchros
found built up of burnt oil
disassemble transmission completely found metal in oil, hardening coming off bearings and gearing build up of particles in oil grooves
ordered parts
cleaned all housings
reassembled trans with new parts
installed trans
filled with oil
test drove vehicle

Job performed by technician 1048 on 13/06/24 Between 11.95 and 13.00 (1.05 Hour)
Job performed by technician 1048 on 13/06/24 Between 13.50 and 13.73 (0.23 Hour)
Job performed by technician 1401 on 14/06/24 Between 8.20 and 9.38 (1.18 Hours)
Job performed by technician 1009 on 14/06/24 Between 9.28 and 9.96 (0.68 Hours)

BLACKLOCKS TRUCK CENTRE

Frolad Pty Ltd ATF Tony White Albury Trust T/A's Blacklocks Truck Centre
ACN 080 868 953 | ABN 96 603 230 104 | LMCT 7494

190 Melbourne Road Wodonga VIC 3690
Phone: (02) 6057 8777
Email: truckservice@blacklocks.com.au
Website: www.blacklockstrucks.com.au



Bank Account Details
BSB: 334-040
Account Number: 553 703 312
Account Name: Blacklocks

Please email all remittances to:
accounts@blacklocks.com.au

Warranty Claim				Page 2 of 3		Doc #: ISWST542400						
Customer No.	Customer Name & Address			Advisor	1308	Colour	white/grey		Team	Service		
Doc. Date	11/07/24			Year / Make / Model			16/ISUZU/FSD 140/120-260 LWB (AW)		Tag No.		HERE	
Reg. No.	04217P			Model No.		FH-FSDCG-D28		Carline		Eng./Trans.		6HK1/M
Stock No.				Chassis No.		JALFSR347G7000004		Kilometres	140542	Prod. Date	12/10/16	Orig. Del. Date
Purchase Order No.	Driver	Contract No.		Contract Name		Contract Exp. Kms		Exp. Date				
☐ CASH ☐ CHEQUE ☐ CREDIT CARD ☐ ACCOUNT	Home Phone	Business Phone	Terms	Selling Dealer		Delivery Kms.		Delivery Date		Warr. Exp. Date		
	Vehicle ID.	Engine No.		Date & Time Promised		Time Received		Quote Price		Air	Pwr	Turb
	JALFSR347G7000046			19/07/24 04:00pm		08:00am				Y	Y	Y

Job performed by technician 1048 on 08/07/24 Between 8.38 and 8.38 (0 Hours)
Job performed by technician 1009 on 10/07/24 Between 16.16 and 16.26 (0.1 Hours)
Job performed by technician 1009 on 10/07/24 Between 15.66 and 16.16 (0.5 Hours)
Job performed by technician 1048 on 10/07/24 Between 8.03 and 9.16 (1.13 Hours)
Job performed by technician 1048 on 09/07/24 Between 13.50 and 16.13 (2.63 Hour)
Job performed by technician 1048 on 09/07/24 Between 9.58 and 13.00 (3.42 Hours)
Job performed by technician 1048 on 08/07/24 Between 13.78 and 15.68 (1.9 Hours)
Job performed by technician 1048 on 08/07/24 Between 8.38 and 10.93 (2.55 Hours)
Job performed by technician 1048 on 05/07/24 Between 13.50 and 16.11 (2.61 Hour)
Job performed by technician 1048 on 05/07/24 Between 8.00 and 13.00 (5 Hours)
Job performed by technician 1048 on 05/07/24 Between 7.98 and 8.00 (0.02 Hours)
Job performed by technician 1048 on 04/07/24 Between 13.50 and 13.58 (0.08 Hour)
Job performed by technician 1048 on 04/07/24 Between 11.15 and 13.00 (1.85 Hour)
Job performed by technician 1048 on 04/07/24 Between 8.05 and 8.81 (0.76 Hours)
Job performed by technician 1048 on 03/07/24 Between 13.50 and 16.15 (2.65 Hour)
Job performed by technician 1048 on 03/07/24 Between 12.93 and 13.00 (0.07 Hour)
Job performed by technician 1048 on 25/06/24 Between 8.15 and 11.56 (3.41 Hours)
Job performed by technician 1048 on 24/06/24 Between 13.50 and 16.11 (2.61 Hour)
Job performed by technician 1048 on 24/06/24 Between 8.01 and 13.00 (4.99 Hours)

Claim # T542400

Total - Labour

3809.38

Parts	Qty	Number	Description	Unit Cost	Ext. Cost	Unit Price	Amount
Job# 2	1	IS92958187	MZW COUNTER MEASURE KIT	2228.61	2228.61	2507.19	2507.19
Job# 2	1	IS8980056330	WASHER THRUST-REV IDLE	19.71	19.71	22.17	22.17
Job# 2	1	NGINF	FREIGHT CHARGE	1.00	1.00	17.25	17.25
Job# 2	1	IS8972531110	BEARING NEEDLE,4TH	20.66	20.66	23.24	23.24
Job# 2	4	IS8972531100	BEARING NEEDLE,MAINSHAFT	11.92	47.68	13.25	53.00
Job# 2	1	IS8972413061	RING BLOCK,2ND & 3RD	171.91	171.91	196.99	196.99
Job# 2	1	IS8973779760	BEARING COUNTER MIDDLE	68.30	68.30	77.48	77.48
Job# 2	2	IS8972413061	RING BLOCK,2ND & 3RD	180.77	361.54	196.99	393.98
Job# 2	2	IS8972413061	RING BLOCK,2ND & 3RD	180.77	361.54	196.99	393.98
Job# 2	1	IS8972530991	BEARING NEEDLE,MAINSHAFT	36.80	36.80	42.33	42.33
Job# 2	1	IS8973779700	BEARING OUTPUT SHAFT FRT	68.87	68.87	77.79	77.79
Job# 2	1	IS1098110170	BEARING NEEDLE,IDLER	15.58	15.58	17.53	17.53
Job# 2	1	IS8973779770	BEARING OUTPUT SHAFT RR	80.44	80.44	90.87	90.87
Job# 2	1	IS8973779500	BEARING INPUT SHAFT	91.27	91.27	103.53	103.53
Job# 2	1	IS8981015050	BEARING 6TH	17.15	17.15	19.29	19.29
Job# 2	1	IS8981422650	BEARING 6TH	10.32	10.32	11.61	11.61
Job# 2	1	IS8973779530	BEARING MAINSHAFT RR	172.55	172.55	195.74	195.74
Job# 2	1	IS8980093740	SHIM COUNTER SHAFT BRG	0.01	0.01	9.21	9.21
Job# 2	1	IS8983525120	SHIM OUTPUT SHAFT	4.27	4.27	4.32	4.32

BLACKLOCKS TRUCK CENTRE

Frolad Pty Ltd ATF Tony White Albury Trust T/A's Blacklocks Truck Centre
ACN 080 868 953 | ABN 96 603 230 104 | LMCT 7494

190 Melbourne Road Wodonga VIC 3690
Phone: (02) 6057 8777
Email: truckservice@blacklocks.com.au
Website: www.blacklockstrucks.com.au

ISUZU
TRUCKS

BLACKLOCKS
TRUCK CENTRE

IVECO

Bank Account Details
BSB: 334-040
Account Number: 553 703 312
Account Name: Blacklocks

Please email all remittances to:
accounts@blacklocks.com.au

Warranty Claim				Page 3 of 3		Doc #: ISWST542400					
Customer No.				Advisor	1308	Colour	white/grey		Team	Service	
Doc. Date	11/07/24			Year / Make / Model				16/ISUZU/FSD 140/120-260 LWB (AW)		Tag No.	HERE
Reg. No.	04217P			Model No.		FH-FSDCG-D28		Carline		FH SERIES	
Stock No.				Chassis No.		JALFSR347G7000004		Kilometres	140542	Prod. Date	12/10/16
Purchase Order No.	Driver		Contract No.		Contract Name		Contract Exp. Kms		Exp. Date		
☐ CASH	Home Phone		Business Phone		Terms		Selling Dealer		Delivery Kms.		Warr. Exp. Date
☐ CHEQUE					Cash				12/10/16		11/10/19
☐ CREDIT CARD	Vehicle ID.		Engine No.		Date & Time Promised		Time Received		Quote Price		Air
☐ ACCOUNT	JALFSR347G7000046				19/07/24 04:00pm		08:00am				Pwr
											Turb
											Y
											Y
											Y

Total - Parts 4257.50

Total - POL 0.00

Recommendations

1048- recommend to replace cracked windscreen
1048- LHS rear axle shock absorber leaking- recommend to replace

R/O Tax 0.00
R/O Totals 8066.88

Claim #	Labour	Parts	Sub - Lab	Sub - Part	POL	Misc.	Tax	Total
T542400	3809.38	4257.50	0.00	0.00	0.00	0.00	0.00	8066.88
Total	3809.38	4257.50	0.00	0.00	0.00	0.00	0.00	8066.88

Authorised by