Regency Park Warehouse

Inspection Details - All Details

Service Report

ISP-438982

Pages: 4
Generated: 25/05/2026 3:13:49 PM

Inspection Details - Service Report

Inspection Status	Location	Description
Complete		M40 3467 Hour Service

Subcontractor Details

Subcontractor
Outside Ideas CLC Pty Ltd

Associated Equipment

Property	Value
Equipment Type	Track Loader
Unique Identifier	
Make	M40: CAT Track Loader
Model	259D
Registration / Plant Number	S26SGB

Attendees

Name	Company	Position	Signature
David Wieloch	Outside Ideas	Service Manager	

Checklists

Cabin Checks

Windows, Wipers, Wiper Fluids	Good
Seat, Seat belt	Good
Controls, Pedals, Levers, switches	Good
Operators Manual	Good
UHF	Good
Radio	Good

Lights	Good
Revolving Light	Good
Reverse Alarm	Good
Horn	Good
Fire Extinguisher	Good
Cab Cleanness	Good
A/C	Good
Emergency Stop Switch	Good
Battery Isolator	Good

Engine & Running Gear

Engine Oil	Changed engine oil and oil filter
Check Coolant	Good
Radiator	Cleaned
Air Filter	Changed
A/C Filters	Changed
Fuel Filter	Changed
Check Hydraulic Oil	Good
Hyd filter	Changed
Drive motor oil	Changed

Body Checks

Body, Guards, Handles	Good
Damages	Good

Boom	Good
Greased	Good
Grease Nipples	Good
Bushes, Pins	Good
Buckets	Good
Track Condition	Good
Hydraulic Hoses / Pipes	Good
Burst Protection	Good

Sign Off

Name & Signature		Signed by: David Wieloch

Other Observations

Ref	Classification	Responsible	Priority	Due Date	Date Closed

Outcomes

Metric	Count	%
Negative Observations	0	0%
Positive Observations	0	0%
Neutral Observations	0	0%
Open Observations	0	0%
Closed Observations	0	0%

Focus For Next Service Report
Next Service due 3650 Hours