



Regency Park Warehouse

Inspection Details - All Details

Service Report

ISP-193264

Pages: 4

Generated: 30/06/2025 2:46:47 PM

Inspection Details - Service Report		
Inspection Status	Location	Description
Complete		M52 5473 Hour Service

Subcontractor Details	
Subcontractor	
Outside Ideas CLC Pty Ltd	

Associated Equipment	
Property	Value
Equipment Type	Excavator / Earth Moving Equipment
Unique Identifier	
Make	M52: CAT Excavator
Model	308E
Registration / Plant Number	S06SGZ

Attendees			
Name	Company	Position	Signature
David Wieloch	Outside Ideas	Service Manager	

Checklists	
Cabin Checks	
Windows, Wipers, Wiper Fluids	Good
Seat, Seat belt	Good
Controls, Pedals, Levers, switches	Good
Operators Manual	Behind Seat
UHF	Good
Radio	Good

Lights	Good
Revolving Light	Good
Reverse Alarm	Good
Horn	Good
Fire Extinguisher	Good
Cab Cleaness	Good
A/C	Good
Emergency Stop Switch	Good
Battery Isolator	Good

Engine & Running Gear

Engine Oil	Changed oil and oil filter
Check Coolant	Good
Radiator	Cleaned
Air Filter	Changed
A/C Filters	Changed
Fuel Filter	Changed
Check Hydraulic Oil	Good
Hyd filter	Changed
Drive motor oil	Changed

Body Checks

Body, Guards, Handles	Good
Damages	Good

Boom	Good
Greased	YES
Grease Nipples	Good
Bushes, Pins	Good
Buckets	Good
Track Condition	Good
Hydraulic Hoses / Pipes	Good
Burst Protection	Good

Sign Off

Name & Signature	DW Signed by: David Wieloch
------------------	--

Other Observations					
Ref	Classification	Responsible	Priority	Due Date	Date Closed

Outcomes		
Metric	Count	%
Negative Observations	0	0%
Positive Observations	0	0%
Neutral Observations	0	0%
Open Observations	0	0%
Closed Observations	0	0%

Focus For Next Service Report

Next Service Due at 5750 Hours