

H06-2A13



SPILAK
TANK TRUCK SERVICE
Ph. 780-849-3031

911-6th St.
Slave Lake, AB T0G 2A0

Hose Test Certificate

Hose Type:

Original Hose Serial Number

load

none

Test Information

Date of Testing:	aug. 29, 2025
Hose Working Pressure:	150 PSI
Hose Test Pressure:	300 PSI
Duration (mins):	5 MINUTES

Material Information on the hose band

Hose Identifier:	4-101
Size:	4"
Length:	10'
Color:	green

Hose Visual Inspections

☒	No visible damage to the reinforcements
☒	No kinked, flattened or permanently deformed wire brades
☒	No soft spots or bulging while under pressure
☒	No damaged, slipping or excessively worn hose couplers
☒	No loose or missing coupling assembly (Camlocks)
☒	The Serial or identification number an Hose Assembly Working Pressure (HAWP) are readable.
☒	O ring replaced

CONTINUITY TEST




PASS



FAIL

Timed Pressure Test Results



Hose Pressure Times starts after the hose has been filled and at pressure

Romulo Manilay

Test Technician (Print)

Romulo Manilay

Test Technician Signature

☒ Pass
☐ Fail

Supervisor Signature

This hose meets all requirements as per B620-14 7.2.0

H06-2A/B



SPILAK
TANK TRUCK SERVICE
Ph. 780-849-3031

911-6th St.
Slave Lake, AB T0G 2A0

Hose Test Certificate

Hose Type:

load hose

Original Hose Serial Number

None

Test Information

Date of Testing:	Aug. 29, 2025
Hose Working Pressure:	150 PSI
Hose Test Pressure:	300 PSI
Duration (mins):	5 MINUTES

Material Information on the hose band

Hose Identifier:	4-0010
Size:	4"
Length:	10'
Color:	black

Hose Visual Inspections

☒	No visible damage to the reinforcements
☒	No kinked, flattened or permanently deformed wire brades
☒	No soft spots or bulging while under pressure
☒	No damaged, slipping or excessively worn hose couplers
☒	No loose or missing coupling assembly (Camlocks)
☒	The Serial or identification number an Hose Assembly Working Pressure (HAWP) are readable.
☒	O ring replaced

CONTINUITY TEST




PASS



FAIL

Timed Pressure Test Results



Hose Pressure Times starts after the hose has been filled and at pressure

Romulo Manilang

Test Technician (Print)

Romulo Manilang

Test Technician Signature



Pass

Fail

Supervisor Signature

This hose meets all requirements as per B620-14 7.2.0

H06-2A13



SPILAK
TANK TRUCK SERVICE
Ph. 780-849-3031

911-6th St.
Slave Lake, AB T0G 2A0

Hose Test Certificate

Hose Type:

Original Hose Serial Number

load hose

1011

Test Information

Date of Testing:	Aug. 29, 2025
Hose Working Pressure:	150 PSI
Hose Test Pressure:	300 PSI
Duration (mins):	5 MINUTES

Material Information on the hose band

Hose Identifier:	2-008
Size:	2"
Length:	8'
Color:	Yellow

Hose Visual Inspections

☒	No visible damage to the reinforcements
☒	No kinked, flattened or permanently deformed wire brades
☒	No soft spots or bulging while under pressure
☒	No damaged, slipping or excessively worn hose couplers
☒	No loose or missing coupling assembly (Camlocks)
☒	The Serial or identification number an Hose Assembly Working Pressure (HAWP) are readable.
☒	O ring replaced

CONTINUITY TEST




PASS



FAIL

Timed Pressure Test Results



Hose Pressure Times starts after the hose has been filled and at pressure

Romulo Manilang

Test Technician (Print)

Rm

Test Technician Signature



Pass

Fail

Supervisor Signature

This hose meets all requirements as per B620-14 7.2.0

H06-2 A13



SPILAK
TANK TRUCK SERVICE
Ph. 780-849-3031

Hose Test Certificate

911-6th St.
Slave Lake, AB T0G 2A0

Hose Type: load hose
Original Hose Serial Number none

Test Information

Date of Testing:	Aug. 29, 2025
Hose Working Pressure:	100 PSI
Hose Test Pressure:	150 PSI
Duration (mins):	5 MINUTES

Material Information on the hose band


Hose Identifier:	3-018
Size:	3"
Length:	18'
Color:	bWe

Hose Visual Inspections

☒	No visible damage to the reinforcements
☒	No kinked, flattened or permanently deformed wire brades
☒	No soft spots or bulging while under pressure
☒	No damaged, slipping or excessively worn hose couplers
☒	No loose or missing coupling assembly (Camlocks)
☒	The Serial or identification number an Hose Assembly Working Pressure (HAWP) are readable.
☒	O ring replaced

CONTINUITY TEST	<u>no ground cable</u>	☒	PASS
		☒	FAIL

Timed Pressure Test Results



Hose Pressure Times starts after the hose has been filled and at pressure

D6 mulo man, my
Test Technician (Print)

[Signature]
Test Technician Signature

☒ Pass
☐ Fail

[Signature]
Supervisor Signature

This hose meets all requirements as per B620-14 7.2.0

H06-2A1B

M78-1



SPILAK
TANK TRUCK SERVICE
Ph. 780-849-3031

911-6th St.

Slave Lake, AB T0G 2A0

Hose Test Certificate

Hose Type:

Original Hose Serial Number

road hose

none

Test Information

Date of Testing:	aug-29-2025
Hose Working Pressure:	100 PSI
Hose Test Pressure:	150 PSI
Duration (mins):	5 MINUTES

Material Information on the hose band

Hose Identifier:	3-0118
Size:	3"
Length:	18'
Color:	blue

Hose Visual Inspections

☒	No visible damage to the reinforcements
☒	No kinked, flattened or permanently deformed wire brades
☒	No soft spots or bulging while under pressure
☒	No damaged, slipping or excessively worn hose couplers
☒	No loose or missing coupling assembly (Camlocks)
☒	The Serial or identification number an Hose Assembly Working Pressure (HAWP) are readable.
☒	O ring replaced

CONTINUITY TEST


no ground
cable

PASS



FAIL

Timed Pressure Test Results



Hose Pressure Times starts after the hose has been filled and at pressure

Romulo manilan

Test Technician (Print)

☒ Pass
☐ Fail

Supervisor Signature

Test Technician Signature

This hose meets all requirements as per B620-14 7.2.0