XA01-182

EDGE ENERGY LOGISTICS

Equipment Work Order WO- 6800

Location: LLB shop Date: Jan 2 2024

Truck/Trailer Information		
Unit #: R-52	Kilometres: 626 498	Hours: 15 890
Make: Kenworth	VIN:	Plate #:

Parts and Materials

DW 1164 LX windshield
DW 1163 LX

Description of Work Completed

Replace both broken windshield
major oil leak at hyd control
Remove hose sent it built
put hose back on and fill hyd tank
check oil leaks oil pan gasket leaks
fix air leak at air tank

add 2L of coolant
add 3L of engine oil

glue wheelchair stripping on driver side door

Completed By: Jass	Signature:	Date: 2 jan 2024
Completed By:	Signature:	Date:
Manager:	Signature:	Date:

EDGE ENERGY LOGISTICS

Equipment Work Order WO- 6730

Location: LLB Shop Date: MAR 05 2024

Truck/Trailer Information		
Unit #: R-52	Kilometres: 629 197	Hours: 16 120
Make: Kenworth	VIN:	Plate #:

Parts and Materials

1X LF14000NN
1X FF5825NN
1X 667-1440 JUNCTION BOX
1X 1051A LIGHT
1X FS 20172
4QL 15W40
1X 577.59623 LIGHT SWITCH
1X SB4411 bulb

Description of Work Completed

Repair wiring for skirt center lights.
R&R RH back up light light
~~[illegible]~~
R&R junction box under center of truck.

Complete service and 300 hr sheet

R&R one bulb in RH beacon + adjust other bulb

Grease unit + levels
Install 3 missing bolts in oil pan, retorque
All pan bolts

Completed By: Jess	Signature:	Date:
Completed By: X	Signature:	Date:
Manager:	Signature:	Date:

PACE

EDGE ENERGY LOGISTICS

Truck/Trailer 300 hr Service Inspection

Location: LLB Shop

Date: MAR05 24

Truck/Trailer Information

Unit #: R-52	Kilometers: 629 197	Hours: 16 620
Make: Kenworth	VIN:	Plate#:

Interior/ Cab		Exterior continued....		Engine continued....		Undercarriage continued....	
Windshield	✓	Reflectors/Flashers	✓	Engine Mounts	✓	Torque Arms	✓
Wipers & Washer	✓	Signal Brake Lights	✓	Water pump	✓	Underbody	✓
Instruments/Odometer	✓	Exterior lights	✓	Draglink	✓	Air Tanks & Mounts	✓
Seats	✓	Batt Connections/Mounts	✓	Drive Shaft	✓	Cam Bushing	✓
Moldings/Sunvisor	✓	Fifth Wheel/Hitch Function (Inc Bed Truck)	✓	Pitman Arm	✓	Brake Pot & Mounting	✓
Air & Electric Horn	✓	Fifth wheel airline/electrical	✓	King Pins	✓	Wheel Seals	
Interior lights	✓	**Engine Compartment**		Shocks	✓	Slack Adjustors	✓
Heater/AC Operation	✓	Check Air Filter	✓	Tie Rod & Ends	✓	Drum/Disc Condition/Thick	✓
Clutch Freeplay	✓	Change All Fluid Filters	✓	Springs, Pins & Bushings	✓	Dayton, Ears & Wedges	NA
Mirrors & Brackets	✓	Check Fluid Levels	✓	Wheel Bearings	✓	Stabilizers/Torsion bars	✓
Brake Pedal	✓	Check for Leaks	✓	**Undercarriage**		Dayton, Ears & Wedges	NA
		Engine Control/Starter	✓	Park Brake	✓		
Exterior		Air Intake System	✓	Transmission Mounts/inputs	✓	First Aid kit	✓
Doors, Hood, Cab, Fender	✓	Alt Mount, Belt & Wiring	✓	Auxiliary Transmission Mounts/inputs	✓	Backup Alarm	✓
Steps, Latches & Handles	✓	Fan, Belt & Shroud, Pulleys	✓	U-Joints & Steady Brng	✓	Fire Extinguisher	✓
Fuel Tanks & Mounts	✓	AC Mount, Belt & Cond	✓	Diff Breathers/Filters	✓	Triangles/Flares	✓
Hub Levels	✓	Air Compressor & Lines	✓	Springs & U-Bolts	✓	**Picker Cab**	
Bumpers/License Plate	✓	Exhaust Manifold	✓	Wear Pads	✓	Load Mass Indicator	
Mud Flaps	✓	Air to Air Connections	✓	Air Bags	✓	A to B Function	
Winch/Winch function	✓	Rad, Mounts and Cond	✓	Hangers	✓	Interior Light	
Air Lines & Glad Hands	✓	Power Steering Pump (fluid)	✓	Air Lines & Wiring	✓	Cab Heater	
Trailer Cord & Ends	✓	Steering Box/Column/Linkage	✓	Frame & Crossmembers	✓	Work Lights	
Tire Pressure & Wear/Tread	✓	Positive air shut off	✓			Hydraulic hoses/connection	
Headlights (Low/High)	✓	Starter Mount & Cond	✓				

☑ **Change Engine Oil and Description:** done

☑ **Lube Chassis and Drive Line:** done

Repairs Required:

Parts Needed:

☐ **Repairs Completed on Work Order#**

☐ **Service/Repair Information input into Samsara**

Mechanic: Jose	**Signature:**	**Date:** MAR 5 2024
Supervisor Acknowledgement:	**Signature:**	**Date:**

EDGE ENERGY LOGISTICS

Equipment Work Order WO- 6561

Location: LLB

Date: MAY 28/24
MAY 29/24

Truck/Trailer Information		
Unit #: R-52	Kilometres: 636896	Hours: 16632
Make:	VIN:	Plate #:

Parts and Materials

X1 973956 dust cover
X1 SPL 250-3X U JOINT
X1 HLK7046K washer fluid pump.
~~OIL 15W40 MOTOR OIL~~
x2 11R24.5
40L 15W40 SYNTHETIC
1X 170.12105 DRAIN VALVE

Description of Work Completed

INSTALL missing dust cover LH #2 3
RBR random loose bolts on rear fenders
RBR midship U JOINT, Grease U JOINT
Change engine oil and filter
R.B.R LH inside drain valve, Under step.
Repair damaged wire for LH swing out light

CHECK windshield wiper issue, Pump is siezed,
INSTALL new pump all ok.
~~TOP UP ENGINE OIL~~
CHECK levels + Grease UNIT
Tighten bolts on Grill.
Replaced RH2 Tires / torqued to 500 ftlbs
Air Tires to 100 psi Rear 110 Front

Completed By: X	Signature:	Date:
Completed By:	Signature:	Date:
Manager:	Signature:	Date: