

INVOICE# \_\_\_\_\_

DATE: July 2/24

DRIVER \_\_\_\_\_

UNIT# SD31

ENGINE HOURS: \_\_\_\_\_

PLEASE DESCRIBE ISSUES WITH TRUCK OR TRAILER

- CVIP
- Grease
- check lights → license plate light out
- check hub levels
- pull all wheels
- adjust brakes
- LH front fender rear bracket broken by dolly leg
- front cylinder weeping from top.

MECHANIC SIGNATURE: \_\_\_\_\_



# COMMERCIAL VEHICLE RECORD OF INSPECTION TRAILER, SEMI-TRAILER, C-DOLLY, CONVERTER DOLLY

The original Record of Inspection must be given to the customer regardless of whether the vehicle passes or not.

Type of Vehicle

Gross Vehicle Weight registered

Vehicle Information

VIN

Unit Number

Year

Make

Model

Odometer

SD31

Registered Owner's Name

Plate Number

Address

Postal Code

Phone Number

Drum Brakes:

Disc Brakes:

LEFT

FRONT

RIGHT

psi  
7 mm

psi  
7 mm

mm  
Drums/Rotors  
mm  
Linings/Pads  
mm  
Push Rod Travel

mm  
psi  
4 mm

psi  
3 mm

psi  
7 mm

psi  
16 mm

mm  
Drums/Rotors  
mm  
Linings/Pads  
mm  
Push Rod Travel

mm  
psi  
15 mm

psi  
15 mm

psi  
4 mm

psi  
5 mm

mm  
Drums/Rotors  
mm  
Linings/Pads  
mm  
Push Rod Travel

mm  
psi  
13 mm

psi  
13 mm

psi  
mm

psi  
mm

mm  
Drums/Rotors  
mm  
Linings/Pads  
mm  
Push Rod Travel

mm  
psi  
mm

psi  
mm

psi  
mm

psi  
mm

mm  
Drums/Rotors  
mm  
Linings/Pads  
mm  
Push Rod Travel

mm  
psi  
mm

psi  
mm

psi  
mm

psi  
mm

mm  
Drums/Rotors  
mm  
Linings/Pads  
mm  
Push Rod Travel

mm  
psi  
mm

psi  
mm

Park Brake Lining Left

mm Right

mm Trans

mm

Wheel Torque Checked

Inner

ft lbs Outer

ft lbs

INVOICE#

4823

DATE:

Oct 20 122

DRIVER

UNIT#

SD31

ENGINE HOURS:

PLEASE DESCRIBE ISSUES WITH TRUCK OR TRAILER

- #7 LH dust shield - Brake shoes - 16mm

+ #1 RH dust shield - Brake shoes - 12mm

- #2 LH dust shield - Brake shoes - 12mm

- #2 RH dust shield - Brake shoes - 13mm

- #3 LH dust shield - Brake shoes - 14mm

- #3 RH dust shield - Brake shoes - 18mm

~~Grease~~  
- Hub levels

POSTED

- #7 RH walking beam cracked both sides / loose v bolts

- #6 x-mem cracked in centre

- #8 x-mem cracked in centre

- #10 x-mem cracked in centre

MECHANIC SIGNATURE:

INVOICE# 4585

DATE: Sept. 6, 2022

DRIVER \_\_\_\_\_

UNIT# SD 31

ENGINE HOURS: \_\_\_\_\_

PLEASE DESCRIBE ISSUES WITH TRUCK OR TRAILER

- Grease + Inspect
- check hub oils
- Weld cracks on #1 axle beam @ axle
- Reset brakes
- check lights

**POSTED**

MECHANIC'S SIGNATURE: [Signature]

INVOICE# 4199

DATE: July 19, 2022

DRIVER \_\_\_\_\_

UNIT# SD 31

ENGINE HOURS: \_\_\_\_\_

**POSTED**

PLEASE DESCRIBE ISSUES WITH TRUCK OR TRAILER

- Welded crack #1 axle RH saddle for beam
- Repair L.H. front corner marker light

MECHANIC SIGNATURE: \_\_\_\_\_

*[Handwritten Signature]*

INVOICE# 4155

DATE: July 12/22

DRIVER \_\_\_\_\_

UNIT# SD31

ENGINE HOURS: \_\_\_\_\_

**POSTED**

PLEASE DESCRIBE ISSUES WITH TRUCK OR TRAILER

- Change Hydraulics
- Change wiring for controls
- Fix marker lights F/R corner
- Fix RH midship Light
- Decal unit
- install license Plate light
- new reflective tape on front.

MECHANIC SIGNATURE: \_\_\_\_\_