



Work Order: 10021

EB10-157

Description: Rental Return - Emsco	1639 Hours	Date Started: 2018-01-17
Equipment: E625 John Deere 290GLC Excavator (Thumb)	RD-2018-100 Insheet RD-2018-218 Outsheet	
Serial#: 1FF290GXCFD706467		

Segment: 1 Parts

302L-Diesel Fuel (2.00ea)

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
546	01/19/18	EMParts	H3-24V-70W H3 24V 70W Halogen Bulb		EA	1.000	3.66	3.66
						Labour Total	0.00	
						Parts Total	3.66	
						Miscellaneous Total	0.00	

Segment: 2 350 Hour Service

350 Hour Service (1500ea)

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
547	01/19/18	EMParts	4632689 Filter-Cab Air 4S00686		EA	1.000	87.28	87.28
548	01/19/18	EMParts	AT300487 Filter-Air Primary		EA	1.000	72.81	72.81
549	01/19/18	EMParts	AT314583 Filter-Air Secondary		EA	1.000	60.32	60.32
550	01/19/18	EMParts	AT365870 Filter-Fuel / Water Separator		EA	1.000	100.45	100.45
551	01/19/18	EMParts	FYA00001490 Filter-Cab Air		EA	1.000	41.47	41.47
552	01/19/18	EMParts	RE522878 Filter-Fuel		EA	1.000	49.36	49.36
553	01/19/18	EMParts	RE539279 Filter-Oil		EA	1.000	20.35	20.35
554	01/19/18	EMParts	RE541922 Filter-Fuel / Water Separator		EA	1.000	56.06	56.06
						Labour Total	0.00	
						Parts Total	488.10	
						Miscellaneous Total	0.00	

Segment: 3 R&R Tool Box Light Bulb

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
545	01/19/18	EMTime	Employee: 1577 Dylan Grant		HRS	0.500		
						Labour Total	0.50	
						Parts Total	0.00	
						Miscellaneous Total	0.00	

Segment: 4 Standard Wash

Standard Wash (750.00ea)



Work Order: 10021

Labour Total	0.50
Parts Total	491.76
Miscellaneous Total	0.00

Description: Lock out switch and Repairs	1639 Hours	Date Started: 2018-02-13
Equipment: E625 John Deere 290GLC Excavator (Thumb)	RD-2018-100 Insheet RD-2018-218 Outsheet	
Serial#: 1FF290GXCFD706467		

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
253	02/13/18	EMParts	24505 Lock-Out Lever Kit		EA	1.000	8.21	8.21
254	02/13/18	EMParts	2484 Master Disconnect Switch		EA	1.000	49.03	49.03

Labour Total	0.00
Parts Total	57.24
Miscellaneous Total	0.00

Segment: 2 Insheet Inspection

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
367	07/17/18	EMTime	Employee: 1577 Dylan Grant		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Install Master Disconnect Switch

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
368	07/17/18	EMTime	Employee: 1577 Dylan Grant		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 Install GCS Decals

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
369	07/17/18	EMTime	Employee: 1577 Dylan Grant		HRS	1.000		



Work Order: 10036

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 Adjust A/C Belt

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
370	07/17/18	EMTime	Employee: 1577 Dylan Grant		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 6 Tighten Suction Coupler Clamps

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
371	07/17/18	EMTime	Employee: 1577 Dylan Grant		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 7 Inspect Thumb Cylinder, Q/A and Shim

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
372	07/17/18	EMTime	Employee: 1577 Dylan Grant		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 8 R&R Panels and Inspect

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
373	07/17/18	EMTime	Employee: 1577 Dylan Grant		HRS	1.500		

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 9 Replace E# Decals with RE#



Work Order: 10036

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
374	07/17/18	EMTime	Employee: 2205 Alexander Zavadil		HRS	0.500		
						Labour Total		0.50
						Parts Total		0.00
						Miscellaneous Total		0.00

Segment: 10 Outsheet Inspection

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
375	07/17/18	EMTime	Employee: 2205 Alexander Zavadil		HRS	2.000		
						Labour Total		2.00
						Parts Total		0.00
						Miscellaneous Total		0.00
						Labour Total		12.00
						Parts Total		57.24
						Miscellaneous Total		0.00

Description: Inspection's and Cleaning Equipment: E625 John Deere 290GLC Excavator (Thumb) Serial#: 1FF290GXCFD706467	1649 Hours RD-2018-284 Insheet EM-2018-105 Outsheet	Date Started: 2018-09-14
--	---	---------------------------------

Segment: 1 Parts and Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
221	09/14/18	EMParts	Dyed Diesel Dyed Diesel		EA	152.170	1.06	161.44
						Labour Total		0.00
						Parts Total		161.44
						Miscellaneous Total		0.00

Segment: 2 Insheet Inspection

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
222	09/14/18	EMTime	Employee: 2205 Alexander Zavadil		HRS	1.500		



Work Order: 10204

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Wash and Cleaned Cab

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
85	10/02/18	EMTime	Employee: 1074 Jack Loughed		HRS	7.000		

Labour Total	7.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 Outsheet Inspection

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
86	10/02/18	EMTime	Employee: 2205 Alexander Zavadil		HRS	1.000		

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	9.50
Parts Total	161.44
Miscellaneous Total	0.00

Description: Service 350HR	3415 Hours	Date Started: 2020-09-04
Equipment: E625 John Deere 290GLC Excavator (Thumb)	GRO#9761	
Serial#: 1FF290GXCFD706467		

Segment: 1 Parts and Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1454	09/24/20	EMParts	4632689 Filter-Cab Air(4S00686)		EA	1.000	26.80	26.80
1455	09/24/20	EMParts	5W40 Spectra 5W40		I	28.000	5.22	146.04
1456	09/24/20	EMParts	AT300487 Filter-Air Primary		EA	1.000	35.78	35.78
1457	09/24/20	EMParts	AT365870 Filter-Fuel / Water Separator		EA	1.000	73.07	73.07
1458	09/24/20	EMParts	FYA00001490 Filter-Cab Air		EA	1.000	17.59	17.59
1459	09/24/20	EMParts	RE522878 Filter-Fuel		EA	1.000	42.85	42.85
1460	09/24/20	EMParts	RE539279 Filter-Oil		EA	1.000	20.35	20.35
1461	09/24/20	EMParts	RE541922 Filter-Fuel / Water Separator		EA	1.000	44.56	44.56



Work Order: 11482

Labour Total	0.00
Parts Total	407.04
Miscellaneous Total	0.00

Segment: 2 350HR Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
166	09/02/20	PR	Employee: 1577 Dylan Grant		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	2.00
Parts Total	407.04
Miscellaneous Total	0.00

Description: Inspections and Repairs	GRO-9331/8043/8136	Date Started: 2020-09-30
Equipment: E625 John Deere 290GLC Excavator (Thumb)	3590 Hours	
Serial#: 1FF290GXCFD706467	RD-2020-277 Insheet	
	RD-2020-347 Outsheet	

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
194	10/13/20	EMParts	4632689 Filter-Cab Air(4S00686)		EA	1.000	26.88	26.88
195	10/13/20	EMParts	AL153660 Wiper Blade-19.5" Steel Frame		EA	1.000	51.66	51.66
196	10/13/20	EMParts	AT300487 Filter-Air Primary		EA	1.000	35.78	35.78
197	10/13/20	EMParts	AT497535 Mirror		EA	1.000	105.01	105.01
198	10/13/20	EMParts	FYA00001490 Filter-Cab Air		EA	1.000	23.22	23.22
199	10/13/20	EMParts	FYA00070858 Strainer-Fuel		EA	1.000	83.09	83.09
200	10/13/20	EMParts	RE522878 Filter-Fuel		EA	1.000	42.85	42.85
201	10/13/20	EMParts	RE539279 Filter-Oil		EA	1.000	20.35	20.35
202	10/13/20	EMParts	RE541922 Filter-Fuel / Water Separator		EA	1.000	44.56	44.56
383	12/16/20	EMParts	FYA00003014 Vent Louver-Round		EA	1.000	38.20	38.20
384	12/16/20	EMParts	4631659 Lock		EA	1.000	81.09	81.09
385	12/16/20	EMParts	5W40 Spectra 5W40		I	30.500	5.22	159.08
386	12/16/20	EMParts	H3-24V-70W H3 24V 70W Halogen Bulb		EA	1.000	3.75	3.75
506	10/20/20	EMParts	0101161800 Bolt-M18		EA	4.000	3.63	14.52
507	10/20/20	EMParts	HT696 Roller-Top Carrier		EA	1.000	216.60	216.60
508	10/20/20	EMParts	R89944 Seal-O-Ring		EA	1.000	6.12	6.12
509	10/20/20	EMParts	U17409 Seal-O-Ring		EA	1.000	8.91	8.91
619	10/22/20	EMParts	4255055 Track Adjustors		EA	1.000	42.56	42.56



Work Order: 11569

Labour Total	0.00
Parts Total	1,004.23
Miscellaneous Total	0.00

Segment: 2 Insheet Inspection

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2547	09/28/20	PR	Employee: 2471 Greg Royer		HRS	2.500		

Labour Total	2.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Wash and Clean Cab

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
529	12/11/20	PR	Employee: 1575 Paul Nixon		HRS	5.000		

Labour Total	5.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 350 Hour Service, Check and adjust fluids

350Hr Service- Drain engine oil, replace engine oil filter, all fuel filters (prime filters), cab air filters, engine primary air filter. Replace fuel screen. Top up washer fluid, replace window wiper blade.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
782	10/16/20	PR	Employee: 1575 Paul Nixon		HRS	3.000		
912	10/20/20	PR	Employee: 2395 Nickolas Schou		HRS	0.500		

Labour Total	3.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 T/S and Repair Coolant Leaks

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
915	10/21/20	PR	Employee: 2395 Nickolas Schou		HRS	4.500		



Work Order: 11569

Labour Total	4.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 6 Check and Adjust Track Tension

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
913	10/20/20	PR	Employee: 2395 Nickolas Schou		HRS	2.000		
916	10/21/20	PR	Employee: 2395 Nickolas Schou		HRS	1.500		
1040	10/21/20	PR	Employee: 2395 Nickolas Schou		HRS	-1.500		
1041	10/21/20	PR	Employee: 2395 Nickolas Schou		HRS	1.500		

Labour Total	3.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 7 Replace Missing Bolts, burnt out lights and Replace Mirrior

Replace left side cab mirror.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
914	10/20/20	PR	Employee: 2395 Nickolas Schou		HRS	1.000		

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 8 Decal Unit

Remove EMSCO decals, install GCS decals.

Segment: 9 Outsheet Inspection and Repairs

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
530	12/11/20	PR	Employee: 1575 Paul Nixon		HRS	2.500		

Labour Total	2.50
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	22.50
Parts Total	1,004.23
Miscellaneous Total	0.00



Work Order: 12304

Description: Pressure check/adjust	Unit on 672 in BC	Date Started: 2021-07-26
Equipment: E625 John Deere 290GLC Excavator (Thumb)	GRO-8749 No hours reported	
Serial#: 1FF290GXCFD706467		

Segment: 1 Parts

Segment: 2 Check and adjust pressures for breaker

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
968	07/22/21	PR	Employee: 2395 Nickolas Schou		HRS	0.500		
						Labour Total	0.50	
						Parts Total	0.00	
						Miscellaneous Total	0.00	
						Labour Total	0.50	
						Parts Total	0.00	
						Miscellaneous Total	0.00	

Description: 350 Hours Service	Unit at Job#672 Blue River Site BC.	Date Started: 2021-09-28
Equipment: E625 John Deere 290GLC Excavator (Thumb)	GRO-11851 3633 Hours	
Serial#: 1FF290GXCFD706467		

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
298	11/17/21	EMParts	5W40 Spectra 5W40		I	23.000	6.47	148.79
963	09/28/21	EMParts	4632689 Filter-Cab Air(4S00686)		EA	1.000	29.84	29.84
964	09/28/21	EMParts	AT300487 Filter-Air Primary		EA	1.000	29.32	29.32
965	09/28/21	EMParts	FYA00001490 Filter-Cab Air		EA	1.000	17.59	17.59
966	09/28/21	EMParts	RE522878 Filter-Fuel		EA	1.000	41.36	41.36
967	09/28/21	EMParts	RE539279 Filter-Oil		EA	1.000	30.16	30.16
968	09/28/21	EMParts	RE541922 Filter-Fuel / Water Seperator		EA	1.000	43.40	43.40
974	09/28/21	EMParts	AT314583 Filter-Air Secondary		EA	1.000	40.77	40.77
						Labour Total	0.00	
						Parts Total	381.23	
						Miscellaneous Total	0.00	

Segment: 2 250 Hour Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
-------	-------------	--------	---------	--------	----	-------	-------	------------



Work Order: 12442

47 10/01/21 PR Employee: 2611 Matthew Walter HRS 1.000

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Diagnose No start

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
48	10/01/21	PR	Employee: 2611 Matthew Walter		HRS	1.500		

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	2.50
Parts Total	381.23
Miscellaneous Total	0.00

Description: T/S and Repair no Start	Unit at BC Job Blue River	Date Started: 2021-10-14
Equipment: E625 John Deere 290GLC Excavator (Thumb)	4012 Hours.	
Serial#: 1FF290GXCFD706467		

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1961	10/15/21	AP	Vendor: 10034 Brandt Tractor Ltd. 12 5244599 Line: 1		EA	3.000	35.61	114.31
1962	10/15/21	AP	Vendor: 10034 Brandt Tractor Ltd. 12 5244599 Line: 2		EA	2.000	4.14	8.86
1963	10/15/21	AP	Vendor: 10034 Brandt Tractor Ltd. 12 5244599 Line: 3		EA	2.000	3.78	8.09
231	10/14/21	EMParts	51M7094 Seal-O-Ring		EA	1.000	4.30	4.30
232	10/14/21	EMParts	AT365870 Filter-Fuel / Water Separator		EA	1.000	73.07	73.07
233	10/14/21	EMParts	DZ111137 Control-Fuel		EA	1.000	1,046.00	1,046.00
234	10/14/21	EMParts	DZ120069 Pump-Fuel Lift		EA	1.000	104.30	104.30
235	10/14/21	EMParts	R51936 Sealing Washer		EA	2.000	5.35	10.70
236	10/14/21	EMParts	R531962 Seal-O-Ring		EA	2.000	3.30	6.60
237	10/14/21	EMParts	R63548 Seal-O-Ring		EA	2.000	3.48	6.96
238	10/14/21	EMParts	RE516335 Pressure Relief		EA	1.000	434.09	434.09
239	10/14/21	EMParts	RE516553 Seal Kit-Fuel Filter		EA	1.000	28.78	28.78
240	10/14/21	EMParts	RE522878 Filter-Fuel		EA	1.000	41.36	41.36
241	10/14/21	EMParts	RE541922 Filter-Fuel / Water Separator		EA	1.000	43.40	43.40

Labour Total	0.00
Parts Total	1,930.82
Miscellaneous Total	0.00



Work Order: 12489

Segment: 2 T/S and Repair No Start

Unit would not start. Suspected fuel issue. Replaced fuel filters and blew line to tank. Pulled off inlet fuel line to lift pump and had an adequate fuel supply. During line reinstall found fitting onto lift pump loose. Attempted to tighten and broke fitting. After getting new fitting from Kamloops and replaced with new lift, pump unit started and had no issues.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
412	10/15/21	PR	Employee: 2395 Nickolas Schou		HRS	4.500		
413	10/16/21	PR	Employee: 2395 Nickolas Schou		HRS	9.000		

Labour Total 13.50

Parts Total 0.00

Miscellaneous Total 0.00

Labour Total 13.50

Parts Total 1,930.82

Miscellaneous Total 0.00

Description: 350 Hour Service	Unit at Blue River BC Site.	Date Started: 2022-01-05
Equipment: E625 John Deere 290GLC Excavator (Thumb)	4392 Hours.	
Serial#: 1FF290GXCFD706467		

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
11	02/01/22	EMParts	AT381935 Tank-Coolant		EA	1.000	231.94	231.94
12	02/01/22	EMParts	PB100400 Cutting Edge Hardware(1"x4" PI		EA	12.000	11.93	143.16
13	02/01/22	EMParts	RE51650 Sediment Bowl(Short)		EA	1.000	102.16	102.16
14	02/01/22	EMParts	RE519696 Sensor-F/W Seperator(Short Pro		EA	1.000	202.09	202.09
15	02/01/22	EMParts	C201VV16 Coupler-Female Aux. 1"		EA	1.000	55.74	55.74
16	02/01/22	EMParts	C202VV16 Coupler-Male Aux. 1"		EA	1.000	31.92	31.92
51	01/05/22	EMParts	4632689 Filter-Cab Air(4S00686)		EA	1.000	29.14	29.14
52	01/05/22	EMParts	AT300487 Filter-Air Primary		EA	1.000	30.12	30.12
53	01/05/22	EMParts	AT365870 Filter-Fuel / Water Seperator		EA	1.000	67.68	67.68
54	01/05/22	EMParts	FYA00001490 Filter-Cab Air		EA	1.000	17.59	17.59
55	01/05/22	EMParts	RE522878 Filter-Fuel		EA	1.000	41.39	41.39
56	01/05/22	EMParts	RE539279 Filter-Oil		EA	1.000	24.57	24.57
57	01/05/22	EMParts	RE541922 Filter-Fuel / Water Seperator		EA	1.000	45.81	45.81
1042	07/28/22	EMParts	5W40 Spectra 5W40		I	22.000	5.92	130.27

Labour Total 0.00

Parts Total 1,153.58

Miscellaneous Total 0.00

Segment: 2 350 Hour Service



GCS Energy Services Ltd.

Work Order: 12712

350 Hour Service.

- Needs fuel bowl replaced

- Twist bucket cutting edge needs to be flipped.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
862	01/17/22	PR	Employee: 2611 Matthew Walter		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Repair fuel filter bowl/sensor issue

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
326	02/04/22	PR	Employee: 2611 Matthew Walter		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 Replace coolant surge tank

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
327	02/04/22	PR	Employee: 2611 Matthew Walter		HRS	1.000		

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 Repair hyd leaks

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
328	02/04/22	PR	Employee: 2611 Matthew Walter		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	4.00
Parts Total	1,153.58
Miscellaneous Total	0.00



Work Order: 13473

Description: 350 Hour Service	Unit at Emerson Site.	Date Started: 2022-09-23
Equipment: E625 John Deere 290GLC Excavator (Thumb)	Hours: 3703	
Serial#: 1FF290GXCFD706467	Next Service: 3750	
	GRO#11046	

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
39	10/05/22	EMParts	AL153660 Wiper Blade-19.5" Steel Frame		EA	1.000	57.70	57.70
40	10/05/22	EMParts	4632689 Filter-Cab Air(4S00686)		EA	1.000	30.54	30.54
41	10/05/22	EMParts	5W40 Spectra 5W40		I	22.000	7.01	154.18
42	10/05/22	EMParts	AT300487 Filter-Air Primary		EA	1.000	45.52	45.52
43	10/05/22	EMParts	AT365870 Filter-Fuel / Water Seperator		EA	1.000	65.65	65.65
44	10/05/22	EMParts	FYA00001490 Filter-Cab Air		EA	1.000	22.90	22.90
45	10/05/22	EMParts	RE522878 Filter-Fuel		EA	1.000	57.52	57.52
46	10/05/22	EMParts	RE539279 Filter-Oil		EA	1.000	30.51	30.51
47	10/05/22	EMParts	RE541922 Filter-Fuel / Water Seperator		EA	1.000	57.48	57.48
114	11/08/22	EMParts	A3 Cork-A (1 3/8"x3")		EA	75.000	1.14	85.50

Labour Total	0.00
Parts Total	607.50
Miscellaneous Total	0.00

Segment: 2 350 Hour Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
80	10/06/22	EMAdj	Scott Scrivener		HRS	3.500		

Labour Total	3.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Repair wipers

Weld Corks at Emerson Creek

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
641	11/08/22	PR	Employee: 2395 Nickolas Schou		HRS	3.000		
642	11/09/22	PR	Employee: 2395 Nickolas Schou		HRS	5.500		
78	10/06/22	EMAdj	Scott Scrivener		HRS	0.500		

Labour Total	9.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 Cork



Work Order: 13473

Labour Total	12.50
Parts Total	607.50
Miscellaneous Total	0.00

Description: 350 Hour Service Unit at Emerson Site. Date Started: 2022-12-12
 Equipment: E625 John Deere 290GLC Excavator (Thumb)
 Serial#: 1FF290GXCFD706467

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
151	12/13/22	EMParts	4632689 Filter-Cab Air(4S00686)		EA	1.000	12.22	12.22
152	12/13/22	EMParts	AT300487 Filter-Air Primary		EA	1.000	53.57	53.57
153	12/13/22	EMParts	AT365870 Filter-Fuel / Water Seperator		EA	1.000	64.34	64.34
154	12/13/22	EMParts	FYA00001490 Filter-Cab Air		EA	1.000	35.32	35.32
155	12/13/22	EMParts	RE522878 Filter-Fuel		EA	1.000	50.36	50.36
156	12/13/22	EMParts	RE539279 Filter-Oil		EA	1.000	30.51	30.51
157	12/13/22	EMParts	RE541922 Filter-Fuel / Water Seperator		EA	1.000	50.34	50.34

Labour Total	0.00
Parts Total	296.66
Miscellaneous Total	0.00

Segment: 2 350 Hour Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
879	12/15/22	PR	Employee: 2395 Nickolas Schou		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Repair Radar

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
880	12/16/22	PR	Employee: 2915 Scott Scrivener		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00



Work Order: 13733

Labour Total	2.50
Parts Total	296.66
Miscellaneous Total	0.00

Description: Repair leaks, low power Date Started: 2023-05-23
 Equipment: E625 John Deere 290GLC Excavator (Thumb)
 Serial#: 1FF290GXCFD706467

Segment: 1 Parts

Segment: 2 Repair Leaks, low power

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
241	07/06/23	PR	Employee: 3110 Callum Deditch		HRS	4.000		
969	05/18/23	PR	Employee: 3110 Callum Deditch		HRS	2.000		

Labour Total	6.00
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	6.00
Parts Total	0.00
Miscellaneous Total	0.00

Description: Inspections, 4000 Hour Service and Repairs 5570 Hours Date Started: 2023-07-10
 Equipment: E625 John Deere 290GLC Excavator (Thumb) RD-2023-221 Insheet RD-2023-224 Outsheet
 Serial#: 1FF290GXCFD706467

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
571	07/10/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524638 Line: 1		EA	1.000	311.54	311.54
572	07/10/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524638 Line: 2		EA	1.000	303.31	303.31
573	07/10/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524638 Line: 3		EA	1.000	471.32	471.32
574	07/10/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524638 Line: 4		EA	1.000	102.91	102.91
585	07/14/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524831 Line: 13		EA	2.000	70.34	140.68
586	07/14/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524831 Line: 14		EA	2.000	102.41	204.82
587	07/14/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524831 Line: 15		EA	31.000	5.29	163.99
588	07/14/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524831 Line: 16		EA	2.000	236.92	473.84
589	07/14/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524828 Line: 10		EA	1.000	43.70	43.70
590	07/14/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524828 Line: 11		EA	1.000	59.66	59.66
591	07/14/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524828 Line: 12		EA	1.000	87.71	87.71
592	07/12/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524744 Line: 6		EA	1.000	17.16	17.16
593	07/12/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524744 Line: 7		EA	1.000	5.96	5.96
594	07/12/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524744 Line: 8		EA	3.000	2.39	7.17



Work Order: 14204

595	07/12/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524744 Line: 9	EA	3.000	3.09	9.27
596	07/06/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524561 Line: 21	EA	1.000	102.41	102.41
597	07/06/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524561 Line: 22	EA	13.000	5.29	68.77
598	07/13/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 454809 Line: 1	EA	-1.000	102.41	-102.41
599	07/13/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 454809 Line: 2	EA	-13.000	5.29	-68.77
600	07/13/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 454809 Line: 4	EA	-1.000	311.54	-311.54
601	07/13/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 454809 Line: 5	EA	-1.000	303.31	-303.31
602	07/13/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 454809 Line: 6	EA	-1.000	471.32	-471.32
603	07/13/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 454809 Line: 7	EA	-1.000	102.91	-102.91
604	07/06/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524561 Line: 23	EA	2.000	6.00	12.00
605	07/13/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 454809 Line: 3	EA	-1.000	12.00	-12.00
1190	07/18/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524984 Line: 1	EA	1.000	103.59	103.59
1191	07/18/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524984 Line: 2	EA	2.000	347.82	695.64
1192	07/18/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524984 Line: 3	EA	1.000	135.47	135.47
1236	07/17/23	AP	Vendor: 10321 Union Tractor Ltd. 040-229180 Line: 1	EA	8.000	51.33	410.66
1237	07/17/23	AP	Vendor: 10321 Union Tractor Ltd. 040-229180 Line: 2	EA	8.000	5.94	47.50
1238	07/17/23	AP	Vendor: 10321 Union Tractor Ltd. 040-229180 Line: 3	EA	8.000	7.40	59.22
1328	07/24/23	AP	Vendor: 10407 Onsite Machining Solutions Ltd. 4944 Line: 1	EA	1.000	412.50	412.50
2284	07/27/23	AP	Vendor: 10401 RBC Avion Visa July 23_L Dahl Line: 6	EA	1.000	38.50	38.50
2296	07/06/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524561 Line: 24	EA	-1.000	102.41	-102.41
2297	07/06/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524561 Line: 25	EA	-13.000	5.29	-68.77
2298	07/06/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524561 Line: 26	EA	1.000	102.41	102.41
2299	07/06/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524561 Line: 27	EA	13.000	5.29	68.77
2300	07/10/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524638 Line: 5	EA	-1.000	311.54	-311.54
2301	07/10/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524638 Line: 6	EA	-1.000	303.31	-303.31
2302	07/10/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524638 Line: 7	EA	-1.000	471.32	-471.32
2303	07/10/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524638 Line: 8	EA	-1.000	102.91	-102.91
2304	07/10/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524638 Line: 9	EA	1.000	311.54	311.54
2305	07/10/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524638 Line: 10	EA	1.000	303.31	303.31
2306	07/10/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524638 Line: 11	EA	1.000	471.32	471.32
2307	07/10/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524638 Line: 12	EA	1.000	102.91	102.91
2308	07/12/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524744 Line: 10	EA	-1.000	17.16	-17.16
2309	07/12/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524744 Line: 11	EA	-1.000	5.96	-5.96
2310	07/12/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524744 Line: 12	EA	-3.000	2.39	-7.17
2311	07/12/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524744 Line: 13	EA	-3.000	3.09	-9.27
2312	07/12/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524744 Line: 14	EA	1.000	17.16	17.16
2313	07/12/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524744 Line: 15	EA	1.000	5.96	5.96
2314	07/12/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524744 Line: 16	EA	3.000	2.39	7.17
2315	07/12/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524744 Line: 17	EA	3.000	3.09	9.27
2316	07/14/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524828 Line: 13	EA	-1.000	43.70	-43.70
2317	07/14/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524828 Line: 14	EA	-1.000	59.66	-59.66
2318	07/14/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524828 Line: 15	EA	-1.000	87.71	-87.71
2319	07/14/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524828 Line: 16	EA	1.000	43.70	43.70
2320	07/14/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524828 Line: 17	EA	1.000	59.66	59.66
2321	07/14/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524828 Line: 18	EA	1.000	87.71	87.71
2322	07/14/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524831 Line: 17	EA	-2.000	70.34	-140.68
2323	07/14/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524831 Line: 18	EA	-2.000	102.41	-204.82
2324	07/14/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524831 Line: 19	EA	-31.000	5.29	-163.99
2325	07/14/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524831 Line: 20	EA	-2.000	236.92	-473.84
2326	07/14/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524831 Line: 21	EA	2.000	70.34	140.68
2327	07/14/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524831 Line: 22	EA	2.000	102.41	204.82
2328	07/14/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524831 Line: 23	EA	31.000	5.29	163.99
2329	07/14/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524831 Line: 24	EA	2.000	236.92	473.84
2330	07/18/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524984 Line: 4	EA	-1.000	103.59	-103.59
2331	07/18/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524984 Line: 5	EA	-2.000	347.82	-695.64
2332	07/18/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524984 Line: 6	EA	-1.000	135.47	-135.47
2333	07/18/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524984 Line: 7	EA	1.000	103.59	103.59
2334	07/18/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524984 Line: 8	EA	2.000	347.82	695.64
2335	07/18/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4524984 Line: 9	EA	1.000	135.47	135.47
2336	07/13/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 454809 Line: 11	EA	1.000	102.41	102.41
2337	07/13/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 454809 Line: 12	EA	13.000	5.29	68.77
2338	07/13/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 454809 Line: 13	EA	1.000	311.54	311.54



Work Order: 14204

2339	07/13/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 454809 Line: 14	EA	1.000	303.31	303.31
2340	07/13/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 454809 Line: 15	EA	1.000	471.32	471.32
2341	07/13/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 454809 Line: 16	EA	1.000	102.91	102.91
2342	07/13/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 454809 Line: 17	EA	-1.000	102.41	-102.41
2343	07/13/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 454809 Line: 18	EA	-13.000	5.29	-68.77
2344	07/13/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 454809 Line: 19	EA	-1.000	311.54	-311.54
2345	07/13/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 454809 Line: 20	EA	-1.000	303.31	-303.31
2346	07/13/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 454809 Line: 21	EA	-1.000	471.32	-471.32
2347	07/13/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 454809 Line: 22	EA	-1.000	102.91	-102.91
2434	07/17/23	AP	Vendor: 10321 Union Tractor Ltd. 040-229180 Line: 4	EA	-8.000	51.33	-410.66
2435	07/17/23	AP	Vendor: 10321 Union Tractor Ltd. 040-229180 Line: 5	EA	-8.000	5.94	-47.50
2436	07/17/23	AP	Vendor: 10321 Union Tractor Ltd. 040-229180 Line: 6	EA	-8.000	7.40	-59.22
2437	07/17/23	AP	Vendor: 10321 Union Tractor Ltd. 040-229180 Line: 7	EA	8.000	51.33	410.66
2438	07/17/23	AP	Vendor: 10321 Union Tractor Ltd. 040-229180 Line: 8	EA	8.000	5.94	47.50
2439	07/17/23	AP	Vendor: 10321 Union Tractor Ltd. 040-229180 Line: 9	EA	8.000	7.40	59.22
95	07/11/23	EMParts	200717 Seal kit	EA	1.000	104.87	104.87
96	07/11/23	EMParts	4346770 Pulley-Tensioner	EA	1.000	270.73	270.73
97	07/11/23	EMParts	4437838 Breather-Hydraulic	EA	1.000	57.65	57.65
98	07/11/23	EMParts	449558 Washer-Sealing	EA	4.000	3.69	14.76
99	07/11/23	EMParts	4630525 Filter-Hydraulic Pilot	EA	1.000	43.65	43.65
100	07/11/23	EMParts	AT365870 Filter-Fuel / Water Separator	EA	1.000	82.09	82.09
101	07/11/23	EMParts	AT497535 Mirror	EA	1.000	128.58	128.58
102	07/11/23	EMParts	FYA00007116 Belt-A/C	EA	1.000	38.02	38.02
103	07/11/23	EMParts	FYA00033065 Filter-Hydraulic Tank	EA	1.000	204.90	204.90
104	07/11/23	EMParts	RE516336 Fuel Tem	EA	1.000	257.06	257.06
105	07/11/23	EMParts	RE520930 Sensor-Fuel Pressure	EA	1.000	591.90	591.90
106	07/11/23	EMParts	RE522878 Filter-Fuel	EA	1.000	54.62	54.62
107	07/11/23	EMParts	RE535517 Filler	EA	1.000	45.69	45.69
108	07/11/23	EMParts	RE539279 Filter-Oil	EA	1.000	30.51	30.51
109	07/11/23	EMParts	RE541922 Filter-Fuel / Water Separator	EA	1.000	54.58	54.58
110	07/11/23	EMParts	RE548027 Tensioner-Belt	EA	1.000	245.93	245.93
111	07/11/23	EMParts	T428818 Belt-Serpentine	EA	1.000	70.98	70.98
112	07/11/23	EMParts	T59014 Seal-O-Ring	EA	2.000	6.94	13.88
113	07/11/23	EMParts	TH100679 Seal-O-Ring	EA	1.000	21.41	21.41
147	03/07/24	EMParts	T59014 Seal-O-Ring	EA	2.000	9.73	19.46
386	07/18/23	EMParts	FYA00007116 Belt-A/C	EA	-1.000	38.02	-38.02
387	07/18/23	EMParts	RE535517 Filler	EA	-1.000	45.69	-45.69
388	07/18/23	EMParts	200717 Seal kit	EA	-1.000	104.87	-104.87
403	07/18/23	EMParts	4310055 Seal	EA	1.000	43.16	43.16
404	07/18/23	EMParts	DZ120069 Pump-Fuel Lift	EA	1.000	111.12	111.12
405	07/18/23	EMParts	FYB00000115 Coupling-Pump to Motor	EA	1.000	254.97	254.97
406	07/18/23	EMParts	R531962 Seal-O-Ring	EA	2.000	1.58	3.16
407	07/18/23	EMParts	R63548 Seal-O-Ring	EA	4.000	1.52	6.08
410	07/19/23	EMParts	9742779 Gasket	EA	1.000	26.92	26.92
445	07/20/23	EMParts	AT446644 Seal Kit	EA	1.000	383.93	383.93
492	08/17/23	EMParts	Dyed Diesel Dyed Diesel	EA	291.480	1.22	355.05
506	07/24/23	EMParts	5W40 Spectra 5W40	I	22.000	7.52	165.37
507	07/24/23	EMParts	75W90 Certop SN 75W90 Gear Lube	EA	16.000	10.27	164.28
508	07/24/23	EMParts	Zinc Free Multoil 5w20 Zink-Free Hydraulic	EA	150.000	7.90	1,185.16
509	07/24/23	EMParts	8058352 Gasket	EA	1.000	24.34	24.34
510	07/24/23	EMParts	966993 Seal-O-Ring	EA	2.000	1.36	2.72
511	07/24/23	EMParts	CH17854 Packing	EA	2.000	8.31	16.62
			PO - Open - #1025127 - 10321 Tooth - Flare (aka duck bill)	EA	8.00	51.33	410.66
			PO - Open - #1025127 - 10321 Pin-Tooth	EA	8.00	5.94	47.50
			PO - Open - #1025127 - 10321 Retainer-Tooth	EA	8.00	7.40	59.22



Work Order: 14204

Labour Total	0.00
Parts Total	8,539.99
Miscellaneous Total	0.00

Segment: 2 Inspections

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
843	07/21/23	PR	Employee: 3103 Dallas Wood		HRS	3.000		
1479	07/24/23	PR	Employee: 3110 Callum Deditch		HRS	3.000		
1480	07/25/23	PR	Employee: 3110 Callum Deditch		HRS	2.000		

Labour Total	8.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Wash and Clean Cab, paint counterweight

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
828	07/10/23	PR	Employee: 2623 Brenton Woolman		HRS	9.500		
829	07/11/23	PR	Employee: 2623 Brenton Woolman		HRS	5.500		
841	07/20/23	PR	Employee: 2623 Brenton Woolman		HRS	9.000		
844	07/21/23	PR	Employee: 2623 Brenton Woolman		HRS	3.500		

Labour Total	27.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 Repair Leaks

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
830	07/11/23	PR	Employee: 3103 Dallas Wood		HRS	7.500		
831	07/11/23	PR	Employee: 3108 Zachary Dean		HRS	4.000		
832	07/12/23	PR	Employee: 3108 Zachary Dean		HRS	8.500		
833	07/12/23	PR	Employee: 3110 Callum Deditch		HRS	1.500		
834	07/13/23	PR	Employee: 3108 Zachary Dean		HRS	9.500		
835	07/14/23	PR	Employee: 3108 Zachary Dean		HRS	7.000		
836	07/14/23	PR	Employee: 3110 Callum Deditch		HRS	1.000		
837	07/17/23	PR	Employee: 3108 Zachary Dean		HRS	7.500		
839	07/18/23	PR	Employee: 3108 Zachary Dean		HRS	4.000		
840	07/19/23	PR	Employee: 3108 Zachary Dean		HRS	9.500		



Work Order: 14204

Labour Total	60.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 Repair Panels, mirrors,

Segment: 6 4000 Hour Service, Belts and Tensioner

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
838	07/17/23	PR	Employee: 3103 Dallas Wood		HRS	3.500		
842	07/20/23	PR	Employee: 3108 Zachary Dean		HRS	0.500		

Labour Total	4.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 7 Check and Repair Codes

Codes
 157-17 Fuel rail Pressure.
 94-18 Low fuel signal pressure.
 174-04 Fuel temp high.
 412-00 EGR temp high
 111-01 Over heat.
 1569-31 Derate.

Segment: 8 Check Cutting edge and Change Bucket Teeth


Segment: 9 Check and Shim Pins

Labour Total	99.50
Parts Total	8,539.99
Miscellaneous Total	0.00

Description: Inspections and Repairs	5948 Hours	Date Started: 2023-11-03
Equipment: E625 John Deere 290GLC Excavator (Thumb)	RD-2023-288 Insheet	
Serial#: 1FF290GXCFD706467		

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
925	11/20/23	AP	Vendor: 10321 Union Tractor Ltd. 040-230595 Line: 1		EA	2.000	331.25	662.50
926	11/20/23	AP	Vendor: 10321 Union Tractor Ltd. 040-230595 Line: 2		EA	2.000	55.28	110.56



927	11/20/23	AP	Vendor: 10321 Union Tractor Ltd. 040-230595 Line: 3	EA	-2.000	55.28	-110.56
949	12/04/23	AP	Vendor: 10407 Onsite Machining Solutions Ltd. 5144 Line: 1	LS	0.000	0.00	1,035.50
1010	11/20/23	AP	Vendor: 10034 Brandt Tractor Ltd. 05 4529882 Line: 2	EA	-1.000	57.46	-57.46
162	11/08/23	EMParts	9755978 Step	EA	0.000	261.48	0.00
163	11/08/23	EMParts	AT387543 Filter	EA	1.000	575.00	575.00
164	11/08/23	EMParts	RE535517 Filler	EA	1.000	58.69	58.69
767	11/21/23	EMParts	R502902 Packing	EA	1.000	16.63	16.63
826	11/21/23	EMParts	R51936 Sealing Washer	EA	7.000	2.69	18.83
853	11/21/23	EMParts	200797 Bushing-Thumb(Brandt)	EA	2.000	262.48	524.96
854	11/21/23	EMParts	3090167 Pin- Coupler to H-Link	EA	1.000	465.86	465.86
855	11/21/23	EMParts	4443880 Bushing (Arm)	EA	2.000	179.49	358.98
856	11/21/23	EMParts	TH102445 Lip Seal-Pin 90mm	EA	4.000	18.03	72.12
935	11/22/23	EMParts	4355875 Bushing (H-Link)	EA	4.000	120.05	480.20
			PO - Open - #1026247 - 10034 Filler	EA	-1.00	57.46	-57.46

07/29/25 10:09:48 AM
Viewpoint Remote .rpt



Work Order: 14472

Segment: 7 Replace Arm, H-Link, Thumb pins and bushings

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
541	12/04/23	PR	Employee: 3103 Dallas Wood		HRS	3.500		
542	12/04/23	PR	Employee: 3109 Cameron Ellsworth		HRS	1.000		
543	12/05/23	PR	Employee: 3103 Dallas Wood		HRS	4.000		
1355	11/21/23	PR	Employee: 3103 Dallas Wood		HRS	3.500		
1356	11/22/23	PR	Employee: 3103 Dallas Wood		HRS	7.500		
1357	11/22/23	PR	Employee: 3109 Cameron Ellsworth		HRS	0.500		
1359	11/23/23	PR	Employee: 3103 Dallas Wood		HRS	3.000		

Labour Total 23.00

Parts Total 0.00

Miscellaneous Total 0.00

Labour Total 35.00

Parts Total 4,671.73

Miscellaneous Total 0.00

Description: Rental Return Legacy	5948 Hours	Date Started: 2023-11-03
Equipment: E625 John Deere 290GLC Excavator (Thumb)	RD-2023-288 Insheet	
Serial#: 1FF290GXCFD706467		

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
165	11/08/23	EMParts	4S00686 Filter-Cab Air (4632689)		EA	1.000	36.93	36.93
166	11/08/23	EMParts	AT300487 Filter-Air Primary		EA	1.000	124.13	124.13
167	11/08/23	EMParts	AT372458 Cap		EA	1.000	229.36	229.36
168	11/08/23	EMParts	FYA00001490 Filter-Cab Air		EA	1.000	101.47	101.47
169	11/08/23	EMParts	FYA00030883 Cover-Joy Stick L/H		EA	1.000	337.40	337.40
170	11/08/23	EMParts	FYA00030889 Cover-Joy Stick R/H		EA	1.000	15.32	15.32
171	11/08/23	EMParts	FYA00070858 Strainer-Fuel		EA	1.000	112.63	112.63
710	12/14/23	EMParts	60/40 Rad-Cool Antifreeze		EA	0.000	6.38	0.00
711	12/14/23	EMParts	Zinc Free Multiloil 5w20 Zink-Free Hydraul		EA	0.000	7.20	0.00

Labour Total 0.00

Parts Total 957.24

Miscellaneous Total 0.00

Segment: 2 Wash and Clean Cab

Segment: 3 Replace Air Filters and top up fluids



GCS Energy Services Ltd.

Work Order: 14473

Cab Air and Engine primary air filter dirty.
Hydraulic fluid low.
Engine air pre-cleaner broken.
No Coolant in Reservoir-no signs of leak.

Segment: 4 Repair Monitors, panels, mirrors

Camera Monitor in cab loose/sloppy zip-tied in.
Both joystick plastic broken.
Battery covers removed and terminals rusty.
Remove renters decals.
Re-adjust R/H rear track frame step extension.
Adjust tracks.
Fuel screen missing.
Adjust mirrors.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1351	11/20/23	PR	Employee: 3103 Dallas Wood		HRS	5.500		

Labour Total 5.50

Parts Total 0.00

Miscellaneous Total 0.00

Labour Total 5.50

Parts Total 1,417.16

Miscellaneous Total 0.00

Description: Reg Maintenance	GRO#11630/7714	Date Started: 2023-12-15
Equipment: E625 John Deere 290GLC Excavator (Thumb)	5972 hours Next Service 6178 hours	
Serial#: 1FF290GXCFD706467		

Segment: 1 parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1257	05/30/24	AP	Vendor: 10064 Comrades Parts & Accessories Ltd. 000-399384 Line: 1	LS		0.000	0.00	39.38
735	05/31/24	EMParts	AT497535 Mirror		EA	1.000	118.91	118.91

Labour Total 0.00

Parts Total 158.29

Miscellaneous Total 0.00

Segment: 2 clean windows

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1428	12/14/23	PR	Employee: 22 Garrett Nelson		HRS	1.000		



Work Order: 14579

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 lack of heat in cab

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1429	12/18/23	PR	Employee: 2024 Travis Schmidt		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 Install mirrior/valve in cooling system

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1360	05/31/24	PR	Employee: 3119 Shawn Dittmer		HRS	2.000		

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	3.50
Parts Total	618.21
Miscellaneous Total	0.00

Description: Reg Maintenance	GRO#7708/13037	Date Started: 2024-06-04
Equipment: E625 John Deere 290GLC Excavator (Thumb)	5976 hours	
Serial#: 1FF290GXCFD706467	6178 next service	

Segment: 1 parts

3m of 5/8 heater hose

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
55	10/08/24	AP	Vendor: 32904 Mid-West Auto Supply Wainwright 562345 Line: 1	EA	-1.000	60.00		-60.00
1381	09/19/24	AP	Vendor: 32904 Mid-West Auto Supply Wainwright 561528 Line: 2	EA	1.000	349.99		349.99
1382	09/19/24	AP	Vendor: 32904 Mid-West Auto Supply Wainwright 561528 Line: 3	EA	1.000	60.00		60.00
1359	09/11/24	EMParts	60/40 Rad-Cool Antifreeze	EA	30.000	7.18		215.36



Work Order: 14911

Labour Total	0.00
Parts Total	565.35
Miscellaneous Total	0.00

Segment: 2 Complete In/Out Sheet,grease machine

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1358	05/29/24	PR	Employee: 3119 Shawn Dittmer		HRS	1.500		

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 repair water leak under cab/trouble shoot no heat in cab

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1359	05/29/24	PR	Employee: 3119 Shawn Dittmer		HRS	1.500		

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 Trouble shoot coolant leak

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
405	09/11/24	PR	Employee: 3119 Shawn Dittmer		HRS	3.000		

Labour Total	3.00
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	6.00
Parts Total	1,025.27
Miscellaneous Total	0.00

Description: Reg Maintenance	GRO13885	Date Started: 2025-06-06
Equipment: E625 John Deere 290GLC Excavator (Thumb)	5986hrs May 27 2025	
Serial#: 1FF290GXCFD706467		

Segment: 1 parts



Work Order: 15382

Segment: 2 Complete Inspection Sheet

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1151	05/27/25	PR	Employee: 3119 Shawn Dittmer		HRS	2.500		

Labour Total	2.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 WASH

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
272	07/16/25	PR	Employee: 22 Garrett Nelson		HRS	4.500		

Labour Total	4.50
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	7.00
Parts Total	459.92
Miscellaneous Total	0.00

