



Work Order: 11136

EB10-226

Description: Inspection and Repairs	4583 Hours	Date Started: 2020-05-27
Equipment: E577 Caterpillar 815F Packer	RD-2020-195 Insheet	
	RD-2020-202 Outsheet	
	GRO-9073/9087/9158/9159/9160/917	
Serial#: CAT0815FJBYN00399	8	

Segment: 1 Parts and Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
258	06/04/20	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S5822210.001 Line: 1		LS	0.000	0.00	174.78
63	06/03/20	EMParts	1940508 Clamp		EA	1.000	35.72	35.72
64	06/03/20	EMParts	9X3352 Filter-Cab Air		EA	1.000	35.44	35.44
85	06/03/20	EMParts	1381510 Plug-Drain		EA	1.000	37.13	37.13
86	06/03/20	EMParts	7M8485 Seal-O-Ring		EA	1.000	3.10	3.10
87	06/04/20	EMParts	1043601 Screw		EA	1.000	1.58	1.58
88	06/04/20	EMParts	1339200 Lever		EA	1.000	70.12	70.12
89	06/04/20	EMParts	1388140 Switch Assembly (Cap As.)		EA	1.000	244.11	244.11
90	06/04/20	EMParts	2076941 Switch Assembly-Toggle		EA	1.000	187.88	187.88
91	06/04/20	EMParts	4B4274 Washer		EA	1.000	0.39	0.39
92	06/04/20	EMParts	6V9505 Screw(M3-0.5x25mm)		EA	2.000	0.43	0.86
166	06/08/20	EMParts	1554200 Cable-20' Positive Air Shut Of		EA	1.000	167.57	167.57
736	08/16/20	EMParts	5W40 Spectra 5W40		I	37.000	5.21	192.90
737	08/16/20	EMParts	60/40 Rad-Cool Antifreeze		EA	55.000	5.90	324.41
738	08/16/20	EMParts	TO4 Spectra Xtreme TO-4 All season		EA	210.000	5.59	1,174.04
1857	05/27/20	EMParts	Dyed Diesel Dyed Diesel		EA	158.990	0.90	143.06
1871	05/28/20	EMParts	1328875 Filter-Power Train		EA	1.000	51.02	51.02
1872	05/28/20	EMParts	1R0722 Filter-Hydraulic		EA	2.000	24.61	49.22
1873	05/28/20	EMParts	1R0762 Filter-Fuel Advanced Efficiency		EA	1.000	29.71	29.71
1874	05/28/20	EMParts	1R1808 Filter-Oil Advanced Efficiency		EA	1.000	33.18	33.18
1875	05/28/20	EMParts	2S8439 Seal-O-Ring		EA	1.000	10.69	10.69
1876	05/28/20	EMParts	3261644 Filter-Fuel / Water Separator		EA	1.000	42.26	42.26
1877	05/28/20	EMParts	3E0410 Filter-Cab Air		EA	1.000	29.18	29.18
1878	05/28/20	EMParts	5H6733 Seal-O-Ring		EA	2.000	11.29	22.58
1879	05/28/20	EMParts	6I2505 Filter-Air Primary		EA	1.000	41.93	41.93
1880	05/28/20	EMParts	7D1195 Seal		EA	2.000	8.87	17.74
1881	05/28/20	EMParts	7X6041 Air Filter		EA	1.000	24.65	24.65

Labour Total	0.00
Parts Total	3,145.25
Miscellaneous Total	0.00

Segment: 2 Insheet Inspection

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2246	05/27/20	PR	Employee: 2471 Greg Royer		HRS	3.000		
2827	05/27/20	PR	Employee: 2471 Greg Royer		HRS	-3.000		
2828	05/27/20	PR	Employee: 2471 Greg Royer		HRS	3.000		



Work Order: 11136

Labour Total	3.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Wash and Clean Cab

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
560	06/05/20	PR	Employee: 1074 Jack Loughheed		HRS	6.500		
866	06/05/20	PR	Employee: 1074 Jack Loughheed		HRS	-6.500		
867	06/05/20	PR	Employee: 1074 Jack Loughheed		HRS	6.500		
1473	06/05/20	PR	Employee: 1074 Jack Loughheed		HRS	-6.500		
1474	06/05/20	PR	Employee: 1074 Jack Loughheed		HRS	6.500		
1684	06/05/20	PR	Employee: 1074 Jack Loughheed		HRS	-6.500		
1685	06/05/20	PR	Employee: 1074 Jack Loughheed		HRS	6.500		

Labour Total	6.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 4000 Hour and Change Coolant

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
229	06/02/20	PR	Employee: 2471 Greg Royer		HRS	5.000		
230	06/03/20	PR	Employee: 2471 Greg Royer		HRS	7.500		
233	06/04/20	PR	Employee: 2471 Greg Royer		HRS	4.500		
541	06/02/20	PR	Employee: 2471 Greg Royer		HRS	-5.000		
542	06/02/20	PR	Employee: 2471 Greg Royer		HRS	5.000		
543	06/03/20	PR	Employee: 2471 Greg Royer		HRS	-7.500		
544	06/03/20	PR	Employee: 2471 Greg Royer		HRS	7.500		
549	06/04/20	PR	Employee: 2471 Greg Royer		HRS	-4.500		
550	06/04/20	PR	Employee: 2471 Greg Royer		HRS	4.500		
856	06/02/20	PR	Employee: 2471 Greg Royer		HRS	-5.000		
857	06/02/20	PR	Employee: 2471 Greg Royer		HRS	5.000		
858	06/03/20	PR	Employee: 2471 Greg Royer		HRS	-7.500		
859	06/03/20	PR	Employee: 2471 Greg Royer		HRS	7.500		
860	06/04/20	PR	Employee: 2471 Greg Royer		HRS	-4.500		
861	06/04/20	PR	Employee: 2471 Greg Royer		HRS	4.500		
1453	06/02/20	PR	Employee: 2471 Greg Royer		HRS	-5.000		
1454	06/02/20	PR	Employee: 2471 Greg Royer		HRS	5.000		
1455	06/03/20	PR	Employee: 2471 Greg Royer		HRS	-7.500		
1456	06/03/20	PR	Employee: 2471 Greg Royer		HRS	7.500		
1461	06/04/20	PR	Employee: 2471 Greg Royer		HRS	-4.500		
1462	06/04/20	PR	Employee: 2471 Greg Royer		HRS	4.500		



Work Order: 11136

Labour Total	17.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 Decal GCS

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
234	06/04/20	PR	Employee: 2471 Greg Royer		HRS	0.500		
551	06/04/20	PR	Employee: 2471 Greg Royer		HRS	-0.500		
552	06/04/20	PR	Employee: 2471 Greg Royer		HRS	0.500		
1463	06/04/20	PR	Employee: 2471 Greg Royer		HRS	-0.500		
1464	06/04/20	PR	Employee: 2471 Greg Royer		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 6 T/S and Repair P.A.S.S.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
235	06/04/20	PR	Employee: 2471 Greg Royer		HRS	0.500		
553	06/04/20	PR	Employee: 2471 Greg Royer		HRS	-0.500		
554	06/04/20	PR	Employee: 2471 Greg Royer		HRS	0.500		
1465	06/04/20	PR	Employee: 2471 Greg Royer		HRS	-0.500		
1466	06/04/20	PR	Employee: 2471 Greg Royer		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 7 Check and Repair Electrical and Switches

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
236	06/04/20	PR	Employee: 2471 Greg Royer		HRS	1.500		
555	06/04/20	PR	Employee: 2471 Greg Royer		HRS	-1.500		
556	06/04/20	PR	Employee: 2471 Greg Royer		HRS	1.500		
862	06/04/20	PR	Employee: 2471 Greg Royer		HRS	-1.500		
863	06/04/20	PR	Employee: 2471 Greg Royer		HRS	1.500		
1467	06/04/20	PR	Employee: 2471 Greg Royer		HRS	-1.500		
1468	06/04/20	PR	Employee: 2471 Greg Royer		HRS	1.500		



Work Order: 11136

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 8 Check and Repair Tilt Cylinder

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
231	06/03/20	PR	Employee: 2471 Greg Royer		HRS	0.500		
237	06/04/20	PR	Employee: 2471 Greg Royer		HRS	0.500		
545	06/03/20	PR	Employee: 2471 Greg Royer		HRS	-0.500		
546	06/03/20	PR	Employee: 2471 Greg Royer		HRS	0.500		
557	06/04/20	PR	Employee: 2471 Greg Royer		HRS	-0.500		
558	06/04/20	PR	Employee: 2471 Greg Royer		HRS	0.500		
1457	06/03/20	PR	Employee: 2471 Greg Royer		HRS	-0.500		
1458	06/03/20	PR	Employee: 2471 Greg Royer		HRS	0.500		
1469	06/04/20	PR	Employee: 2471 Greg Royer		HRS	-0.500		
1470	06/04/20	PR	Employee: 2471 Greg Royer		HRS	0.500		

Labour Total	1.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 9 Replace Missing Hindge

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
232	06/03/20	PR	Employee: 2471 Greg Royer		HRS	0.500		
547	06/03/20	PR	Employee: 2471 Greg Royer		HRS	-0.500		
548	06/03/20	PR	Employee: 2471 Greg Royer		HRS	0.500		
1459	06/03/20	PR	Employee: 2471 Greg Royer		HRS	-0.500		
1460	06/03/20	PR	Employee: 2471 Greg Royer		HRS	0.500		

Labour Total	0.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 10 Outsheat

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
559	06/05/20	PR	Employee: 2395 Nickolas Schou		HRS	2.500		
561	06/08/20	PR	Employee: 2395 Nickolas Schou		HRS	4.000		
864	06/05/20	PR	Employee: 2395 Nickolas Schou		HRS	-2.500		
865	06/05/20	PR	Employee: 2395 Nickolas Schou		HRS	2.500		
868	06/08/20	PR	Employee: 2395 Nickolas Schou		HRS	-4.000		
869	06/08/20	PR	Employee: 2395 Nickolas Schou		HRS	4.000		



Work Order: 11136

1471	06/05/20	PR	Employee: 2395 Nickolas Schou	HRS	-2.500
1472	06/05/20	PR	Employee: 2395 Nickolas Schou	HRS	2.500
1475	06/08/20	PR	Employee: 2395 Nickolas Schou	HRS	-4.000
1476	06/08/20	PR	Employee: 2395 Nickolas Schou	HRS	4.000

Labour Total	6.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 11 Straighten L/H Step and replace broken bolt

Labour Total	37.00
Parts Total	3,145.25
Miscellaneous Total	0.00

Description: Inspections and Repairs	4596 Hours	Date Started: 2020-08-18
Equipment: E577 Caterpillar 815F Packer	RD-2020-275 Insheet RD-2021-240 Outsheets	
Serial#: CAT0815FJBYN00399		

Segment: 1 Parts and Service

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2425	08/16/21	AP	Vendor: 10508 Red Deer Fasteners & Tools Ltd. H06270 Line: 1	LS		0.000	0.00	28.03
20	09/07/21	EMParts	OMT Operators Manual	EA		1.000	105.45	105.45
176	10/09/20	EMParts	Dyed Diesel Dyed Diesel	EA		229.400	0.70	159.64
3768	09/21/20	EMParts	Dyed Diesel Dyed Diesel	EA		9.460	0.70	6.62

Labour Total	0.00
Parts Total	299.74
Miscellaneous Total	0.00

Segment: 2 Insheet Inspection

Pull out of line up, run/test. Pictures and park up front.
-Paul

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
766	08/11/21	PR	Employee: 2471 Greg Royer	HRS		0.500		
770	08/12/21	PR	Employee: 2471 Greg Royer	HRS		0.500		
1809	01/28/22	PR	Employee: 1575 Paul Nixon	HRS		0.500		
3361	08/26/20	PR	Employee: 1577 Dylan Grant	HRS		2.000		



Work Order: 11420

Labour Total	3.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Wash and Clean Cab

Segment: 4 Check and Adjust Fluids Levels

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
767	08/11/21	PR	Employee: 2471 Greg Royer		HRS	0.500		
771	08/12/21	PR	Employee: 2471 Greg Royer		HRS	1.000		

Labour Total	1.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 T/S and Repair Squeeling Belt

Segment: 6 T/S Start up noise and Codes

Knocks on Startup
Active Codes
081 1711.03
Stored Codes
036 E0265.3
036 E0198.1

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
768	08/11/21	PR	Employee: 2471 Greg Royer		HRS	2.500		
772	08/12/21	PR	Employee: 2471 Greg Royer		HRS	1.000		

Labour Total	3.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 7 T/S and Repair A/C

Segment: 8 Adjust Scrapers

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
769	08/11/21	PR	Employee: 2471 Greg Royer		HRS	2.500		
773	08/12/21	PR	Employee: 2471 Greg Royer		HRS	0.500		



Work Order: 11420

Labour Total	3.00
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	11.50
Parts Total	299.74
Miscellaneous Total	0.00

Description: Inspections, Replace front window and Repairs

Date Started: 2023-04-14

Equipment: E577 Caterpillar 815F Packer

Serial#: CAT0815FJBYN00399

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
488	04/18/23	AP	Vendor: 10132 Gregg Distributors LP 059-538348 Line: 1	EA		1.000	11.99	11.99
1930	04/18/23	AP	Vendor: 10132 Gregg Distributors LP 059-538348 Line: 2	EA		-1.000	11.99	-11.99
1931	04/18/23	AP	Vendor: 10132 Gregg Distributors LP 059-538348 Line: 3	EA		1.000	11.99	11.99
2075	06/27/23	AP	Vendor: 10401 RBC Avion Visa June 23_L Dahl Line: 9	LS		0.000	0.00	2,040.00
2130	05/29/23	AP	Vendor: 10401 RBC Avion Visa May 23_L Dahl Line: 11	LS		0.000	0.00	586.75
2283	07/27/23	AP	Vendor: 10401 RBC Avion Visa July 23_L Dahl Line: 7	LS		0.000	0.00	8,250.00
368	04/18/23	EMParts	1010745 Blade-Wiper	EA		1.000	63.49	63.49
656	08/21/23	EMParts	Dyed Diesel Dyed Diesel	EA		56.780	1.22	69.16
PO - Open - #1025261 - 10401 Portland Tractor Canada				LS		0.00	0.00	2,040.00
						Labour Total	0.00	
						Parts Total	13,061.39	
						Miscellaneous Total	0.00	

Segment: 2 Inspections

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2173	04/14/23	PR	Employee: 1575 Paul Nixon		HRS	1.500		
						Labour Total	1.50	
						Parts Total	0.00	
						Miscellaneous Total	0.00	

Segment: 3 Wash and Clean Cab

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
2172	04/13/23	PR	Employee: 2623 Brenton Woolman		HRS	4.000		



Work Order: 14009

Labour Total	4.00
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	5.50
Parts Total	13,061.39
Miscellaneous Total	0.00

Description: Inspections and Repairs	5612 Hours	Date Started: 2023-11-08
Equipment: E577 Caterpillar 815F Packer	RD-2023-308 Insheet	
	RD-2024-152 Outsheet	
Serial#: CAT0815FJBYN00399		

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
305	03/14/24	AP	Vendor: 10508 Red Deer Fasteners & Tools Ltd. H71849 Line: 1	EA		6.000	16.79	100.74
803	03/15/24	AP	Vendor: 10416 Hose Headquarters (Red Deer) Ltd. S7325988.001 Line: 1	EA		1.000	61.48	61.48
959	03/21/24	AP	Vendor: 10188 Messer Canada Inc. 2107522513 Line: 1	EA		9.080	21.61	196.22
1010	03/28/24	AP	Vendor: 10321 Union Tractor Ltd. 040-231868 Line: 1	EA		5.000	10.93	54.63
1011	03/28/24	AP	Vendor: 10321 Union Tractor Ltd. 040-231868 Line: 2	EA		10.000	1.51	15.10
1012	03/28/24	AP	Vendor: 10321 Union Tractor Ltd. 040-231868 Line: 3	EA		2.000	50.21	100.42
1372	04/03/24	AP	Vendor: 32404 MechTech Heavy Equipment Repair Ltd 100521-1 Line: 1	EA		3.000	50.00	150.00
1960	04/29/24	AP	Vendor: 10401 RBC Avion Visa Apr 24_L Dahl Line: 1	EA		5.000	6.77	33.86
1973	03/15/24	AP	Vendor: 10321 Union Tractor Ltd. 040-231750 Line: 1	EA		120.000	20.22	2,426.64
2080	03/27/24	AP	Vendor: 10401 RBC Avion Visa Mar 24_L Dahl Line: 6	EA		6.000	0.08	0.48
2081	03/27/24	AP	Vendor: 10401 RBC Avion Visa Mar 24_L Dahl Line: 7	EA		6.000	0.40	2.40
2562	12/27/23	AP	Vendor: 10401 RBC Avion Visa Dec 23_L Dahl Line: 21	EA		3.000	96.00	288.00
87	04/08/24	EMParts	Dyed Diesel Dyed Diesel	EA		68,140	1.28	87.14
133	12/07/23	EMParts	2709181 Floormat-Upper	EA		1.000	591.96	591.96
270	03/14/24	EMParts	6D7889 Seal-O-Ring	EA		6.000	19.54	117.24
351	12/12/23	EMParts	1924241 Muffler-815F	EA		1.000	1,909.74	1,909.74
815	03/22/24	EMParts	1554100 Cable-10' Positive Air Shut Of	EA		1.000	105.77	105.77
			PO - Open - #1026770 - 10401 Heavy duty injector test- labor and shop suppl	EA		3.00	96.00	288.00
			PO - Open - #1027134 - 10321 2V7053 Tip 815 packer	EA		120.00	20.22	2,426.64
			PO - Open - #1027248 - 10321 Capscrew	EA		5.00	10.93	54.63
			PO - Open - #1027248 - 10321 nut-hex	EA		10.00	1.51	15.10
			PO - Open - #1027248 - 10321 1062047- cleaner bar	EA		2.00	50.21	100.42
			Labour Total				0.00	
			Parts Total				9,126.61	
			Miscellaneous Total				0.00	

Segment: 2 Inspections

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
467	04/05/24	PR	Employee: 3103 Dallas Wood		HRS	4.500		



Work Order: 14497

Labour Total	4.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 Wash/paint cab

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
620	03/14/24	PR	Employee: 3131 Shawn Rowe		HRS	5.500		

Labour Total	5.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 Repair Muffler, lights, P.A.S.S.,A/C,

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
616	03/12/24	PR	Employee: 3131 Shawn Rowe		HRS	3.000		
618	03/13/24	PR	Employee: 3131 Shawn Rowe		HRS	3.000		
621	03/14/24	PR	Employee: 3131 Shawn Rowe		HRS	3.000		
1260	03/18/24	PR	Employee: 3131 Shawn Rowe		HRS	1.000		
1262	03/28/24	PR	Employee: 3131 Shawn Rowe		HRS	7.000		

Labour Total	17.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 5 Repair Leak

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
617	03/12/24	PR	Employee: 3131 Shawn Rowe		HRS	1.000		
619	03/13/24	PR	Employee: 3131 Shawn Rowe		HRS	1.500		
622	03/15/24	PR	Employee: 3131 Shawn Rowe		HRS	7.500		
1261	03/18/24	PR	Employee: 3131 Shawn Rowe		HRS	6.000		

Labour Total	16.00
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 6 Repair scrapers

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
466	04/04/24	PR	Employee: 3131 Shawn Rowe		HRS	2.000		



Work Order: 14497

Labour Total	2.00
Parts Total	0.00
Miscellaneous Total	0.00
Labour Total	45.00
Parts Total	11,166.61
Miscellaneous Total	0.00

Description: Rental Return Emsco	5612 Hours	Date Started: 2023-11-08
Equipment: E577 Caterpillar 815F Packer	RD-2023-308 Insheet RD-2024-152 Outsheet	
Serial#: CAT0815FJBYN00399		

Segment: 1 Parts

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
1143	11/27/23	AP	Vendor: 10111 Finning (Canada) a division of Finning International 985237310 Line: 1		EA	-1.000	15.76	-15.76
169	03/08/24	EMParts	3228568 Button-Horn Steering Wheel		EA	1.000	112.59	112.59
232	03/12/24	EMParts	2861102 Latch Assembly		EA	1.000	185.11	185.11
233	03/12/24	EMParts	3435527 Bowl Assembly-Fuel		EA	1.000	71.57	71.57
242	11/14/23	EMParts	7X2500 Latch		EA	1.000	115.48	115.48
630	11/16/23	EMParts	1R0762 Filter-Fuel Advanced Efficiency		EA	1.000	34.60	34.60
631	11/16/23	EMParts	1R1808 Filter-Oil Advanced Efficiency		EA	1.000	40.40	40.40
632	11/16/23	EMParts	3261644 Filter-Fuel / Water Separator		EA	1.000	55.22	55.22
633	11/16/23	EMParts	3E0410 Filter-Cab Air		EA	1.000	63.43	63.43
634	11/16/23	EMParts	6I2505 Filter-Air Primary		EA	1.000	54.54	54.54
635	11/16/23	EMParts	6I2506 Filter-Air Secondary		EA	1.000	128.71	128.71
636	11/16/23	EMParts	6W5427 Pin Assembly-Tow		EA	1.000	504.02	504.02
637	11/16/23	EMParts	7X2497 Handle-Door		EA	1.000	10.69	10.69
638	11/16/23	EMParts	9X3352 Filter-Cab Air		EA	1.000	54.03	54.03

Labour Total	0.00
Parts Total	1,414.63
Miscellaneous Total	0.00

Segment: 2 Wash and Clean Cab

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
463	04/03/24	PR	Employee: 2623 Brenton Woolman		HRS	8.000		
464	04/04/24	PR	Employee: 2623 Brenton Woolman		HRS	8.500		
465	04/05/24	PR	Employee: 2623 Brenton Woolman		HRS	4.000		
615	03/15/24	PR	Employee: 3131 Shawn Rowe		HRS	1.000		



Work Order: 14498

Labour Total	21.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 3 250 Hour Service

Engine oil low.
 Engine primary air filter full of soot.
 No sign of service decal, nothing written on filters, overdue for service.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
611	03/11/24	PR	Employee: 3131 Shawn Rowe		HRS	2.000		
613	03/12/24	PR	Employee: 3131 Shawn Rowe		HRS	2.500		

Labour Total	4.50
Parts Total	0.00
Miscellaneous Total	0.00

Segment: 4 Rpiar windows,latches, locks

Lock needs to be cut off of radiator cap.
 Windshield cracked-L/H side shield has a big rock chip.
 Horn cap/Switch missing.
 Rear tow pin missing.
 Cab door release handle broken.

Trans	Actual Date	Source	Details	STATUS	UM	Units	Price	Total Cost
612	03/11/24	PR	Employee: 3131 Shawn Rowe		HRS	1.000		
614	03/13/24	PR	Employee: 3131 Shawn Rowe		HRS	2.000		

Labour Total	3.00
Parts Total	0.00
Miscellaneous Total	0.00

Labour Total	29.00
Parts Total	6,339.42
Miscellaneous Total	0.00

Description: Inspections and Repairs Equipment: E577 Caterpillar 815F Packer Serial#: CAT0815FJBYN00399	5620 Hours RD-2025-141 Insheet	Date Started: 2025-05-08
--	-----------------------------------	---------------------------------

Segment: 1 Parts

Segment: 2 Inspections



Work Order: 15347

Segment: 3 Wash and Clean Cab

Segment: 4 Repair Leaks

Segment: 5 Repair door

Segment: 6 Replace batteries

Labour Total	0.00
Parts Total	4,924.79
Miscellaneous Total	0.00