# G5 – 14M Repair History

## 2020 Repairs

- Replace road in side-shift cylinder and head in lift cylinder
- Replace wear strips for circle and moldboard
- Replace circle slides and shims
- Replace leaking hydraulic hose

#### 2021 Repairs

- Replace leaking hydraulic hose
- Replace bottom brass slides
- Install new right hand steering cylinder wiring harness
- Re-shim circle
- Install new tie rod and re-shim side-shift cylinder
- Install new fan motor and resistor
- Replace leaking hydraulic hose
- Install new steps
- Install new steering pins
- Install new batteries
- Replace leaking hydraulic hose

### 2022 Repairs

- Install new brass top slides
- Replace leaking hydraulic hose
- Machine Inspection Repairs Repair/rebuild the circle drive. Replace tandem drive chains and rebuild hub assembly. Repair/rebuild brake groups, install new bearings. Install new steering pins and bushings
- Install new water pump and replace rad hose
- Replace upper and lower king pin on front right side
- Install new circle drive motor and seal
- Replace broken right rear drive chain
- Replace three leaking hydraulic hoses

#### 2023 Repairs

- Replace transmission suction hose
- Replace broken window
- Repair/rebuild circle drive and install new brass. Install new brass for moldboard slides. Replace tandem drives. Install new segments.
- Replace shuttle valve
- Install new batteries
- Replace circle drive housing studs and bolts
- Install new pinon for circle gear
- Install new starter

#### 2024 Repairs

- Replace broken chain drive
- Install new retainers in circle
- Install new actuator valve and reseal
- Install new exhaust elbow and clamps
- Replace leaking hydraulic hose

### 2025 Repairs

- Rebuild circle drive with new update
- Replace remote engine shut down switch
- Reseal circle drive. Install new duo cone seals on pinon

- Replace park brake pressure switch
- Replace ground cable and articulation links behind cab
- Install new freeze switch