## 2008 DODGE 5500

EB42-1

#### 2008 Dodge 5500

#### 406897 Km

#### VIN: 3D6WD76A58G217021

#### Options Installed on unit:

- VMAC Air compressor in working condition.
- Air Tank 14" Diameter x 57" Length.
- Service body mounted Crane 4000 Lb lifting capacity.
- Service body 13' Long x 8' Wide.

#### **Recent Notable Repairs:**

- CVIP May 6, 2025 406889 Km
- Windshield Replaced for CVIP.
- Starter Replaced May 6, 2025 406880 km.
- Replaced TIPM Aug 13, 2024 363453 Km.
- Transmission Rebuilt and Torque Converter Replaced Feb 21, 2024 363453 km
- Brake booster, pads, rotors and hubs replaced Feb 21, 2024 363453 km.
- Front Suspension Serviced Feb 24, 2024 363453 km.
- **Rear Crank Seal Replaced** Feb 24, 2024 363453 km.
- Driveshaft Rebuit, balanced and re-installed Jan 25, 2024 363100 km.
- New Reman Transfer Case Installed Dec 4, 2023 363100 km.
- Two New Batteries installed Dec 16, 2023 335714 km.
- Installed Preventatively Rebuilt Turbo Nov 29, 2023.
- VMAC belt and Engine serpentine belt replaced June 19, 2023.

#### **Minor Repairs:**

- Driver seat has been re-foamed and upholstered.
- A/C Lines all replaced July 24, 2023 351261 km.
- A/C Compressor and Condenser Replaced Feb 8, 2022 299633 km.
- New Winter Front purchased Oct 20, 2020 249673 km.
- Unit was serviced Oil and Fuel Filters every 6000 hours, 5w40 Duron HP Oil.



# REPAIR / MAINTENANCE REPORT

	CUSTOMER: AMPS	<u> </u>	TE	CHNICIAN: DAKO	TA.S
	UNIT#: 51005	_			1.
	LOCATION: Leduc			EN #1 363100	KM
	DATE: Noul4 to Dec4	3052	G	EN #2	
	PROBLEM:			\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	_
	transfer case, remove to	rubo, s	Serviced Front diff	tanmission, e	engin
	REPAIRS / NOTES:				
			١. ٨.		
Noo 14	removed coolent, removed	charge	air, removed Air	intake, put a	nr+
	on Jack Stands removed pas	sager w	mel, wheel well t	sox removed, rem	20069
	batterys. All to get accepts	5 40	trubo		
Nov 15	removed coolnet lines form then pulled turbo 4 nut	trubo,	oil lines remove	asuell, removed	exhast
12 21	- 11 - 2 - 1 05 - 410x	1.		1 0	
(00016	puller Drive shafts MH	rront ar	to rear, removed	transter cas	<u>e</u>
	Startes dissambleing Dri	oe snat	45 1 KM 1/140 1/00	Cer sec de lines	3
	pulled transfer case out.	Pilising	1em sem +61 +11115	the lage to fans	A Sac
1000 F	removed for removed Show	ich . con	noved intake form	Huac	
	tanmissin dained best out	+ com	presser out rem	oved there line	es.
	than tried to in Stall me	wcom	presser dosn't f	Fi+	
1 700 200			•		
COOM	installed rails in the b	ack of	St005		
Nonay	Gerviced engin and removed	9.th Co	oper/drand		
17-22	fi 1. ADA 1	1113	FF(1 1 12	24	
100001	6tone drive line rebuild in	Stallec	55tt torge Nou	d6 tanser casci	installed
Del	washers on driveline a drive line of a drive line finish put a	E WOUNTY	+ WORK PULLE BUX	in tenner	
40	PARTS:	7 Inters	in ait Thiteis	in larriey	
	installed from end installed	٠٨ ٨٠	M I'm Deces	Sylem : 1:1-	
	Finished all on repairs Double	check	Aife trusmission to	indo indali	
JC5 .	wheel possage Sid		21 Inter standing ////	WW IIIO WA	
	, , ,				



DATE: April 18/23
UNIT#: S+005
MILEAGE: 34922
INSPECTED BY: DAKOTAS

NOTES:

WORKORDER DESCRIPTION	MS	AR	NA	COMMENTS
BODY/EXTERIOR:				
CONDITION OF WINDSHEILD/WIPERS		/		needs new wipers
CONDITION OF MIRRORS				<b>1</b>
BODY DAMAGE				Front bumper
ELECTRICAL:				
HORN OPERATION	V			
BACK-UP ALARM	V			
HIGH-BEAM HEADLIGHTS	U	100		
LOW-BEAM HEADLIGHTS				
WORK/SIGNAL/TAIL/MARKER LIGHTS		V		Left hand rear center Light mout cracked
LOAD TEST BATTERY				0
CHARGING SYSTEM	V			
HEATER/AIR CONDITIONING OPERATION				
BRAKES/TIRES:				
TIRE PRESSURE	1			LF: 100 RF: 100 LR: 100 RR: 100 SPARE: 100
TIRE TREAD DEPTH				LF: 100 RF: 100 LR: 100 RR: 100 SPARE: 100  LF: 100 RF: 100 LR: 6m RR: 6m SPARE: 9mm
SPARE TIRE CARRIER OPERATION				
BRAKE PADS FRONT	V			LF: 12mm RF: 12mm
BRAKE PADS REAR				LI: 8m LO: 7mm RI: 7mm RO: 8m
BRAKE ROTORS	V			LI: 8m LO: 7mm RI: 7mm RO: 8m LF: .5in RF: in.5. LR: .5in RR: 5in
BRAKE FLUID LEVEL/LEAKS				
PARKING BRAKE OPERATION				
SUSPENSION/STEERING				
UPPER/LOWER BALL JOINTS	1			
INNER/OUTER TIE ROD ENDS	V			
STEERING COMPONENTS (OTHER)				
SUSPENSION COMPONENTS (OTHER)				rear sway bar bush open no play
SHOCKS/STRUTS	V			1000
CV AXLES/BOOTS				
GREASE SUSPENSION/DRIVELINE				
UNDERHOOD:				
OIL AND FILTER SERVICE	V			13.5 Liters of oil
FUEL FILTER				neld
AIR FILTER/INTAKE HOSES	V			
COOLANT LEVEL/LEAKS	V			
BELT CONDITION				
WINDSHEILD WASHER FLUID				
RESET SERVICE REMINDER/INSTALL DECAL			~	
RESET TIRE PRESSURE SENSOR WHEEL POSITIONS				
OIL LEAKS				rear bell houseing sweet
AIR COMPRESSOR OIL LEVEL/OPERATION				
SAFETY/OTHER:				
FIRE EXTINGUISHER & TAG				
AMBER BEACON OPERATION	V			
BUGGY WIP CONDITION				



DATE: Aug 38 /22 UNIT#: 3 34605 MILEAGE: 36053 INSPECTED BY: DAKOTA MS – MEETS STANDARD AR – ATTENTION REQUIRED NA – NOT APPLICABLE

WORKORDER DESCRIPTION	MS	AR	NA	A COMMENTS		
BODY/EXTERIOR:						
CONDITION OF WINDSHEILD/WIPERS				Replaced Wipers		
CONDITION OF MIRRORS	1					
BODY DAMAGE	V					
ELECTRICAL:						
HORN OPERATION	V.					
BACK-UP ALARM	V					
HIGH-BEAM HEADLIGHTS	10%					
LOW-BEAM HEADLIGHTS	10	9				
WORK/SIGNAL/TAIL/MARKER LIGHTS		~		Rear Diver side		
LOAD TEST BATTERY	1					
CHARGING SYSTEM	V					
HEATER/AIR CONDITIONING OPERATION		1		NOT WORKING		
BRAKES/TIRES:						
TIRE PRESSURE	1			LF: 106 RF: 105 LR: 105 RR: 105 SPARE: 100		
TIRE TREAD DEPTH	V			LF: 4 RF: 4 LR: 9 SPARE:		
SPARE TIRE CARRIER OPERATION	V					
BRAKE PADS FRONT	V			LF: RF:		
BRAKE PADS REAR	V			LI: LO: RI: RO:		
BRAKE ROTORS	1			LF: RF: LR: RR:		
BRAKE FLUID LEVEL/LEAKS				boshes		
PARKING BRAKE OPERATION				VV		
SUSPENSION/STEERING						
UPPER/LOWER BALL JOINTS	.1					
INNER/OUTER TIE ROD ENDS	4					
STEERING COMPONENTS (OTHER)						
SUSPENSION COMPONENTS (OTHER)	J					
SHOCKS/STRUTS	1			Some dumage on Rear		
CV AXLES/BOOTS	J			9		
GREASE SUSPENSION/DRIVELINE						
UNDERHOOD:						
OIL AND FILTER SERVICE	1			SERVICE 10.5 liters		
FUEL FILTER	V			Selling to the transfer of the		
AIR FILTER/INTAKE HOSES	0			3 - 3 - 2		
COOLANT LEVEL/LEAKS	J					
BELT CONDITION				NEEDS REPlaceing		
WINDSHEILD WASHER FLUID	V		3.	0		
RESET SERVICE REMINDER/INSTALL DECAL				3		
RESET TIRE PRESSURE SENSOR WHEEL POSITIONS			1	9		
OIL LEAKS	1			bell Housing		
AIR COMPRESSOR OIL LEVEL/OPERATION	1			0		
SAFETY/OTHER:						
FIRE EXTINGUISHER & TAG						
AMBER BEACON OPERATION						
BUGGY WID CONDITION	1./		- 7			

forme crack on weld



DATE: 18 July 2022 UNIT#: 51005 MILEAGE: 302962 MS – MEETS STANDARD AR – ATTENTION REQUIRED NA – NOT APPLICABLE

INSPECTED BY: DAYOTA

WORKORDER DESCRIPTION	MS	AR	NA	COMMENTS
BODY/EXTERIOR:				
CONDITION OF WINDSHEILD	6			
CONDITION OF MIRRORS	V			passage Low Mirror Cracked
BODY DAMAGE			~	
ELECTRICAL:				
HORN OPERATION	-			334
BACK-UP ALARM	/			
HIGH-BEAM HEADLIGHTS				V 15- 1 C
LOW-BEAM HEADLIGHTS	~			V:
SIGNAL/TAIL/MARKER LIGHTS	~			
LOAD TEST BATTERY				
CHARGING SYSTEM				
HEATER/AIR CONDITIONING OPERATION				August 1.
BRAKES/TIRES:				
TIRE PRESSURE		/		LF: RF: LR: AL RR: SPARE:
TIRE TREAD DEPTH				LF: 1/2 RF: 1/2 RR: SPARE:
SPARE TIRE CARRIER OPERATION				430
BRAKE PADS				LF: RF: LR: RR:
BRAKE ROTORS	~			LF: RF: LR: RR:
BRAKE FLUID LEVEL/LEAKS				
PARKING BRAKE OPERATION	~			
SUSPENSION/STEERING				
UPPER/LOWER BALL JOINTS	1			
INNER/OUTER TIE ROD ENDS	-			
STEERING COMPONENTS (OTHER)				Some plag
SUSPENSION COMPONENTS (OTHER)				1.1 120
SHOCKS/STRUTS				will need new Shocks in Front
CV AXLES/BOOTS				
GREASE SUSPENSION/DRIVELINE				
UNDERHOOD:				
OIL AND FILTER SERVICE	V			chang &
FUEL FILTER	V			changes
AIR FILTER/INTAKE HOSES	V,			Changes
COOLANT LEVEL/LEAKS				U
BELT CONDITION				
WINDSHEILD WASHER FLUID	V			Filled
RESET SERVICE REMINDER/INSTALL DECAL				
RESET TIRE PRESSURE SENSOR WHEEL POSITIONS	,	37-15	. /	
OIL LEAKS		- 4		
SAFETY/OTHER:		399		
FIRE EXTINGUISHER & TAG	V			
AMBER BEACON OPERATION				
BUGGY WIP CONDITION				

NOTES. AND OF THE PROPERTY	NOTES: A	22	Left	inside	tire	Floot
----------------------------	----------	----	------	--------	------	-------

# **DND** Driveline Ltd.

## dnddriveline.com

ALBERTA MOBILE POWER SYSTEM 3906-71 AVE UNIT 103

**LEDUC AB T9E0R8** 

(780)781-3404-CELL (780)\_\_\_-

Tax ID:

305-7611 Sparrow Drive Leduc, AB T9E-0H3 7809860221 GST 835850223RT0001

Year Make. 2008 Dodge Ram 3500 ST

Engine 6.7L L6

License **CGR-1943** Klm in/out 301289 / 301289

3D6WD76A586217021 Vin

11:18 am Date 03/03/22 Schedule 03/03/22 **INVOICE: 10324** Page 1 .....

REMARKS AND LABOR DESCRIPTIONS	HRS	PRICE	PARTS &	LUBRICANTS	QTY	PRICE	TOTAL
LUBRICATION AND OIL SERVICE INCLUDES REPLACE ENGINE OIL CHANGE OIL FILTER. CHECK FLUID LEVELS INCLUDING BRAKE FLUID, POWER STEERING FRANSMISSION & WINDOW WASHER. CHECK FIRE AND HOSES FOR WEAR & SAFETY. VISUAL CHASSIS INSPECTION CHECK ANTIFREEZE STRENGTH. REPLACE FUEL FILTER	0.90	37.00	AMSOIL 5W40 SY EHC ON OIL 27620 ENGINE OI EHC ON OIL FILTE WINDSHIELD WA: AIR FILTER #6930 FUEL FILTER #23' EHC ON FUEL FIL SHOP SUPPLIES	L FILTER ER SHER FLUID ((N) 733XE(N)	12.0 12.0 1.00 1.00 5.00 1.00 1.00 1.00	15.99 0.10 19.99 0.50 1.80 87.99 49.99 0.50 25.00	191.88 1.20 19.99 0.50 9.00 87.99 49.99 0.50 25.00
DATE TIME PHONE APPROVED	AMOUN		Il Parts Are New nless Shown As (U) Used or (R) Rebuilt	Labor 167.50 Sublet 0.00	Parts & Lubrica		386.0
I acknowledge notice and oral approval of an increa original estimated price	se in the	Tr	nis vehicle will be reached date shown above	ssembled within3 days of e if I donot authorize the mended	HAZ. D SHOP Gasolir Sub To GST T/	tal	0.00 0.00 0.00 553.55 27.68
CHARGE	X			SIGNATURE	Deposi Disc. A PST TA	pplied AX	0.00 0.00 0.00 581.2
PO # 6225	PO # 6225  A C C E P T A N C E S I G N A T U R E  I accept the charges and terms of this agreement.  BALAN  I authorize the above repairs and necessary materials. Your employees ma						581.2

I authorize the above repairs and necessary materials. Your employees may operate vehicle for inspection, testing, delivery at my risk. You will not be responsible for loss or damage to vehicle or items left in it. I agree to pay reasonable storage on vehicle left more that 3 working days after notification that job is completed. Labor is guaranteed 90 days or 4000 miles whichever occurs first. 



DATE: ADMI 23121
UNIT#: ST-005.
MILEAGE: 279617.
INSPECTED BY: Nothing

WORKORDER DESCRIPTION	MS	AR	NA	COMMENTS
BODY/EXTERIOR:				
CONDITION OF WINDSHEILD				
CONDITION OF MIRRORS				
BODY DAMAGE				
ELECTRICAL:				
HORN OPERATION				
BACK-UP ALARM				
HIGH-BEAM HEADLIGHTS	1			
LOW-BEAM HEADLIGHTS				
SIGNAL/TAIL/MARKER LIGHTS				
LOAD TEST BATTERY				106% - 108%
CHARGING SYSTEM	/			14.4 wac
HEATER/AIR CONDITIONING OPERATION				NO A/C.
BRAKES/TIRES:				
TIRE PRESSURE				LF: 85 RF: 85 LR: 85 RR: 85, SPARE: 85.
TIRE TREAD DEPTH				LF: \\ RF: \\ LR: \\ RR: \\ SPARE: \\
SPARE TIRE CARRIER OPERATION				
BRAKE PADS				LF: \\ RF: \\ LR: \\ RR: \\
BRAKE ROTORS	/			LF: 38 RF: 37 LR: 38 RR: 37.
BRAKE FLUID LEVEL/LEAKS	/			
PARKING BRAKE OPERATION				
SUSPENSION/STEERING				
UPPER/LOWER BALL JOINTS				
INNER/OUTER TIE ROD ENDS				
STEERING COMPONENTS (OTHER)				
SUSPENSION COMPONENTS (OTHER)	/			
SHOCKS/STRUTS	-			
CV AXLES/BOOTS		_	V	
GREASE SUSPENSION/DRIVELINE	-			
UNDERHOOD:				
OIL AND FILTER SERVICE				Completed Setuce.
FUEL FILTER				Replaced
AIR FILTER/INTAKE HOSES	/			
COOLANT LEVEL/LEAKS				
BELT CONDITION				
WINDSHEILD WASHER FLUID				
RESET SERVICE REMINDER/INSTALL DECAL				
RESET TIRE PRESSURE SENSOR WHEEL POSITIONS			/	
OIL LEAKS				
SAFETY/OTHER:				
FIRE EXTINGUISHER & TAG				
AMBER BEACON OPERATION				
BUGGY WIP CONDITION				

IOTES:	



DATE: MAR 3 | 21
UNIT#: ST-005
MILEAGE: 271767
INSPECTED BY: SOUTHORS.

BODY/EXTERIOR:  CONDITION OF WINDSHEILD  CONDITION OF MIRRORS  BODY DAMAGE  ELECTRICAL:  HORN OPERATION  BACK-UP ALARM  HIGH-BEAM HEADLIGHTS  LOW-BEAM HEADLIGHTS  SIGNAL/TAIL/MARKER LIGHTS  LOAD TEST BATTERY  CHARGING SYSTEM  HEATER/AIR CONDITIONING OPERATION  BRAKES/TIRES:  TIRE PRESSURE  TIRE TREAD DEPTH  SPARE TIRE CARRIER OPERATION  BRAKE PADS  LF: [2 RF: ]2 LR: ]3 SPARE: [3]  ENGLY TRE TREAD LET TO THE TREAD LET TO THE TREAD RESIDENCE TO THE TREAD LET TO T	
CONDITION OF MIRRORS  BODY DAMAGE  ELECTRICAL:  HORN OPERATION  BACK-UP ALARM  HIGH-BEAM HEADLIGHTS  LOW-BEAM HEADLIGHTS  SIGNAL/TAIL/MARKER LIGHTS  LOAD TEST BATTERY  CHARGING SYSTEM  HEATER/AIR CONDITIONING OPERATION  BRAKES/TIRES:  TIRE PRESSURE  TIRE TREAD DEPTH  SPARE TIRE CARRIER OPERATION	
BODY DAMAGE  ELECTRICAL:  HORN OPERATION  BACK-UP ALARM  HIGH-BEAM HEADLIGHTS  LOW-BEAM HEADLIGHTS  SIGNAL/TAIL/MARKER LIGHTS  LOAD TEST BATTERY  CHARGING SYSTEM  HEATER/AIR CONDITIONING OPERATION  BRAKES/TIRES:  TIRE PRESSURE  TIRE TREAD DEPTH  SPARE TIRE CARRIER OPERATION	
ELECTRICAL:  HORN OPERATION  BACK-UP ALARM  HIGH-BEAM HEADLIGHTS  LOW-BEAM HEADLIGHTS  SIGNAL/TAIL/MARKER LIGHTS  LOAD TEST BATTERY  CHARGING SYSTEM  HEATER/AIR CONDITIONING OPERATION  BRAKES/TIRES:  TIRE PRESSURE  TIRE TREAD DEPTH  SPARE TIRE CARRIER OPERATION	
HORN OPERATION  BACK-UP ALARM  HIGH-BEAM HEADLIGHTS  LOW-BEAM HEADLIGHTS  SIGNAL/TAIL/MARKER LIGHTS  LOAD TEST BATTERY  CHARGING SYSTEM  HEATER/AIR CONDITIONING OPERATION  BRAKES/TIRES:  TIRE PRESSURE  TIRE TREAD DEPTH  SPARE TIRE CARRIER OPERATION	
BACK-UP ALARM HIGH-BEAM HEADLIGHTS LOW-BEAM HEADLIGHTS SIGNAL/TAIL/MARKER LIGHTS LOAD TEST BATTERY CHARGING SYSTEM HEATER/AIR CONDITIONING OPERATION BRAKES/TIRES: TIRE PRESSURE TIRE TREAD DEPTH SPARE TIRE CARRIER OPERATION  BACK-UP ALARM HEADLIGHTS LOW-BEAM HEADLIGHTS LUM-BEAM HEADLIGH	
HIGH-BEAM HEADLIGHTS  LOW-BEAM HEADLIGHTS  SIGNAL/TAIL/MARKER LIGHTS  LOAD TEST BATTERY  CHARGING SYSTEM  HEATER/AIR CONDITIONING OPERATION  BRAKES/TIRES:  TIRE PRESSURE  TIRE TREAD DEPTH  SPARE TIRE CARRIER OPERATION  HIGH-BEAM HEADLIGHTS  LUM-SUBJECT  LUM-SUBJECT	
LOW-BEAM HEADLIGHTS  SIGNAL/TAIL/MARKER LIGHTS  LOAD TEST BATTERY  CHARGING SYSTEM  HEATER/AIR CONDITIONING OPERATION  BRAKES/TIRES:  TIRE PRESSURE  TIRE TREAD DEPTH  SPARE TIRE CARRIER OPERATION  LF: 13 RF: 13 LR: 13 SPARE: 13	
SIGNAL/TAIL/MARKER LIGHTS  LOAD TEST BATTERY  CHARGING SYSTEM  HEATER/AIR CONDITIONING OPERATION  BRAKES/TIRES:  TIRE PRESSURE  TIRE TREAD DEPTH  SPARE TIRE CARRIER OPERATION  LF: 13 RF: 13 LR: 13 SPARE: 13	
LOAD TEST BATTERY  CHARGING SYSTEM  HEATER/AIR CONDITIONING OPERATION  BRAKES/TIRES:  TIRE PRESSURE  TIRE TREAD DEPTH  SPARE TIRE CARRIER OPERATION  LF: 13 RF: 13 LR: 13 SPARE: 13	
CHARGING SYSTEM  HEATER/AIR CONDITIONING OPERATION  BRAKES/TIRES:  TIRE PRESSURE  TIRE TREAD DEPTH  SPARE TIRE CARRIER OPERATION  LF: 13 RF: 13 LR: 13 RR: 13 SPARE: 13	
HEATER/AIR CONDITIONING OPERATION  BRAKES/TIRES:  TIRE PRESSURE  TIRE TREAD DEPTH  SPARE TIRE CARRIER OPERATION  LF: 13 RF: 13 LR: 13 RR: 13 SPARE: 13	
HEATER/AIR CONDITIONING OPERATION  BRAKES/TIRES:  TIRE PRESSURE  TIRE TREAD DEPTH  SPARE TIRE CARRIER OPERATION  LF: 13 RF: 13 LR: 13 RR: 13 SPARE: 13	
TIRE PRESSURE  LF: SO RF: SO SPARE: SO  TIRE TREAD DEPTH  LF: \( \) RF: \( \) RF: \( \) SPARE: \	
TIRE TREAD DEPTH  LF:   3 RF:   3 LR:   3 SPARE:   3 SP	
TIRE TREAD DEPTH  LF:   3 RF:   3 LR:   3 SPARE:   3 SP	>
SPARE TIRE CARRIER OPERATION	
PRAYE PADE	
BRAKE PAUS	
BRAKE PADS         LF:   2 RF:   2 LR:   2 RR:   2           BRAKE ROTORS         LF: 38 RF: 37 LR: 38 RR: 37.9	
BRAKE FLUID LEVEL/LEAKS	
PARKING BRAKE OPERATION	
SUSPENSION/STEERING	
UPPER/LOWER BALL JOINTS	
INNER/OUTER TIE ROD ENDS	
STEERING COMPONENTS (OTHER)	
SUSPENSION COMPONENTS (OTHER)	
SHOCKS/STRUTS	
CV AXLES/BOOTS	
GREASE SUSPENSION/DRIVELINE	
UNDERHOOD:	
OIL AND FILTER SERVICE Conducted Service.	
FUEL FILTER Leolace d	
AIR FILTER/INTAKE HOSES	
COOLANT LEVEL/LEAKS	
BELT CONDITION	
WINDSHEILD WASHER FLUID	
RESET SERVICE REMINDER/INSTALL DECAL	
RESET TIRE PRESSURE SENSOR WHEEL POSITIONS	
OIL LEAKS	
SAFETY/OTHER:	
FIRE EXTINGUISHER & TAG	
AMBER BEACON OPERATION	
BUGGY WIP CONDITION	

NOTES:	-RH Fr	nh tạc	eel be	edias	aus	Replaced @	)
	271767.	•		J		•	
-	A11 4	wheels	Stude	red	aced.	Rear Replaced	Encusas
we	ex to fe	19.		,			,
	1 wheel	replaced	due	to	crack.		



WORKORDER DESCRIPTION	MS	AR	NA	COMMENTS
BODY/EXTERIOR:				
CONDITION OF WINDSHEILD				
CONDITION OF MIRRORS				
BODY DAMAGE				
ELECTRICAL:				
HORN OPERATION				
BACK-UP ALARM				
HIGH-BEAM HEADLIGHTS				
LOW-BEAM HEADLIGHTS				
SIGNAL/TAIL/MARKER LIGHTS				
LOAD TEST BATTERY				113% - 115%
CHARGING SYSTEM				14.80mc
HEATER/AIR CONDITIONING OPERATION				
BRAKES/TIRES:		/		
TIRE PRESSURE	-			LF: 合 RF: 음 LR: 음 RR: 음 SPARE: 음
TIRE TREAD DEPTH	<u></u>			LF: 13m RF: 13m LR: 13 mRR: 13 m SPARE: 13m
SPARE TIRE CARRIER OPERATION				
BRAKE PADS				LF:   QueRF: 12 m LR: 12m RR: 12m.
BRAKE ROTORS				LF: 12m, RF: 12m, LR: 12m, RR: 12m, . LF: 38.00 RF: 37-45 LR: 3809 RR: 38.17
BRAKE FLUID LEVEL/LEAKS				
PARKING BRAKE OPERATION				
SUSPENSION/STEERING				
UPPER/LOWER BALL JOINTS				
INNER/OUTER TIE ROD ENDS				
STEERING COMPONENTS (OTHER)				
SUSPENSION COMPONENTS (OTHER)				
SHOCKS/STRUTS				
CV AXLES/BOOTS				
GREASE SUSPENSION/DRIVELINE				
UNDERHOOD:				
OIL AND FILTER SERVICE				
FUEL FILTER				
AIR FILTER/INTAKE HOSES				
COOLANT LEVEL/LEAKS				
BELT CONDITION				
WINDSHEILD WASHER FLUID				
RESET SERVICE REMINDER/INSTALL DECAL				
RESET TIRE PRESSURE SENSOR WHEEL POSITIONS			/	
OIL LEAKS				
SAFETY/OTHER:				
FIRE EXTINGUISHER & TAG				
AMBER BEACON OPERATION				
BUGGY WIP CONDITION				

NOTES:	 	 





# **REPAIR / MAINTENANCE REPORT**

Nº 0083

UNIT#:
DATE: Sept 20/20
LOCATION: AMPS SLOP
HOURS: GEN#1 249621 GEN#2 NA
Km's.
PROBLEM:
New Service touck, lepars, moos, accessories.
REPAIRS/NOTES:  - Clossed up and repaired writing underload, at switch banks water driver stat, at Spot lights.
- Replace 2 Side Spotlights.
Twired in brake Controller and 7 pin plug. Replaced har Junction box
- Repaired crope wiring - Repaired UMAC wring to ECM
- Replaced battery Caldes Ar took and rear step re-rooted.
- Replaced batteres Replaced head lights.
- Replaced alternator - Installed air deflector on light bor
- Replaced For belt, tensioner, idler pulley, and For Chitch.
- Tostalled wroter Front, the chains and triangles.
- Installed Cargo heater, wired, photosed hoser.
- Replaced Freenhoguister and buggy whop, orbor beacons.
-Replaced Marker lights, licence plate light.
- Replace of Stooring Stabilizer, sway har bushings and links.
- Serviced vinac (450 hour Service).
-Replaced autogers and jacks Replaced Front drive short
"tassener side front abject closed in new door.
- Installed, relocated air reels Peplaced room brakes and Calipers.
- Mounted Cargo hooves - Completed CUIP.
- Replaced beach vise mounted ladder tack.
-Dealls installed Replaced all Six tires.
-Radio and booster installed
- Onver seat re-apholstered. Installed Seat Covers.
- Replaced Cabinet door Slocks.
- Serviced engine, transmission (replaced pan jasket), serviced trans case
and DIFFS
-Replaced Missing fender flore extensions.